

Kal ki meeting

New Sanganer Road corridor. Turning movement, gap acceptance, PCU. Bolne ke liye script, padhne ke liye nahi.

Sabse pehle: teen sawaal poochhna

Unhone likha hai ki road galat hai. Iska matlab do cheezein ho sakti hain, aur dono ka jawab bilkul alag hai. Guess mat karna. Shuru mein hi clear kar lena, warna poori meeting galat patri par chali jayegi.

Sir, aapne likha tha ki road taken incorrect hai. Main ye clear kar loon pehle. Aap alignment ki baat kar rahe hain, ki humne galat corridor uthaya? Ya method ki baat kar rahe hain, ki approach galat hai?

Jo bhi jawab aaye, agla page uske hisaab se kholna.

Agar wo kehte hain: corridor hi galat hai

Ye maan lena. Bahas mat karna. Aur ye actually humari taraf se pehle hi likha hua hai, isliye position kamzor nahi hoti.

Chhe mein se teen junction ki position **inferred** hai, confirmed nahi. TMC-01, TMC-02 aur TMC-06. Baaki teen naam se match karte hain. Ye baat dashboard ke har map aur har table par likhi hui hai.

Jo cheez isko theek karti hai wo ek hi hai: survey location schedule. Wo abhi tak mila nahi hai.

Sir bilkul, teen junction ki location humne infer ki hai kyunki location schedule abhi tak nahi mila. Wo humne har jagah label kiya hua hai, chhupaya nahi hai. Aap schedule de dijiye, main aaj hi coordinates fix karke dobara chala dunga. Baaki jo counts hain wo workbook ke hain, wo nahi badlenge.

Yaad rakhna: junction ki position badalne se movement counts nahi badalte. Counts workbook se aate hain, map se nahi. Ye farak unko batana zaroori hai.

Agar wo kehte hain: method galat hai

Ab yahan tikna hai. Poochhna ki kaunsa hissa. Do sabse common objection ye hote hain:

- PCU factor kyun badla. Jawab neeche PCU wale section mein.
- Gap acceptance kis basis par. Jawab gap wale section mein.

Aur ek line jo poori meeting sambhal leti hai:

Sir, har number ke saath uska source hai aur uska code hai. Aap jis bhi figure par sawaal karenge, main aapko wo cell dikha sakta hoon jahan se wo aaya hai. Agar kahin main galat hoon, main use theek kar dunga, aaj hi.

Turning movement kya hai

Ye sabse basic cheez hai, isliye ise sabse saaf bolna hai. Agar ye clear ho gaya to baaki sab uske upar khada ho jaata hai.

Ek junction par gaadi kisi ek arm se aati hai aur kisi ek arm se nikalti hai. Survey wale har 15 minute mein ginte hain ki kitni gaadiyan left gayi, kitni straight, kitni right. Char arm hain, teen movement har arm se. Matlab **12 movement per junction**.

Aur yahi wo jagah hai jahan sabse badi baat chhoot gayi.

Survey mein U-turn ka column hai hi nahi. Kam count nahi hai. Column hi nahi hai. Aur JDA ka poora scheme U-turn par bana hai: signal hata kar saat U-turn bay lagane hain.

Matlab jis movement par scheme khada hai, uska koi traffic data hi nahi hai.

Sir, scheme ka basic idea ye hai ki right turn ko U-turn mein badal do. Lekin survey mein U-turn ginti hi nahi gayi. Left, straight, right, bas. To jis movement ke liye saat bay ban rahe hain, uska ek bhi observation nahi hai.

Aur ek number jo unke saamne rakhna hai

	Kya kaha gaya	Survey se kya nikla
Turning traffic	50%	29.6%
Straight ja rahi	koi claim nahi	70.4%

Scheme turning traffic ke liye bana hai. Lekin is road par das mein se saat gaadi turn kar hi nahi rahi, wo seedha ja rahi hai. To hum minority movement ke around poora junction reorganise kar rahe hain.

Agar wo poochhein 50% kahan se aaya: wo news report hai, Patrika, 7 April 2026. JDA ka document nahi. Ye humne page par bhi likha hai. Zid mat karna is par, seedha bol dena ki humein koi published DPR nahi mila.

Gap acceptance kya hai

Ye thoda technical hai lekin roz ki cheez hai. Isko example se samjhana, formula se nahi.

Sir aap khud jab median opening par U-turn lete hain, to kya karte hain? Rukte hain, saamne se aa rahi traffic dekhte hain, aur jab do gaadi ke beech itna gap milta hai ki nikal jayein, tab nikalte hain. Bas wahi gap acceptance hai.

Do number isme kaam ke hain.

- **Critical gap.** Sabse chhota gap jo driver accept kar lega. Isse chhota aayega to wo rukega.
- **Follow-up headway.** Ek hi gap mein agar do gaadi nikal rahi hain, to unke beech ka time.

Jitna bada critical gap, utni kam gaadi nikal payegi us bay se. Ye seedha capacity ban jaata hai.

Jo sabse zaroori baat hai isme: ye number humne India ke field studies se liye hain, is corridor par naapa nahi hai. Isliye humne ek number par bharosa nahi kiya.

Humne wahi test **12 alag published basis** par chalaya. Result 11 mein wahi aata hai. Ek mein nahi aata, aur wo bhi humne page par likha hai.

Sir, critical gap wo number hai jise sabse aasani se challenge kiya ja sakta hai, kyunki humne wo chuna hai, naapa nahi. Isliye humne ek value defend karne ke bajaye baarah published basis par wahi test chala diya. Aap jis paper par bharosa karte hain, wo chun lijiye, answer saamne aa jayega.

Agar wo poochhein: aapne U-turn ko kaise model kiya

Ye asli technical sawaal hai aur iska seedha jawab dena hai.

Humne U-turn ko opposing stream mein **merge** maana hai, uske aar-paar crossing nahi. Merge mein chhota gap chahiye hota hai crossing ke muqable. Ye assumption poore scale ko set karti hai, isliye humne use likh kar rakha hai.

Aur ek baat jo hamare haq mein jaati hai

Indian code mein is movement ke liye koi design gap hai hi nahi. Indo-HCM 2017 mein mid-block median opening ya U-turn ka koi chapter nahi hai. Sabse kareeb CSIR-CRRI ki ek field recommendation hai, 4.5 second, aur wo bhi inter-urban highway par naapi gayi thi, urban arterial par nahi.

Matlab jis manoeuvre par ye poora scheme khada hai, uske liye kisi bhi Indian standard mein design value hai hi nahi. Ye apne aap mein ek finding hai.

PCU wala point

Ye shayad sabse zyada challenge hoga, isliye ekdum saaf rakhna.

PCU matlab ek gaadi kitni road capacity khaati hai, car ke comparison mein. Ek bus ek car se zyada jagah leti hai, ek scooter kam.

Survey ne har class ke liye ek fixed factor lagaya hai. Two-wheeler ko 0.50. Lekin IRC:106 kehta hai ki ye factor fixed nahi hota, wo us class ke share par depend karta hai. Jab two-wheeler stream ka 10% se upar ho, to factor 0.75 hona chahiye.

Is corridor par two-wheeler **49.11%** hain. Aadhi traffic. Aur unko 0.50 par chalaya gaya hai jabki code 0.75 maangta hai.

Isse corridor demand kam se kam **14.9%** understate hoti hai.

Do baatein jo khud se bolni hain, poochhne se pehle:

- Correction dono taraf jaata hai. 2W understated hai, lekin cycle aur MAV bucket thoda overstated hai. Humne net figure diya hai, sirf favourable half nahi.
- Aadhi correction possible hi nahi hai, kyunki survey ke paanch column composite hain. Ek hi column mein car, auto aur pickup ghuse hue hain. Unke liye humne band diya hai, single number nahi.

Sir jo theek ho sakta tha wo humne theek kiya, aur jo nahi ho sakta uske liye humne range di hai. Composite column ka single number banana wahi galti hoti jo hum report kar rahe hain.

Agar wo kahein ki factor badalna hi nahi chahiye tha: JMRC ke apne Phase-II DPR mein two-wheeler 0.75 par hai aur MAV 3.7 par. Yani correction state government ke andar pehle se ho chuki hai.

Jo humein nahi pata, wo pehle bol dena

Ye kamzori nahi hai. Meeting mein sabse zyada bharosa isi se banta hai. Aur agar unhone khud pakda to bahut bura lagega.

- **Teen junction ki location inferred hai.** Location schedule chahiye.
- **Camera se counting wala hissa verify nahi hua hai.** Code bana hua hai, apne test pass karta hai, lekin asli footage nahi dekhi. Isliye humne koi accuracy figure claim nahi kiya. Validation report abhi template hai, uske gates pehle publish kiye hain.
- **Critical gap literature se hai,** is corridor par naapa nahi. Isiliye baarah basis par chalaya.

Sir jo humne naapa hai wo humne likha hai, aur jo assume kiya hai wo alag se likha hai. Aap dono ko alag alag dekh sakte hain. Yahi is report ka poora point hai.

Baat kaam par kaise laani hai

Ye audit door kholne ke liye tha. Meeting ke aakhri paanch minute isi ke liye rakhna.

Sir ye jo maine dikhaya, ye sirf issued workbooks se nikala hua hai. Na koi field visit, na koi extra data. Agar location schedule aur footage mil jaye, to yahi kaam measured numbers ke saath ho sakta hai, aur tab har figure ke saath error rate bhi hoga. Main scope aur timeline likh kar bhej sakta hoon.

Jo cheezein unse maangni hain, ek hi baar mein:

- Survey location schedule. Teen junction ki position fix ho jayegi.
- TMC-04 ki footage aur camera position ki 7 stills. Counting validate ho jayegi.
- Agar koi DPR ya board resolution hai scheme ka, wo. Abhi hum news report ke against compare kar rahe hain, jo theek nahi hai.

Numbers, ek nazar mein

Movements	12 per junction. U-turn ka column zero, count nahi.
Turning	29.6% actual, 50% claimed. 1.7x.
Two-wheeler	49.11% of stream. 0.50 lagaya, IRC 0.75 maangta hai.
PCU effect	Demand kam se kam 14.9% understated.
U-turn bays	12 mein se 11 approach demand nahi le sakte.
Gap bases	12 published basis, 11 mein wahi jawab.
2W critical gap	3.5 s. Follow-up 2.04 s, four-lane par naapa hua.
Arithmetic	225 stored total apne hi components se match nahi karte.
Day 2	555 series mein 396 pehle din se bilkul same. Ginti nahi hui.
Corridor	New Sanganer Road, 5.34 km, chhe junction.

Ek aakhri baat. Agar wo kisi point par sahi hain, wahin maan lena aur likh lena. Is poore kaam ka argument yahi hai ki galti maani jaati hai, chhupai nahi jaati. Agar hum defensive ho gaye to wahi cheez kar rahe honge jiski hum report kar rahe hain.