TURBINE UNIT 4B ROUTINE INSPECTION REPORT

Date: Oct 02, 2024 | Inspector: Chief Tech R. Vance

Status: OPERATIONAL - NORMAL

Bearing Temperature: 62 C - WITHIN 70 C TOLERANCE

Rotor Shaft Vibration: 1.2 mm/s - NORMAL THRESHOLD

Hydraulic Seals: Verified intact, zero visible leaks

Conclusion: Equipment certified for continuous duty through Q4.