

# WDO Inspection

\*\*\* ACTIVE INFESTATION FOUND \*\*\*

---

|                            |                                            |
|----------------------------|--------------------------------------------|
| <b>Findings:</b>           | Active subterranean termite infestation    |
| <b>Location:</b>           | Foundation — south wall, garage header     |
| <b>Treatment Required:</b> | YES — full treatment estimated \$2,500     |
| <b>Structural Damage:</b>  | Moderate — sistering of joists recommended |