

Hybrid golden-section angle sampling

■ Exposure time
■ Motor settling (dead time)

Step-and-shoot:

Exposure

Motor
settling

Continuous scan:




Exposure only

Revolution 1
 $\varphi_0 = 0^\circ$

Revolution 2
 $\varphi_0 = 137.5^\circ$

Revolution 3
 $\varphi_0 = 275^\circ$

3 revolutions combined:
near-uniform coverage



■ Rev 1 ■ Rev 2 ■ Rev 3

