Motor Vehicle Repair Bill

Car brand: toyota Malik Industries Autoservis s.r.o
Car model: a54 Nizkozemska 98, Bratislava
VIN number: 123456 Slovak Republic

Fuel type: Benzín

Customer name: jozef andrej

Customer e-mail: andrej@gmail.com

Customer phone number: 123

Item no.	Mechanic	Start day	End day	Days total
1	Andrej Andrej	2020-05-15	2020-05-16	1

Repair description
needed to repair a screw

Total cost of repair: 120.0 €