Motor Vehicle Repair Bill

Car brand: Hyundai Malik Industries Autoservis s.r.o
Car model: IX35 Nizkozemska 98, Bratislava
VIN number: rfe64664w Slovak Republic

Fuel type: Diesel

Customer name: Veronika Vrtova

Customer e-mail: veronika.vrtova@gmail.com

Customer phone number: 4894949

Item no.	Mechanic	Start day	End day	Days total
1	Filip Cernak	2020-05-28	2020-05-31	1

Repair description
spatna zrkadla

Total cost of repair: 200.0 €