## Motor Vehicle Repair Bill

Car brand: Skoda Malik Industries Autoservis s.r.o
Car model: Karoq Nizkozemska 98, Bratislava
VIN number: fhshiu1819 Slovak Republic

Fuel type: Diesel

Customer name: Juraj Malík

Customer e-mail: juraj@gmail.com Customer phone number: 0918555666

Item no.	Mechanic	Start day	End day	Days total
1	Filip Velký	2020-05-22	2020-05-25	1

Repair description
vymenené elné sklo

Total cost of repair: 249.0 €