```
12CSensor
   + Initialize()
   + Reset()
   + Close Device()
      VFMI 7700

    m registerVEML7700

- m pl2Cdriver
- m fd
+ VEML7700()
+ Initialize()
+ Get ALS Lux()
+ Get White Lux()
+ Set Gain()
+ Get Gain()
+ Set Integration Time()
+ Get Integration Time()
+ Close Device()
+ Reset()
Get ALS()
- Get White()

    Compute Lux()
```