



Auto Cool & 60° Air
Conditioning and
Refrigeration

South Beach
(242) 558-9373
kashmir.colebrooke@gmail.com

INVOICE
INV0011

DATE
Feb 11, 2026

DUE
On Receipt

BALANCE DUE
BSD \$2,482.65

BILL TO

Harbor Breeze #8

Paradise Island

DESCRIPTION	RATE	QTY	DISCOUNT	AMOUNT
Humidifier , ozone unit , fog spray rooms Upon detecting mold spores in certain areas due to old electrical components such as TV, DVR, phone, and Internet modem, our action plan involves the removal of these components and the installation of a humidifier in both the right and left wings of the building. Additionally, an ozone machine will be placed in the living room and kitchen areas, remaining operational while the villa is closed. Each room will be fogged again for mold spores prior to the installation of systems designed to improve air quality in each area. The ozone machine will remain operational, and the humidifier will run for three days on its own every month upon reset, ensuring better air quality and preserving the area's safety from mold spores and mildew.	\$2,758.50	1 Material-1,482.65	-\$275.85 10%	\$2,482.65

PAYMENT INSTRUCTIONS Commonwealth Bank Branch 21103 oakes field	TOTAL	\$2,482.65
		BALANCE DUE
		BSD \$2,482.65

Account number 7033238089

Kashmir Colebrooke

Saving

BY CHECK

Kashmir Colebrooke

The 24-volt transformer in the condenser system experienced a burnout. We were able to replace the 24-volt system, and the air conditioning is now operational.