

Arm side — full wiring

Mega 2560 · 4× MG996R · HC-05 slave · 6 V bench PSU for servos

