

LOCKOUT-TAGOUT PROCEDURE

Developed By:
Cardinal Compliance Consultants
5353 Secor Rd.
Toledo, OH 43623
P: 419-882-9224

Description: Air Compressor #2			Procedure #: 41	
Facility: Game One	Location: Maintenance Room	Rev: 0	Date: 01/02/2025	Origin: 01

Machine to be Locked Out	
	2 Isolation Points to be Locked and Tagged
	Notes:
	Notes go here.