

LOCKOUT-TAGOUT PROCEDURE

Developed By:
Cardinal Compliance Consultants
5353 Secor Rd.
Toledo, OH 43623
P: 419-882-9224

Description: Air Compressor #2	Procedure #: 41
--------------------------------	-----------------

Facility: Game One Location: Maintenance Room Rev: 0 Date: 01/02/2025 Origin: 01