

LOCKOUT-TAGOUT PROCEDURE

Developed By:
Cardinal Compliance Consultants
5353 Secor Rd.
Toledo, OH 43623
P: 419-882-9224

Description: Air Compressor #2		Procedure #: 41		
Facility: Game One	Location: Maintenance Room	Rev: 0	Date: 01/02/2025	Origin: 01

Machine to be Locked Out



2		Isolation Points to be	
		Locked and Tagged	

Notes:

Notes go here.

SHUTDOWN SEQUENCE

1. Notify affected personnel. 2. Properly shut down machine. 3. Isolate all energy sources. 4. Apply LOTO devices. 5. Verify total de-energization of all sources.

Energy Source	Device	Isolation Point	Isolation Method	Verification Method	Verification Device
Chemical Oxygen 12,000					