

LOCKOUT-TAGOUT PROCEDURE

Developed By:
Cardinal Compliance Consultants
5353 Secor Rd.
Toledo, OH 43623
P: 419-882-9224

| Description: Air Compressor #2 | ription: Air Compressor #2 | | Procedure #: 41 | |
|--------------------------------|----------------------------|--------|------------------|------------|
| Facility: Game One | Location: Maintenance Room | Rev: 0 | Date: 01/02/2025 | Origin: 01 |

Machine to be Locked Out



|) | | Isolation Points to be | | |
|---|--|--------------------------|--|--|
| _ | | Locked and Tagged | | |

Notes:

Notes go here.

SHUTDOWN SEQUENCE

1. Notify affected personnel. 2. Properly shut down machine. 3. Isolate all energy sources. 4. Apply LOTO devices. 5. Verify total de-energization of all sources.

| Energy Source | Device | Isolation Point | Isolation Method | Verification Method | Verification Device |
|------------------------------|--------|-----------------|------------------|------------------------|---------------------|
| Chemical Oxygen 12,000 | | | | | |
| Electric 240 | | | | | |
| Electric 240 | | | | | |



LOCKOUT-TAGOUT PROCEDURE

Developed By:
Cardinal Compliance Consultants
5353 Secor Rd.
Toledo, OH 43623
P: 419-882-9224

| Description: Air Compressor #2 | | Procedure #: 41 | | |
|--------------------------------|----------------------------|-----------------|------------------|------------|
| Facility: Game One | Location: Maintenance Room | Rev: 0 | Date: 01/02/2025 | Origin: 01 |

| Energy Source | Device | Isolation Point | Isolation Method | Verification Method | Verification Device |
|-----------------|--------|-----------------|------------------|------------------------|---------------------|
| | | | | | |
| Electric 240 | | | | | |
| | | | | | |