

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION

Requirements for Use

Nondisclosure

This document contains Protected Critical Infrastructure Information (PCII). In accordance with the provisions of the Critical Infrastructure Information Act of 2002 (the CII Act), (6 U.S.C. §671- 674), PCII is exempt from release under the Freedom of Information Act (5 U.S.C. §552) and similar State and local disclosure laws. Unauthorized release may result in criminal and administrative penalties. Safeguard and disseminate in accordance with the CII Act, the implementing Regulation at 6 C.F.R. part 29 (the Final Rule) and PCII Program requirements.

By reviewing this cover sheet and accepting the attached PCII you are agreeing not to disclose it to other individuals without following the access requirements and to abide by the guidance contained herein. Your acceptance provides immediate access only to the attached PCII. If not a PCII Authorized User, you are required to complete certification within 30 days of receipt of this information.

For Certification <https://www.cisa.gov/pcii-authorized-user-training> For Assistance pcii-assist@cisa.dhs.gov

Access

Individuals eligible to access the attached PCII must be Federal, State or local government employees or their designated contractors and must meet all the following requirements:

- Assigned to homeland security duties related to this critical infrastructure
- Demonstrate a valid need-to-know
- Sign a Non-Disclosure Agreement (except Federal employees)

Handling

Storage Store PCII in a secure container. **Do not leave this document unattended.**

Dissemination Methods:

Email Encrypt the email if possible. If unavailable, use approved email systems per PCII Program guidelines. Send PCII as a password protected attachment and provide the password in a separate email.

Mail USPS First Class mail or an equivalent. Seal the document in an opaque envelope, to prevent inadvertent opening, then place it inside a second plain outer envelope without PCII markings. Include sender's and recipient's full names and addresses on the outer envelope and add "POSTMASTER: DO NOT FORWARD. RETURN TO SENDER." below return address.

Telephone Use a secure telephone connection. If unavailable or impractical, verify the caller on other end is a PCII Authorized User and state you will discuss PCII.

Hand Delivery Authorized individuals hand carrying PCII must control it from loss or viewing throughout transit.

Reproduction Ensure this cover sheet is the first page of all reproductions containing PCII.

Destruction Destroy copies of this document when no longer required according to PCII Program procedures.

For details on access, marking, and handling requirements, see the *PCII Program Procedures Manual*.

Sanitized Products

You may create a sanitized work product using PCII. The product must not reveal any information relating to the identity of the submitting person or entity (explicitly or implicitly); is proprietary, business sensitive, or trade secret; and is otherwise not customarily in the public domain.

Derivative Products

Mark a newly created document derived from PCII with "PROTECTED CRITICAL INFRASTRUCTURE INFORMATION" in the header and footer of pages containing PCII. Mark (PCII) beside each paragraph containing PCII. Attach a PCII green cover sheet on all newly created derivative products containing PCII. Include the PCII Submission Identification Number(s) of the source document(s) on the newly created document as a footnote.

Submission Identification Number

PCII-2027

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION



ABC

Enterprise Physical Security Consulting

Site Security Facility Assessment

Executive Client Report

CLIENT	Portland
SITE NAME	Clayton Jerde
ASSESSMENT ID	79
ASSESSMENT DATE	July 21, 2026
ADDRESS	742 Maple Ridge Lane, Apt 4B, Austin, TX, 78705, United States

OVERALL SECURITY SCORE

60

/ 100

RISK CLASSIFICATION

MEDIUM RISK

Table of Contents

Executive Dashboard	3
Executive Summary	4
Site Security Snapshot	5
Area Overview	6
Executive Risk Highlights	7
Embedded Area Summaries	8
Embedded Area Reports	9
Area Report: Area Assessment Report	9
Subarea Report: Sub Area	26
Area Report: Area Assessment Report	34
Subarea Report: Sub Area	42

Executive Dashboard

(PCII) AREAS ASSESSED

(PCII) 2

(PCII) SUB AREAS

(PCII) 2

(PCII) MEDIA ANALYSED

(PCII) 4

(PCII) SECURITY DEVICES

(PCII) 1

(PCII) CRITICAL VULNERABILITIES

(PCII) 0

(PCII) ASSESSMENT CONFIDENCE

(PCII) High

Executive Summary

I

OVERALL ASSESSMENT

- (PCII) Location research was performed for 742 Maple Ridge Lane, Apt 4B, Austin, TX 78705.
- (PCII) The exact street address could not be independently verified in available public web results, so location intelligence is anchored to ZIP Code 78705 and the North University/West Campus/University of Texas central Austin context rather than to a confirmed parcel.
- (PCII) ZIP 78705 is a dense, highly transient, university-oriented area: Census Reporter lists 33,238 residents in 2.1 square miles, or about 16,056.8 people per square mile, and UnitedStatesZipCodes places the ZIP near coordinates 30.29, -97.74.
- (PCII) The area is dominated by apartments, student housing, university facilities, small commercial uses, schools, and nearby medical/institutional uses.
- (PCII) Public demographic data show a young population, low reported median household income relative to Austin and Texas, high renter occupancy, and high annual mobility, all consistent with a student-heavy district.
- (PCII) Public crime data are available through Austin Police Department CrimeViewer and the APD NIBRS Group A Offense Crimes dataset, but a validated address-level or one-/two-/three-mile extraction was not obtainable from the reviewed public pages.

S

CURRENT SECURITY POSTURE

- (PCII) Score: 60/100
- (PCII) Risk Classification: MEDIUM RISK
- (PCII) Property Type: Commercial Facility; submitted address format includes Apt 4B, suggesting possible tenant suite, apartment-style unit, or mixed-use/multitenant condition that requires verification.

A

AREA SUMMARY

- (PCII) Existing Area Report for Perimeter recorded a security score of 60 and medium risk.
- (PCII) The provided report identified perimeter-related observations and recommendations; this location intelligence report does not re-analyze those findings.; Existing Area Report for the second Perimeter entry recorded a security score of 70 and medium risk.
- (PCII) The provided area summary noted perimeter observations; this report uses the score only for aggregation and does not add new security recommendations.

Site Security Snapshot

S

ASSESSMENT SNAPSHOT

- (PCII) Overall Score: 56
- (PCII) Risk Classification: Medium
- (PCII) Target Score: 80
- (PCII) Assessment Confidence: High
- (PCII) Areas Assessed: 2
- (PCII) Sub Areas: 2
- (PCII) Media: 4
- (PCII) Devices: 1
- (PCII) Total Vulnerabilities: 0

Area Overview

Area	Score	Risk	Media	Devices	Sub Areas	Status
Perimeter	-	-	2	0	1	PENDING
Perimeter	-	-	2	1	1	PENDING

Executive Risk Highlights

(PCII) TOP SECURITY STRENGTHS

(PCII) Adequate baseline security posture.

(PCII) TOP SECURITY WEAKNESSES

(PCII) Vulnerabilities exist in current controls.

(PCII) OVERALL SECURITY OUTLOOK

(PCII) Requires ongoing remediation to stabilize security.

Embedded Area Summaries

TRANSITION

(PCII) The following pages contain the executive summaries for each assessed Area. Each Area Summary includes executive findings, CPTED observations, vulnerabilities, remediation priorities, and attached SubArea assessments.

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION

Requirements for Use

Nondisclosure

This document contains Protected Critical Infrastructure Information (PCII). In accordance with the provisions of the Critical Infrastructure Information Act of 2002 (the CII Act), (6 U.S.C. §671- 674), PCII is exempt from release under the Freedom of Information Act (5 U.S.C. §552) and similar State and local disclosure laws. Unauthorized release may result in criminal and administrative penalties. Safeguard and disseminate in accordance with the CII Act, the implementing Regulation at 6 C.F.R. part 29 (the Final Rule) and PCII Program requirements.

By reviewing this cover sheet and accepting the attached PCII you are agreeing not to disclose it to other individuals without following the access requirements and to abide by the guidance contained herein. Your acceptance provides immediate access only to the attached PCII. If not a PCII Authorized User, you are required to complete certification within 30 days of receipt of this information.

For Certification <https://www.cisa.gov/pcii-authorized-user-training> For Assistance pcii-assist@cisa.dhs.gov

Access

Individuals eligible to access the attached PCII must be Federal, State or local government employees or their designated contractors and must meet all the following requirements:

- Assigned to homeland security duties related to this critical infrastructure
- Demonstrate a valid need-to-know
- Sign a Non-Disclosure Agreement (except Federal employees)

Handling

Storage Store PCII in a secure container. **Do not leave this document unattended.**

Dissemination Methods:

Email Encrypt the email if possible. If unavailable, use approved email systems per PCII Program guidelines. Send PCII as a password protected attachment and provide the password in a separate email.

Mail USPS First Class mail or an equivalent. Seal the document in an opaque envelope, to prevent inadvertent opening, then place it inside a second plain outer envelope without PCII markings. Include sender's and recipient's full names and addresses on the outer envelope and add "POSTMASTER: DO NOT FORWARD. RETURN TO SENDER." below return address.

Telephone Use a secure telephone connection. If unavailable or impractical, verify the caller on other end is a PCII Authorized User and state you will discuss PCII.

Hand Delivery Authorized individuals hand carrying PCII must control it from loss or viewing throughout transit.

Reproduction Ensure this cover sheet is the first page of all reproductions containing PCII.

Destruction Destroy copies of this document when no longer required according to PCII Program procedures.

For details on access, marking, and handling requirements, see the *PCII Program Procedures Manual*.

Sanitized Products

You may create a sanitized work product using PCII. The product must not reveal any information relating to the identity of the submitting person or entity (explicitly or implicitly); is proprietary, business sensitive, or trade secret; and is otherwise not customarily in the public domain.

Derivative Products

Mark a newly created document derived from PCII with "PROTECTED CRITICAL INFRASTRUCTURE INFORMATION" in the header and footer of pages containing PCII. Mark (PCII) beside each paragraph containing PCII. Attach a PCII green cover sheet on all newly created derivative products containing PCII. Include the PCII Submission Identification Number(s) of the source document(s) on the newly created document as a footnote.

Submission Identification Number

PCII-2027

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION



Executive Security Area Summary

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
AREA NAME	Perimeter
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

60 / 100

RISK CLASSIFICATION

MEDIUM RISK

TABLE OF CONTENTS

EXECUTIVE ASSESSMENT SUMMARY	4
CPTED SECURITY SNAPSHOT	5
KEY FINDINGS	6
CORE VULNERABILITY PROFILE	7
PRIORITY REMEDIATION ACTIONS	9
SECURITY CONTROLS EFFECTIVENESS	10
SECURITY GAPS	11
SECURITY MATURITY BENCHMARK	12
ADVANCED SECURITY ANALYSIS	13
STRATEGIC CONCLUSION	16
ATTACHED SUBAREA ASSESSMENTS	17
SUB-AREA REPORTS	
SUB AREA	18

1. Executive Assessment Summary

(PCII) The overall security posture of the Clayton Jerde facility perimeter is moderately effective but requires enhancements to meet a higher security standard. Key strengths include the presence of a security guard, a manual boom barrier controlling vehicle entry, and a well-maintained perimeter fence. However, critical vulnerabilities exist, such as a partially obstructed CCTV camera, lack of electronic access control systems, and an open entrance gate during operational hours. These gaps expose the facility to unauthorized access and reduce its deterrent capability. The lack of a visitor management kiosk further complicates the tracking and verification of visitors, increasing liability risks. The CPTED assessment highlights deficiencies in natural surveillance and access control, while maintenance and territorial reinforcement are relatively stronger. To improve security maturity, strategic recommendations include installing electronic access control systems, repositioning the CCTV camera, and implementing a visitor management system. Post-remediation, the facility is expected to achieve a more robust security posture, significantly reducing the risk of unauthorized access and enhancing operational security.

2. CPTED Security Snapshot

(PCII) CPTED analysis across access controls, surveillance, reinforcement, and maintenance guidelines:

NATURAL SURVEILLANCE

40/100

HIGH

Findings: Obstructed CCTV view due to tree.

ACCESS CONTROL

50/100

HIGH

Findings: Lack of electronic access control systems.

TERRITORIAL REINFORCEMENT

60/100

MEDIUM

Findings: Well-maintained perimeter fence.

MAINTENANCE

70/100

MEDIUM

Findings: Well-maintained entrance and landscaping.

ACTIVITY SUPPORT

50/100

HIGH

Findings: Lack of electronic visitor management.

3. Key Findings

- (PCII) The CCTV camera's field of view is blocked by a tree, reducing surveillance effectiveness.
- (PCII) No electronic access control system is present, increasing unauthorized entry risk.
- (PCII) The entrance gate is open during business hours, compromising access control.

4. Core Vulnerability Profile

OBSTRUCTED CCTV VIEW

MEDIUM

Description:	The CCTV camera's field of view is partially blocked by a tree.
Evidence:	Tree partially blocks camera view.
Observation:	Camera placement needs adjustment for full coverage.
Analysis:	Obstruction makes undetected entry feasible.
Vulnerability Details:	Limited visibility at entrance.
Impact:	Reduced surveillance effectiveness.
Likelihood:	Medium
Recommended Mitigation:	Reposition camera to avoid obstruction.

ATTACK PATH

Exploitation Method:	Approach entrance where camera view is blocked.
Required Skill:	Novice
Attack Sequence:	Enter undetected due to obstructed view.
Probability of Success:	Medium
Detection Probability:	Low
Required Tools:	None
Time To Exploit:	Immediate

IMPLICATIONS

Operational Impact:	Compromised monitoring capabilities.
Business Impact:	Potential liability issues.
Security Impact:	Increased risk of unauthorized access.
Safety Impact:	Increased risk to personnel.
Escalation Path:	Potential access to sensitive areas.

RISK JUSTIFICATION

Likelihood Justification:	Obstruction makes undetected entry feasible.
Impact Justification:	Direct access to facility.
Severity Justification:	Medium due to surveillance gap.
Evidence Used:	Visible obstruction in image.
Rationale:	Obstruction reduces camera effectiveness.

LACK OF ELECTRONIC ACCESS CONTROL

HIGH

Description:	No electronic systems are in place to verify or control access.
Evidence:	No electronic access controls visible.
Observation:	Access relies on manual checks, which are less reliable.

Analysis:	Easy entry due to lack of controls.
Vulnerability Details:	Open access during business hours.
Impact:	Increased risk of unauthorized access.
Likelihood:	High
Recommended Mitigation:	Install electronic access control systems.

ATTACK PATH

Exploitation Method:	Enter through open gate without verification.
Required Skill:	None
Attack Sequence:	Walk through gate during open hours.
Probability of Success:	High
Detection Probability:	Low
Required Tools:	None
Time To Exploit:	Immediate

IMPLICATIONS

Operational Impact:	Increased liability and security risk.
Business Impact:	Risk of theft or vandalism.
Security Impact:	Potential for unauthorized access.
Safety Impact:	Increased risk to personnel.
Escalation Path:	Access to sensitive areas.

RISK JUSTIFICATION

Likelihood Justification:	Easy entry due to lack of controls.
Impact Justification:	High potential for unauthorized access.
Severity Justification:	High due to open access.
Evidence Used:	Open gate and lack of controls visible in image.
Rationale:	Open access presents high risk.

5. Priority Remediation Actions

IMMEDIATE (0-30 DAYS)

Reposition CCTV camera to avoid obstruction.

Location:	Main Entrance
Vulnerability Addressed:	Obstructed CCTV View
Rationale:	Improves surveillance coverage and effectiveness.
Business Impact:	Enhances security monitoring capabilities.
Security Impact:	Reduces undetected entry risk.
Implementation Effort:	Low
Expected Risk Reduction:	Significant reduction in risk of undetected entry.

SHORT-TERM (1-3 MONTHS)

Install electronic access control systems.

Location:	Main Entrance
Vulnerability Addressed:	Lack of Electronic Access Control
Rationale:	Ensures controlled and verified access.
Business Impact:	Reduces liability and enhances security.
Security Impact:	Prevents unauthorized access.
Implementation Effort:	Medium
Expected Risk Reduction:	Drastic reduction in unauthorized access risk.

LONG-TERM (3-12 MONTHS)

Implement a visitor management system.

Location:	Main Entrance
Vulnerability Addressed:	Lack of Visitor Management
Rationale:	Tracks and verifies visitors effectively.
Business Impact:	Enhances operational security and compliance.
Security Impact:	Improves accountability and tracking.
Implementation Effort:	Medium
Expected Risk Reduction:	Improves overall security management.

6. Security Controls Effectiveness

Access Control

Status: Ineffective

Commentary: No electronic systems to verify access.

Surveillance

Status: Limited

Commentary: Camera view obstructed, reducing effectiveness.

Detection

Status: Ineffective

Commentary: Limited by obstructed CCTV coverage.

Delay

Status: Moderate

Commentary: Manual barrier provides some delay.

Response

Status: Moderate

Commentary: Guard presence offers immediate response.

Barriers

Status: Moderate

Commentary: Manual boom barrier lacks electronic verification.

7. Security Gaps

Critical

Lack of Electronic Access Control

- Risk Created:

High exposure to unauthorized entry.
- Likely Attack Enabled:

Entering through open gate without verification.
- Corrective Action:

Install electronic access control systems.

High

Obstructed CCTV View

- Risk Created:

Reduced surveillance coverage.
- Likely Attack Enabled:

Undetected entry through obstructed areas.
- Corrective Action:

Reposition CCTV camera.

8. Security Maturity Benchmark

Current Level:	Level 2 - Standard Commercial
Assigned Reasoning:	Site implements basic security measures such as a guard and a boom barrier but lacks electronic systems.
Preventing Advancement:	Absence of electronic access controls and obstructed surveillance coverage.
Required Controls To Advance:	Install electronic access controls and reposition CCTV for full coverage.

Fastest Security Improvements

Reposition CCTV camera to avoid obstruction.	
Effort:	Low
Impact:	High
ROI Justification:	Improves surveillance coverage with minimal cost.

Install electronic access control systems.	
Effort:	Medium
Impact:	High
ROI Justification:	Drastically reduces unauthorized access risk.

9. Advanced Security Analysis

Physical Security Engineering

(PCI) The facility's physical security relies on manual processes and natural deterrents, which are insufficient for high-security needs. Recommendations focus on integrating electronic systems to bolster security.

Security Resilience

Intrusion Resistance

Score: 55 / 100

Reasoning: Manual controls offer basic deterrence but are easily bypassed.

Detection Capability

Score: 50 / 100

Reasoning: Obstructed CCTV limits detection.

Delay Capability

Score: 60 / 100

Reasoning: Manual barrier provides moderate delay.

Response Capability

Score: 65 / 100

Reasoning: Guard presence offers immediate response but lacks technological support.

Attack Vector Analysis

Unauthorized Access through Open Gate

Difficulty: Low

Likelihood: High

Detection: Low

Consequence: High

Mitigation: Install electronic access control systems.

Layered Defense Review

Deter Layer

Current State:	Manual deterrents in place.
Strengths:	Presence of guard and barriers.
Weaknesses:	Lack of electronic systems.
Failure Scenarios:	Intruders bypass manual checks.
Improvements:	Integrate electronic deterrents.

Delay Layer

Current State:	Manual barriers provide some delay.
Strengths:	Boom barrier and fence.
Weaknesses:	No electronic verification.
Failure Scenarios:	Barrier bypassed during open hours.
Improvements:	Automate barriers for improved delay.

Detect Layer

Current State:	Limited by obstructed CCTV.
Strengths:	CCTV presence.
Weaknesses:	Obstructed view limits detection.
Failure Scenarios:	Intruders remain undetected.
Improvements:	Reposition CCTV for better coverage.

Respond Layer

Current State:	Guard presence provides immediate response.
Strengths:	Immediate human response.
Weaknesses:	No electronic support.
Failure Scenarios:	Limited response capability without technology.
Improvements:	Enhance response with electronic alerts.

(PCI) Weakest Layer: DETECT

Delay Detect Respond**DDR Assessment**

Delay:	Medium
Detect:	Low
Respond:	Medium

(PCI) Current systems rely heavily on manual processes, limiting detection capabilities.

Likelihood vs Impact Matrix

Unauthorized Access

Likelihood: High

Impact: High

Priority: Critical

Adversary Exploitation Scenarios

(PCI) Scenario 1: An intruder could exploit the open gate during business hours, bypass the manual boom barrier, and remain undetected due to the obstructed CCTV camera.

Control Failure Consequences

CCTV

Consequence: Loss of surveillance coverage and increased risk of undetected intrusion.

10. Strategic Conclusion

(PCII) The Clayton Jerde facility's perimeter security is currently at a moderate level, with significant areas for improvement. The most critical weakness is the lack of electronic access control systems, while the strongest existing control is the presence of a security guard. Implementing recommended improvements is expected to elevate the security rating to a higher standard, reducing unauthorized access risks and enhancing overall security resilience. The future security outlook is positive, with a strategic focus on integrating advanced technologies and maintaining a proactive security posture.

11. Attached Subarea Assessments

Sub Area

Security Score: 40 / 100

Risk Level: High

Executive Summary:

Security Posture The current security posture of this sub-area is inadequate, with significant gaps in surveillance and access control mechanisms. The existing controls fail to meet the acceptable risk threshold, primarily due to the absence of electronic monitoring devices.

Environment Overview The sub-area serves as a meeting room within a facility, characterized by a central table and seating for collaborative activities. Access appears to be unrestricted, with no visible barriers or entry controls. The physical layout is typical for such environments, but lacks security-enhancing features.

Threat Exposure The primary threat vectors include unauthorized access and potential information leakage. Given the lack of surveillance, even low-skilled intruders could exploit these weaknesses. The likelihood of such events is heightened by the absence of deterrent measures.

Strategic Recommendations Immediate investment in surveillance technology, such as cameras, is crucial to enhance monitoring capabilities. Implementing access control systems will significantly reduce unauthorized entry risks. These measures will improve operational security and protect sensitive information, justifying the investment with potential risk mitigation.

Key Vulnerabilities:

- Absence of Surveillance Systems (HIGH)
- Unrestricted Access (HIGH)

Key Recommendations:

- Deploy surveillance cameras at strategic locations within the meeting room.
- Install access control systems at entry points to restrict unauthorized entry.

Conclusion:

Critical Risks The most urgent risks include the absence of surveillance systems and unrestricted access. These gaps significantly increase the likelihood of unauthorized activities and potential information breaches.

Primary Security Strengths The controlled environment, with limited entry points, is a strength; however, it is undermined by the lack of effective security measures.

Business Impact Summary The current security state poses a risk to business operations by exposing sensitive information and increasing the potential for unauthorized access. This could lead to financial losses and reputational damage if not addressed.

Expected Security Improvement Implementing the recommended surveillance and access control measures is expected to significantly enhance security, raising the security score to 75 and reducing the risk level to Medium. This will improve monitoring, deter unauthorized access, and protect sensitive information.

Consultant Opinion Addressing the identified vulnerabilities through immediate action is crucial for enhancing the security posture of this sub-area. The recommended measures will provide robust monitoring and access control, aligning the security state with acceptable risk thresholds.

Recommended Reassessment Interval A reassessment is recommended within 6 months to ensure the effectiveness of implemented measures and to adjust strategies as necessary.

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION

Requirements for Use

Nondisclosure

This document contains Protected Critical Infrastructure Information (PCII). In accordance with the provisions of the Critical Infrastructure Information Act of 2002 (the CII Act), (6 U.S.C. §671- 674), PCII is exempt from release under the Freedom of Information Act (5 U.S.C. §552) and similar State and local disclosure laws. Unauthorized release may result in criminal and administrative penalties. Safeguard and disseminate in accordance with the CII Act, the implementing Regulation at 6 C.F.R. part 29 (the Final Rule) and PCII Program requirements.

By reviewing this cover sheet and accepting the attached PCII you are agreeing not to disclose it to other individuals without following the access requirements and to abide by the guidance contained herein. Your acceptance provides immediate access only to the attached PCII. If not a PCII Authorized User, you are required to complete certification within 30 days of receipt of this information.

For Certification <https://www.cisa.gov/pcii-authorized-user-training> For Assistance pcii-assist@cisa.dhs.gov

Access

Individuals eligible to access the attached PCII must be Federal, State or local government employees or their designated contractors and must meet all the following requirements:

- Assigned to homeland security duties related to this critical infrastructure
- Demonstrate a valid need-to-know
- Sign a Non-Disclosure Agreement (except Federal employees)

Handling

Storage Store PCII in a secure container. **Do not leave this document unattended.**

Dissemination Methods:

Email Encrypt the email if possible. If unavailable, use approved email systems per PCII Program guidelines. Send PCII as a password protected attachment and provide the password in a separate email.

Mail USPS First Class mail or an equivalent. Seal the document in an opaque envelope, to prevent inadvertent opening, then place it inside a second plain outer envelope without PCII markings. Include sender's and recipient's full names and addresses on the outer envelope and add "POSTMASTER: DO NOT FORWARD. RETURN TO SENDER." below return address.

Telephone Use a secure telephone connection. If unavailable or impractical, verify the caller on other end is a PCII Authorized User and state you will discuss PCII.

Hand Delivery Authorized individuals hand carrying PCII must control it from loss or viewing throughout transit.

Reproduction Ensure this cover sheet is the first page of all reproductions containing PCII.

Destruction Destroy copies of this document when no longer required according to PCII Program procedures.

For details on access, marking, and handling requirements, see the *PCII Program Procedures Manual*.

Sanitized Products

You may create a sanitized work product using PCII. The product must not reveal any information relating to the identity of the submitting person or entity (explicitly or implicitly); is proprietary, business sensitive, or trade secret; and is otherwise not customarily in the public domain.

Derivative Products

Mark a newly created document derived from PCII with "PROTECTED CRITICAL INFRASTRUCTURE INFORMATION" in the header and footer of pages containing PCII. Mark (PCII) beside each paragraph containing PCII. Attach a PCII green cover sheet on all newly created derivative products containing PCII. Include the PCII Submission Identification Number(s) of the source document(s) on the newly created document as a footnote.

Submission Identification Number

PCII-2027

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION



Executive Security Area Summary

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

40 / 100

RISK CLASSIFICATION

HIGH RISK

TABLE OF CONTENTS

EXECUTIVE ASSESSMENT SUMMARY	4
DEVICE ANALYSIS	5
CORE VULNERABILITY PROFILE	6
PRIORITY REMEDIATION ACTIONS	7
STRATEGIC CONCLUSION	8

1. Executive Assessment Summary

(PCI) Security Posture

The current security posture of this sub-area is inadequate, with significant gaps in surveillance and access control mechanisms. The existing controls fail to meet the acceptable risk threshold, primarily due to the absence of electronic monitoring devices.

Environment Overview

The sub-area serves as a meeting room within a facility, characterized by a central table and seating for collaborative activities. Access appears to be unrestricted, with no visible barriers or entry controls. The physical layout is typical for such environments, but lacks security-enhancing features.

Threat Exposure

The primary threat vectors include unauthorized access and potential information leakage. Given the lack of surveillance, even low-skilled intruders could exploit these weaknesses. The likelihood of such events is heightened by the absence of deterrent measures.

1. Lack of Surveillance: No visible cameras or monitoring devices, increasing vulnerability to unauthorized access.
2. Unrestricted Access: Open access points without barriers or access control increase the risk of intrusion.
3. Information Security Risks: The environment is prone to information leakage due to lack of secure communication measures.

Strategic Recommendations

Immediate investment in surveillance technology, such as cameras, is crucial to enhance monitoring capabilities. Implementing access control systems will significantly reduce unauthorized entry risks. These measures will improve operational security and protect sensitive information, justifying the investment with potential risk mitigation.

2. Device Analysis

(PCII) No electronic security devices are deployed in this sub-area, resulting in a significant monitoring gap. The absence of surveillance cameras or access control systems leaves the area vulnerable to unauthorized access and information breaches. Implementing cameras and access control systems would provide critical monitoring capabilities, reducing the risk of intrusion and enhancing overall security.

3. Core Vulnerability Profile

ABSENCE OF SURVEILLANCE SYSTEMS

HIGH

Description: No visible cameras or monitoring devices in the video frames.

Evidence: No visible cameras or monitoring devices in the video frames.

Likelihood: High

Recommended Mitigation: Install surveillance cameras to monitor activities.

UNRESTRICTED ACCESS

HIGH

Description: Open access points without physical barriers observed in video frames.

Evidence: Open access points without physical barriers observed in video frames.

Likelihood: Medium

Recommended Mitigation: Implement access control systems.

4. Priority Remediation Actions

IMMEDIATE

Deploy surveillance cameras at strategic locations within the meeting room.

Vulnerability Addressed: VULN-1

Expected Risk Reduction: Significant reduction in unauthorized access risk.

IMMEDIATE

Install access control systems at entry points to restrict unauthorized entry.

Vulnerability Addressed: VULN-2

Expected Risk Reduction: Significant improvement in access control.

5. Strategic Conclusion

(PCII) The current security posture of this sub-area is inadequate, with a high risk level due to the absence of surveillance systems and access controls. The environment lacks necessary security measures, making it vulnerable to unauthorized access and information leakage.

Critical Risks

The most urgent risks include the absence of surveillance systems and unrestricted access. These gaps significantly increase the likelihood of unauthorized activities and potential information breaches.

Primary Security Strengths

The controlled environment, with limited entry points, is a strength; however, it is undermined by the lack of effective security measures.

Business Impact Summary

The current security state poses a risk to business operations by exposing sensitive information and increasing the potential for unauthorized access. This could lead to financial losses and reputational damage if not addressed.

Expected Security Improvement

Implementing the recommended surveillance and access control measures is expected to significantly enhance security, raising the security score to 75 and reducing the risk level to Medium. This will improve monitoring, deter unauthorized access, and protect sensitive information.

Consultant Opinion

Addressing the identified vulnerabilities through immediate action is crucial for enhancing the security posture of this sub-area. The recommended measures will provide robust monitoring and access control, aligning the security state with acceptable risk thresholds.

Recommended Reassessment Interval

A reassessment is recommended within 6 months to ensure the effectiveness of implemented measures and to adjust strategies as necessary.

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION

Requirements for Use

Nondisclosure

This document contains Protected Critical Infrastructure Information (PCII). In accordance with the provisions of the Critical Infrastructure Information Act of 2002 (the CII Act), (6 U.S.C. §671- 674), PCII is exempt from release under the Freedom of Information Act (5 U.S.C. §552) and similar State and local disclosure laws. Unauthorized release may result in criminal and administrative penalties. Safeguard and disseminate in accordance with the CII Act, the implementing Regulation at 6 C.F.R. part 29 (the Final Rule) and PCII Program requirements.

By reviewing this cover sheet and accepting the attached PCII you are agreeing not to disclose it to other individuals without following the access requirements and to abide by the guidance contained herein. Your acceptance provides immediate access only to the attached PCII. If not a PCII Authorized User, you are required to complete certification within 30 days of receipt of this information.

For Certification <https://www.cisa.gov/pcii-authorized-user-training> For Assistance pcii-assist@cisa.dhs.gov

Access

Individuals eligible to access the attached PCII must be Federal, State or local government employees or their designated contractors and must meet all the following requirements:

- Assigned to homeland security duties related to this critical infrastructure
- Demonstrate a valid need-to-know
- Sign a Non-Disclosure Agreement (except Federal employees)

Handling

Storage Store PCII in a secure container. **Do not leave this document unattended.**

Dissemination Methods:

Email Encrypt the email if possible. If unavailable, use approved email systems per PCII Program guidelines. Send PCII as a password protected attachment and provide the password in a separate email.

Mail USPS First Class mail or an equivalent. Seal the document in an opaque envelope, to prevent inadvertent opening, then place it inside a second plain outer envelope without PCII markings. Include sender's and recipient's full names and addresses on the outer envelope and add "POSTMASTER: DO NOT FORWARD. RETURN TO SENDER." below return address.

Telephone Use a secure telephone connection. If unavailable or impractical, verify the caller on other end is a PCII Authorized User and state you will discuss PCII.

Hand Delivery Authorized individuals hand carrying PCII must control it from loss or viewing throughout transit.

Reproduction Ensure this cover sheet is the first page of all reproductions containing PCII.

Destruction Destroy copies of this document when no longer required according to PCII Program procedures.

For details on access, marking, and handling requirements, see the *PCII Program Procedures Manual*.

Sanitized Products

You may create a sanitized work product using PCII. The product must not reveal any information relating to the identity of the submitting person or entity (explicitly or implicitly); is proprietary, business sensitive, or trade secret; and is otherwise not customarily in the public domain.

Derivative Products

Mark a newly created document derived from PCII with "PROTECTED CRITICAL INFRASTRUCTURE INFORMATION" in the header and footer of pages containing PCII. Mark (PCII) beside each paragraph containing PCII. Attach a PCII green cover sheet on all newly created derivative products containing PCII. Include the PCII Submission Identification Number(s) of the source document(s) on the newly created document as a footnote.

Submission Identification Number

PCII-2027

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION



Executive Security Area Summary

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
AREA NAME	Perimeter
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

70 / 100

RISK CLASSIFICATION

MEDIUM RISK

TABLE OF CONTENTS

EXECUTIVE ASSESSMENT SUMMARY	4
CPTED SECURITY SNAPSHOT	5
CORE VULNERABILITY PROFILE	6
STRATEGIC CONCLUSION	7
ATTACHED SUBAREA ASSESSMENTS	8
SUB-AREA REPORTS	
SUB AREA	9

1. Executive Assessment Summary

(PCII) The security assessment of the meeting room within the facility's perimeter reveals a moderately secure environment that relies heavily on natural surveillance and regular maintenance. The open layout of the room allows for oversight during meetings, contributing to its security strengths. However, the absence of visible security devices such as CCTV cameras and electronic access controls presents significant vulnerabilities. This lack of automated systems increases the risk of unauthorized access and limits the facility's ability to monitor and respond to security incidents effectively. Additionally, while the room is actively used for meetings, providing some natural surveillance, there is no security presence during non-meeting times, leaving the area vulnerable to unauthorized access. To enhance security, it is recommended to install surveillance cameras and electronic access control systems, improve external signage to reinforce territorial boundaries, and schedule regular security checks during non-peak hours. These measures are expected to significantly improve the security posture, aligning it more closely with industry standards for secured facilities. The projected outcome is a more robust security environment that reduces liability and ensures business continuity.

2. CPTED Security Snapshot

(PCII) CPTED analysis across access controls, surveillance, reinforcement, and maintenance guidelines:

NATURAL SURVEILLANCE

60/100

MEDIUM

Findings: Limited visibility of access points; No visible surveillance devices

ACCESS CONTROL

50/100

HIGH

Findings: No visible access control mechanisms

TERRITORIAL REINFORCEMENT

65/100

MEDIUM

Findings: Clear signage and defined meeting space

MAINTENANCE

70/100

MEDIUM

Findings: Well-maintained environment

ACTIVITY SUPPORT

55/100

HIGH

Findings: Active meeting with engagement

3. Core Vulnerability Profile

LACK OF SURVEILLANCE DEVICES

HIGH

Evidence: No visible CCTV cameras or surveillance devices.

Likelihood: High

Recommended Mitigation: Install CCTV cameras to provide continuous surveillance coverage.

ABSENCE OF ELECTRONIC ACCESS CONTROLS

MEDIUM

Evidence: No visible electronic access control systems.

Likelihood: Medium

Recommended Mitigation: Implement electronic access control systems to restrict unauthorized access.

4. Strategic Conclusion

(PCII) The assessment of the meeting room's security highlights the need for immediate improvements in surveillance and access control. By installing CCTV cameras and electronic access control systems, the facility can significantly enhance its security posture, reducing unauthorized access risks and aligning with industry standards. These measures will provide a more robust security environment, ensuring business continuity and reducing liability. Continuous monitoring and regular updates to security protocols will be essential to maintaining this improved security posture.

5. Attached Subarea Assessments

Sub Area

Security Score: 45 / 100

Risk Level: High

Executive Summary:

Security Posture The current security posture of the Sub Area is inadequate, with significant vulnerabilities due to limited surveillance and unmanaged access points. The existing CCTV camera provides some coverage, but the overall security controls are insufficient to mitigate high-risk threats effectively.

Environment Overview This Sub Area is a loading dock facility featuring multiple docks, a delivery truck, and storage items such as a dumpster and barrels. The environment is industrial, with several potential access points, including loading dock doors and adjacent areas.

Threat Exposure The primary threats include unauthorized access and theft, facilitated by the open nature of the loading docks and limited surveillance. The skill level required to exploit these vulnerabilities is low, increasing the likelihood of incidents.

Strategic Recommendations Enhance security by installing additional CCTV cameras to cover all potential entry points and blind spots. Implement physical barriers or access control systems at loading docks to reduce unauthorized access. These measures will significantly improve the security posture and reduce operational risks associated with theft and unauthorized access.

Key Vulnerabilities:

- Limited Surveillance Coverage (HIGH)
- Unsecured Access Points (HIGH)
- Unsecured Storage Materials (MEDIUM)

Key Recommendations:

- Install additional CCTV cameras to cover all loading dock areas and access points.
- Install physical barriers or implement access control at loading docks.
- Implement measures to secure and monitor storage items near docks.

Conclusion:

Critical Risks The most urgent risks involve unauthorized access through unguarded loading docks and the potential for theft or unauthorized activities due to unsecured storage materials. Immediate action is required to mitigate these vulnerabilities.

Primary Security Strengths The existing CCTV camera provides a foundational level of surveillance, which can be built upon to enhance the overall security infrastructure.

Business Impact Summary The current security deficiencies pose a significant threat to business operations, with potential financial and reputational impacts from theft and unauthorized access. Addressing these vulnerabilities will protect assets and ensure operational continuity.

Expected Security Improvement Implementing the recommended actions is expected to improve the security score to 75, reducing the risk level to medium. Enhanced surveillance and access control will significantly decrease the likelihood of security breaches.

Consultant Opinion The Sub Area's security trajectory is positive, provided the recommended improvements are implemented promptly. These actions will address critical vulnerabilities and establish a more robust security framework.

Recommended Reassessment Interval A reassessment should be conducted within 6 to 12 months to ensure the effectiveness of implemented measures and to identify any new vulnerabilities.

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION

Requirements for Use

Nondisclosure

This document contains Protected Critical Infrastructure Information (PCII). In accordance with the provisions of the Critical Infrastructure Information Act of 2002 (the CII Act), (6 U.S.C. §671- 674), PCII is exempt from release under the Freedom of Information Act (5 U.S.C. §552) and similar State and local disclosure laws. Unauthorized release may result in criminal and administrative penalties. Safeguard and disseminate in accordance with the CII Act, the implementing Regulation at 6 C.F.R. part 29 (the Final Rule) and PCII Program requirements.

By reviewing this cover sheet and accepting the attached PCII you are agreeing not to disclose it to other individuals without following the access requirements and to abide by the guidance contained herein. Your acceptance provides immediate access only to the attached PCII. If not a PCII Authorized User, you are required to complete certification within 30 days of receipt of this information.

For Certification <https://www.cisa.gov/pcii-authorized-user-training> For Assistance pcii-assist@cisa.dhs.gov

Access

Individuals eligible to access the attached PCII must be Federal, State or local government employees or their designated contractors and must meet all the following requirements:

- Assigned to homeland security duties related to this critical infrastructure
- Demonstrate a valid need-to-know
- Sign a Non-Disclosure Agreement (except Federal employees)

Handling

Storage Store PCII in a secure container. **Do not leave this document unattended.**

Dissemination Methods:

Email Encrypt the email if possible. If unavailable, use approved email systems per PCII Program guidelines. Send PCII as a password protected attachment and provide the password in a separate email.

Mail USPS First Class mail or an equivalent. Seal the document in an opaque envelope, to prevent inadvertent opening, then place it inside a second plain outer envelope without PCII markings. Include sender's and recipient's full names and addresses on the outer envelope and add "POSTMASTER: DO NOT FORWARD. RETURN TO SENDER." below return address.

Telephone Use a secure telephone connection. If unavailable or impractical, verify the caller on other end is a PCII Authorized User and state you will discuss PCII.

Hand Delivery Authorized individuals hand carrying PCII must control it from loss or viewing throughout transit.

Reproduction Ensure this cover sheet is the first page of all reproductions containing PCII.

Destruction Destroy copies of this document when no longer required according to PCII Program procedures.

For details on access, marking, and handling requirements, see the *PCII Program Procedures Manual*.

Sanitized Products

You may create a sanitized work product using PCII. The product must not reveal any information relating to the identity of the submitting person or entity (explicitly or implicitly); is proprietary, business sensitive, or trade secret; and is otherwise not customarily in the public domain.

Derivative Products

Mark a newly created document derived from PCII with "PROTECTED CRITICAL INFRASTRUCTURE INFORMATION" in the header and footer of pages containing PCII. Mark (PCII) beside each paragraph containing PCII. Attach a PCII green cover sheet on all newly created derivative products containing PCII. Include the PCII Submission Identification Number(s) of the source document(s) on the newly created document as a footnote.

Submission Identification Number

PCII-2027

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION



Executive Security Area Summary

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

45 / 100

RISK CLASSIFICATION

HIGH RISK

TABLE OF CONTENTS

EXECUTIVE ASSESSMENT SUMMARY	4
DEVICE ANALYSIS	5
CORE VULNERABILITY PROFILE	6
PRIORITY REMEDIATION ACTIONS	7
STRATEGIC CONCLUSION	8

1. Executive Assessment Summary

(PCII) Security Posture

The current security posture of the Sub Area is inadequate, with significant vulnerabilities due to limited surveillance and unmanaged access points. The existing CCTV camera provides some coverage, but the overall security controls are insufficient to mitigate high-risk threats effectively.

Environment Overview

This Sub Area is a loading dock facility featuring multiple docks, a delivery truck, and storage items such as a dumpster and barrels. The environment is industrial, with several potential access points, including loading dock doors and adjacent areas.

Threat Exposure

The primary threats include unauthorized access and theft, facilitated by the open nature of the loading docks and limited surveillance. The skill level required to exploit these vulnerabilities is low, increasing the likelihood of incidents.

- Limited Surveillance: Only one CCTV camera is installed, providing inadequate coverage (Image ID 44).
- Accessible Entry Points: Multiple loading docks and adjacent areas are potential unauthorized entry points (Image ID 44).
- Unsecured Storage: The presence of a dumpster and barrels near the loading docks could be used to conceal criminal activity (Image ID 44).

Strategic Recommendations

Enhance security by installing additional CCTV cameras to cover all potential entry points and blind spots. Implement physical barriers or access control systems at loading docks to reduce unauthorized access. These measures will significantly improve the security posture and reduce operational risks associated with theft and unauthorized access.

2. Device Analysis

(PCII) The deployed CCTV camera is positioned to monitor the loading dock area, providing some level of surveillance. However, its effectiveness is limited by its singular placement, leaving multiple potential access points unmonitored. The camera's condition appears functional based on the available closeup image, but its coverage is insufficient for comprehensive security. Additional cameras are recommended to ensure full coverage and effective monitoring.

3. Core Vulnerability Profile

LIMITED SURVEILLANCE COVERAGE

HIGH

Description: Only one CCTV camera present, covering a limited area (Image ID 44).

Evidence: Only one CCTV camera present, covering a limited area (Image ID 44).

Likelihood: High

Recommended Mitigation: Install additional cameras to ensure full coverage.

UNSECURED ACCESS POINTS

HIGH

Description: Multiple loading docks without physical barriers (Image ID 44).

Evidence: Multiple loading docks without physical barriers (Image ID 44).

Likelihood: High

Recommended Mitigation: Implement physical barriers or access control systems.

UNSECURED STORAGE MATERIALS

MEDIUM

Description: Dumpster and barrels near loading docks (Image ID 44).

Evidence: Dumpster and barrels near loading docks (Image ID 44).

Likelihood: Medium

Recommended Mitigation: Secure and monitor storage items.

4. Priority Remediation Actions

IMMEDIATE

Install additional CCTV cameras to cover all loading dock areas and access points.

Vulnerability Addressed: VULN-1

Expected Risk Reduction: Significant reduction in unauthorized access risk.

SHORT-TERM

Install physical barriers or implement access control at loading docks.

Vulnerability Addressed: VULN-2

Expected Risk Reduction: Substantial decrease in unauthorized entry risk.

MEDIUM-TERM

Implement measures to secure and monitor storage items near docks.

Vulnerability Addressed: VULN-3

Expected Risk Reduction: Moderate reduction in misuse risk.

5. Strategic Conclusion

(PCII) The security posture of the Sub Area is currently rated as high risk, primarily due to limited surveillance and unsecured access points. The presence of a single CCTV camera provides some monitoring; however, it is insufficient to cover the entire area effectively.

Critical Risks

The most urgent risks involve unauthorized access through unguarded loading docks and the potential for theft or unauthorized activities due to unsecured storage materials. Immediate action is required to mitigate these vulnerabilities.

Primary Security Strengths

The existing CCTV camera provides a foundational level of surveillance, which can be built upon to enhance the overall security infrastructure.

Business Impact Summary

The current security deficiencies pose a significant threat to business operations, with potential financial and reputational impacts from theft and unauthorized access. Addressing these vulnerabilities will protect assets and ensure operational continuity.

Expected Security Improvement

Implementing the recommended actions is expected to improve the security score to 75, reducing the risk level to medium. Enhanced surveillance and access control will significantly decrease the likelihood of security breaches.

Consultant Opinion

The Sub Area's security trajectory is positive, provided the recommended improvements are implemented promptly. These actions will address critical vulnerabilities and establish a more robust security framework.

Recommended Reassessment Interval

A reassessment should be conducted within 6 to 12 months to ensure the effectiveness of implemented measures and to identify any new vulnerabilities.