Problem Number ID: TTE 01- 1 (TTE - Test Troubleshooting Exercise)
Issue Type: Audio
Issue Found: Audio Input Configuration Mismatch
Date: 11/1/2026
Time - Issue: 10:22pm
Time - Resolution: 10:57pm
Issue Description: After successfully establishing a Bluetooth connection between the Soundcore Q20i headset and Windows 11, the operating system recognized the headphones as the default audio output device. However, the system continued using the integrated Microphone Array (AMD Audio Device) as the default audio input device.

The Soundcore Q20i microphone appeared greyed out in Windows Sound Settings, resulting in an audio input configuration mismatch, where audio playback was routed through the Bluetooth headset while microphone input remained assigned to the computer's integrated microphone.

Steps Taken To Resolve:
Connect Headphones: Turn on the Soundcore Q20i headphones and connect them through Bluetooth.
Open Sound Settings: Press Windows + I, then navigate to System → Sound.
Check Audio Output: Confirm that Soundcore Q20i is selected as the default output device.
Correct Audio Input: Under Input, change the default microphone from Microphone Array (AMD Audio Device) to Headset (Soundcore Q20i).
Test Microphone: Select the headset microphone, start a microphone test, speak, and play back the recording.
Verify Resolution: Confirm that both headphone audio and microphone input function correctly.

Solution: I switched the default input from the computer's built-in microphone to the headset microphone in Windows Sound Settings. Then I tested it to confirm it was working.

I opened Windows Sound Settings and changed the default input device from the computer’s built-in microphone to the Soundcore Q20i headset microphone. I then tested the microphone to verify that it was functioning correctly.

Final Status: Resolved
Time - Resolution: 10:57pm