

Issue ISS-008 North Slab Edge

Practice file: Cedarline Training Hall, job SYNTH-HALL-01.

Original text. Not a real project and not a platform export.

Number: ISS-008

Status: Open

Type: Quality

Location: north edge of the existing equipment pad, about 2 feet long.

Description: the edge is spalled. The superintendent photographed it and left the area uncovered.

Requested action: the architect reviews the photo and says whether a patch is enough.

This issue is a quality note. It does not set the placement rule for the new hall slab. That rule is in the concrete section and in RFI-014.

Opened: 2026-04-11. Assigned to: architect of record (practice role).

Root cause: unknown until the review. Do not invent one in the daily report.