

Division 03 Cast-in-Place Concrete

Section 03 30 00.

Curing: keep cast-in-place concrete wet for 7 days when the daily low stays above 40 F.

Weather limit: do not place concrete when the air temperature is below 40 F or above 95 F.

Strength: do not load the slab until test cylinders reach 75 percent of the specified strength.