Roof / south vent

No leak observed at vent.

System	Observation	Status
Roof	Vent condition	See note
Panel	Cover not removed	Not inspected
HVAC	Filter	