




Charging Energy vs Tunnel Gap



Lever Arm vs Tunnel Gap



Gap Resistance vs Tunnel Gap



Phosphorus (P) Arsenic (As)