10000237 KIRAN PETKAR

Employee Name : KIRAN PETKARManager's Name : Prashant Pathak

Goalsheet Approval Date: 23-Apr-2017

KRA Category : Business KRA Weightage : 20 _

I/av	l lait	KDI	Value	(4)	(2)	(2)	(4)	(F)	Actual	Approises
Key Performance	Unit	KPI Weightage	Value	(1) Unsatisfactor	(2) Needs	(3) Good Solid	(4) Superior	(5) Outstanding	Actual achievement	Appraisee comment on
Indicator		vveigritage		y	Improvement	Performance	Performance	Performance	of year end	actual
(KPI)				Performance	in provenient	. Giroimanoo			or your one	achievement
description										
Support for commissioning &	Text			Mar_16	Mid March	Feb_17	Mid Feb	Jan_17	01-01-2017	1) 1 no pressure transmitter & 8 nos
modification of H2										Control valve are
Loop reactor Batch automation for										removed for servicing same
increase in										logic
batch/Production& it's commissioning										implementation & DCS configuration
activity										done at site for
										catalyst project of Loop reactor dated
										on 1 oct 2016 2) better efficiency
										and operation
										Opportunity base PM & CM of loop
										reactor completed
										on 26 sep -2016 & on 23 feb -2017
										3)instrument availability done by
										using Regular
										calibration ,servicing & spare
										inventory of XV-30
										5,XV-306,XV-311, oop Hydrogen
										service valves-PC V-302A,PCV-701B
										V .This help to
										reduce repetitive failure almost zero.
										4) New LT-302 provided for V-707
2.H2 Linde Tail	Text			Mar_16	Mid March	Feb_17	Mid Feb	Jan_17	Control valve blank	Existing PRV
Gas line new control valve									datasheet mail to user Dept for filling	venting during normal operation,
installation &									the process	so this PRV to be
commissioning activity.									parameter in November'2016.	replaced with control valve, for
										selecting the control valve
										process parameter
3.H2 Caloric	Text			Jan_16	Mid Jan	Dec_16	Mid Dec	Nov_16	H2 Caloric Natural	mail to user Dept. Natural gas line
Natural gas line FT installation &									gas line FT installation &	existing mass flow meter failed & this
commissioning									commissioning	cost is approx. 12
activity.									carried out in August'2016.	lakh, so on same location
										multivariable type
										orifice flow transmitter
										installed having costing is approx.
										2.5 lakh. It's
										commissioning done & checked
										performance found
4. Support to other	Text			Mar_16	Mid March	Feb_17	Mid Feb	Jan_17	100%	working okay. 1)Fatty Acid
departments for commissioning &									complete==Suppor t & logic	headload calculation, 2)Fatty
modification of :									implementation for	Acid Pre-heater
a.To achieve energy saving. b.									the Improvement plants/projects in	thermowell & RTD sensor location
Commissioning Supports for									given time frame by December'2016	purpose new thermowell/RTD
projects Beads									end.	procurement done
c.Fatty Acid Pre- heater thermowll &										in Dec'2016 & waiting for
RTD sensor location to be					1				1	shutdown opportunity. 3)GDP
relocated. d.GDP					1					Plant Thermic fluid
Plant Thermic fluid line FT relocation					1					line FT relocation drawing submitted
& installation. e.TT					1				1	to concern Dept
point added in supply/return line &					1				1	
it's cabling work, f.CPP Vam Control					1				1	
valve installation &					1					
it's loop checking. 5.Prepare the	Text					Every week report		Before 30 th	Report prepared	Daily routine plant
report for					1	prepared & action			before 30th of	round abnormality
monitoring of abnormalities in					1	to taken on abnormality			every month	are observed & as per availability of
plant for enhanching the					1				1	material/resources corrective action
process.					1				1	taken 1) Improve
					1				1	operation & life of instrument-250
I	I	I I	1	I	I	I	I	I	I	I

Key Performance Indicator (KPI) description	Unit	KPI Weightage	Value	(1) Unsatisfactor y Performance	(2) Needs Improvement	(3) Good Solid Performance	(4) Superior Performance	(5) Outstanding Performance	Actual achievement of year end	Appraisee comment on actual achievement
										no's canopy provided to instrument which was badly affecting acidic water of cooling tower 2) Safety & reliability -30 nos corrosive stand & instrument support replaced & modified which give operation safety and reliability to maintenance people 3) DCS panel -A) PMMC DCS room panel door hinges replaced with spare one dated on 2 Jan 2017. B) panel light, fan of K4 panel operation checked on 5 Nov 2016 4) To improve steam consumption - A) DFA-C-401 header & SM30/50 boiler PRV (MAKE-Spirax) Marshall) servicing done dated on 11 Feb-2017.

KRA Category : Process KRA Weightage : 20 _

Key Performance Indicator (KPI) description	Unit	KPI Weightage	Value	(1) Unsatisfactor y Performance	(2) Needs Improvement	(3) Good Solid Performance	(4) Superior Performance	(5) Outstanding Performance	Actual achievement of year end	Appraisee comment on actual achievement
1.To plan & complete the servicing of below listed plant valve's for better operation & performance 1)Hydrogen calloric PSA valve.2)H2 Linde PSA Valve.3)Nitrogen Plant PSA valve 4)Natural Gas Skid 5)H2 Loop Reactor valve	Text					95% complete		100% complete	100% complete	100 % Completed as per schedule & clearence As per Instrument shutdwn Job list clearence As per Instrument shutdwn Job list clearence in a strain of the formation of the functioning of serviced instruments:1) Hydrogen caloric PSA valve:Hydrogen caloric PSA valve:Hydrogen caloric PSA valve:Hydrogen carried out every 1.5 years for avoiding the downtime/failure.Last time servicing carried out in PSA valve servicing carried out every 1.5 years for avoiding the downtime/failure.Last time servicing carried out every 1.5 years for avoiding the downtime/failure.Last time servicing carried out every 1.5 years for avoiding the downtime/failure.Last time servicing carried out in May' 2016.3)Nitrogen Plant PSA valve servicing carried out in May' 2016.3)Nitrogen Plant PSA valve servicing carried out every 1.0 years for avoiding the downtime/failure. Also all 9 no's Actuator servicing carried out.Last servicing done in N

Key Performance Indicator (KPI) description	Unit	KPI Weightage	(1) Unsatisfactor y Performance	(2) Needs Improvement	(3) Good Solid Performance	(4) Superior Performance	(5) Outstanding Performance	Actual achievement of year end	Appraisee comment on actual achievement
2.To ensure the Safety reliability in Plants by checking the thermowells of Fatty Acid Columns &	Text		20 thermowell	25 thermowell	30 thermowell inspection.	35 thermowell	40 thermowell	60 no's Thermowell inspection done against target of 40 no's	ovember/2016.4)N atural Gas Skid:2 Bar & 4 Bar==Both Skid servicing & overhauling carried out in Cotober/2016.5)H2 Loop Reactor valve:Control valve PCV-302A/PCV-70 1BV,XV-311,XV-30 6,XV-3068 servicing & overhauling carried Fatty Acid Plant distillation section 40 no's & Splitting section 12 no's thermowell inspection/checkin
Hyrdogen Reformer. (Qty: 90 no's)									g carried out. Hydrogen caloric & H2 Linde Plant 8 no's thermowell inspection/checkin g carried out
3.Coal heater A& B—Bed temperature thermowell to be replaced with better MOC Thermowell for long life.((Qty: 8 no's)	Text		1 no's Thermowell	3 no's Thermowell	5 no's Thermowell	6 no's Thermowell	8 no's Thermowell	All 8 no's thermowell completed	All 8 no's thermowell inspection carried out & out of this 4 no's Thermowell replaced with new better MOC thermowell in October'2016.
4.Non working instrument loops made okay. 1) C-303:FT-R351A 2)SPD-FT-50519A 3)C-402FT-4305 4)Fatty Alcohol FT-1003 5) Fatty Acid XV-9504 6)Column attached TT.	Text			1 instrument out of 8 non working instruments: before March'2017.	2 instrument out of 8 non working instruments: 25% complete before March'2017.	Instrument out of 8 non working instruments: 50% complete before March'2017.	6 instrument out of 8 non working instruments: 75% complete before March'2017.	All 6 no's instrument made okay & it's working satisfactory.	1) C-303:==FT- R351A & FT- R351B are integral mounting. Due to high temperature flowmeter electronics gets hot & chances of failure of electronics & sensor, also malfunctioning of instrument. This both transmitter convert integral to remote dated on 26 oct 2016. Now they working okay. 2)SPD-FT-50519A showing wrong indication & also chance of sensor failure. they convert integral to remote dated on 13 July 2016 3)C-402 FT-4305 vortex shedding frequency changed & configuration done, now working okay. 4) Fatty Alcohol FT-1003 New high temp sensor replaced with spare on dated on 16 Nov 2016-Now working okay.
5.Planning for the shutdown jobs by prepaing the list, procuring the material and service required	Text				100% complete within define timelimit			100% complete	List of completed vs pending jobs prepared a month before the shutdown. shutdown activities finished 2 days before scheduled target

KRA Category : People KRA Weightage : 20 _

Key	Unit	KPI	Value	(1)	(2)	(3)	(4)	(5)	Actual	Appraisee
Performance		Weightage		Unsatisfactor	Needs	Good Solid	Superior	Outstanding	achievement	comment on
Indicator				У	Improvement	Performance	Performance	Performance	of year end	actual
(KPI)				Performance	·				,	achievement
description										
1. To meet IDP	Text				-	Mar'17			100% complete	Problem solving
completion on problem solving										Technique attened in year 2016 &
Techniques										same implemented
										in routine maintenance
										activity.
2. Class room	Text					Dec'16			Completed in	DCS advanced
training on DCS programming.									November'2016	training for Yokogawa and
programming.										Invensys attended
										while on the job for
										shutdown activities. In Aug
										2016,
										November'2016. Also while
										performing AMC
										activities with OEM
										engineers learnt advance functions
										in DCS on
3. To cover all the	Text					1000/			4000/	quarterly basis. 1) In 2016-2017
people of	rext			•	•	100% complete	·	•	100% complete	Covered 100%
Department for										people of
personal & plant safety training										instrument department related
programme.										to PPEs ,personal
										safety ,Permit
										system,industrial safety &
										emergency
										preparedness , First Aid refresher
										training, 2) Safety
										awareness training
										to new joinees, GET about
										instruments
										working related
										safety, toolbox talk to contract
										employees etc. = 5
										Apprentice + New
										Own instruments 6+ working
										persons.
4.New SOP generation for	Text			Nil	1 New SOPs	2 New SOPs	3 New SOPs	5 New SOPs	8 New SOPs prepared.	8 new SOP/Calibration
excellence path.									propareu.	Procedure are
1										prepared.
								I		

KRA Category : Business KRA Weightage : 40 _

Key Performance Indicator	Unit	KPI Weightage	Value	(1) Unsatisfactor v	(2) Needs Improvement	(3) Good Solid Performance	(4) Superior Performance	(5) Outstanding Performance	Actual achievement of year end	Appraisee comment on actual
(KPI) description				Performance					,	achievement
1)Maintenance of :CM Preparing calibration reports for Critical Instruments 2) Remaining Instruments Preparing PM format & PM checklist 3)History card updation	Text			<90% for all functions	90% for all functions	1,95% completion of CM total: 242 nos. 2)PM of Remaining 384 nos Instruments 3) Not pending more than a week after completion of job	94% for all functions	95% for all functions	1)10% completion of CM total: 242 nos. Preparing report before 5th of each month. 2)PM of Remaining Instruments: 384no s. Preparing report before 3rd of every month.	100% completed of Fatty Acid distillation section 1) PM of 384 nos instrument & CM of 242 nos instrument & CM of 242 nos instrument completed as per schedule 2)Same above tag Calibration report ,history card , breakdown analysis ,PM& CM check list Prepared 3)Predictive maintenance done for reliability & operation confidence A) Column bottom control valve LCV-3201/LCV-3401/LC V-103/LCV-4301/2 LCV-4301/2 L

Key Performance	Unit	KPI Weightage	Value	(1) Unsatisfactor	(2) Needs	(3) Good Solid	(4) Superior	(5) Outstanding	Actual achievement	Appraisee comment on
Indicator (KPI) description		Weightage		y Performance	Improvement	Performance	Performance	Performance	of year end	actual achievement
	Τ									out as per clearance
"2.Reduction in downtime(Last year-140 hrs, Target-126 hrs)	Text			Increase by 10%	No reduction	Reduction by 2%	Reduction by 5% in all plant areas.	Reduction by 7% in all plant areas.	Last year 2015-2016, Down time in Distillation section is 25.00 hrs & this Year 2016-2017 is 9.00 hrs ,neraly 64% improvement	1) Last year 2015-2016 Down time in Distillation section is 25.00 hrs at 55.00 hrs
3.MTBF - a)Bottom level control valve of C301-C302-C303 b)Temperature transmitter of local make, RTDs .	Text			Minimum 5 % improvement.	Minimum 10% improvement.	Minimum 20% improvement. a)Bottom level control valve of C3 01_302_303_Last Year failure _5 times Target: 4 times b)Other Instruments_ Last Year failure 10 times Target: 8 times	Minimum 25% improvement.	Minimum 30% improvement.	80 % improvement. a)Bottom level control valve of C301-302-303-Las t Year failure -5 times, This year failure:1 times. b)Other Instruments- Last Year failure 10 times, This year failure:7 times	failure. 80 % improvement. a) Bottom level control valve of C301-302-303-Las t Year failure-1 times. (C-302 bottom Control LCV-3401 -1 time failure happen, so this valve servicing & overhauling carried out. Also all column bottom control valve 1 valve made ready in workshop as a critical spares in case of emergency. b) Other Instruments- Last Year failure 10 times, This year failure: 10 times, This year failure: 12 times (Temperature transmitter failure transmitter failure E 2 no's displacer level transmitter failure:
4.Failure Analysis reports	Text			Pending for more than 12 days after failure occurance.	Pending for more than 7 days after failure occurance.	Not Pending for more than 5 days after failure occurance.	Not Pending for more than 4 days after failure occurance.	Not Pending for more than 3 days after failure occurance.	100% complete within 2 days of breakdown.	Failure analysis report prepared within 2 days after breakdown, also analysis done for avoiding the repeatative breakdown.