




18

1

zbrojenja

$$\begin{array}{c} \text{||} \quad \diagup \quad \diagdown \quad \text{||} \\ \text{||} \quad \diagdown \quad \diagup \quad \text{||} \end{array}$$

— 100 —

$\frac{1}{x} \cdot \frac{1}{x} = \frac{1}{x^2}$ $\frac{1}{x} \cdot \frac{1}{x} = \frac{1}{x^2}$

ZAGIECIE PRETÓW GÓRNYCH

Do I

$$\frac{40}{40} = 1$$

* – pręt dociąć przy krawędzi/otworze

$\pm 0.00 = 225.50m \text{ n.p.m.}$

Faza	Skala	Branża	Nr rysunku	Data
PW	1:50	KONSTR.	K-10	04.2023