

DIP-8 DIMENSION (FIG. NO. DIM-DIP8-0103-B)




0	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α			4.31			0.170
A1	0.38			0.015		
A2	3.15	3.40	3.65	0.124	0.134	0.144
В	0.38	0.46	0.51	0.015	0.018	0.020
B1	1.27	1.52	1.77	0.050	0.060	0.070
С	0.20	0.25	0.30	0.008	0.010	0.012
D	8.95	9.20	9.45	0.352	0.362	0.372
E	6.15	6.40	6.65	0.242	0.252	0.262
E1		7.62			0.300	
е		2.54			0.100	
L	3.00	3.30	3.60	0.118	0.130	0.142
θ	0°		15°	0°		15 °

DIP-14 DIMENSION (FIG. NO. DIM-DIP14-0103-B)




	Dimen	sions In Mill	meters	Dime	ensions In Inc	ches
Symbol	Min	Nom	Max	Min	Nom	Max
Α		<del></del>	4.31			0.170
A1	0.38			0.015		
A2	3.15	3.40	3.65	0.124	0.134	0.144
В		0.46			0.018	
B1		1.52			0.060	
С		0.25			0.010	
D	19.00	19.30	19.60	0.748	0.760	0.772
E	6.20	6.40	6.60	0.244	0.252	0.260
E1		7.62			0.300	
е		2.54			0.100	
L	3.00	3.30	3.60	0.118	0.130	0.142
θ	0°		15 °	0°		15 °


DIP-16 DIMENSION (FIG. NO. DIM-DIP16-0103-B)



0	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α			4.31			0.170
A1	0.38			0.015		
A2	3.15	3.40	3.65	0.124	0.134	0.144
В	0.38	0.46	0.51	0.015	0.018	0.020
B1	1.27	1.52	1.77	0.050	0.060	0.070
С	0.20	0.25	0.30	0.008	0.010	0.012
D	19.00	19.30	19.60	0.748	0.760	0.772
E	6.15	6.40	6.65	0.242	0.252	0.262
E1		7.62			0.300	
е		2.54			0.100	
L	3.00	3.30	3.60	0.118	0.130	0.142
θ	0.		15°	0°		15°


DIP-28 DIMENSION (FIG. NO. DIM-DIP28-0103-B)






0	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α			5.34			0.210
A1	0.38			0.015		
A2	3.65	3.85	4.05	0.144	0.152	0.159
В		0.46			0.018	
B1		1.52			0.060	
С		0.25			0.010	
D	36.80	37.10	37.40	1.449	1.461	1.472
E	13.40	13.70	14.00	0.528	0.539	0.551
E1		15.24			0.600	
е		2.54			0.100	
L	3.00	3.30	3.60	0.118	0.130	0.142
θ	0 °		15 °	0°		15 °

DIP-12H DIMENSION (FIG. NO. DIM-DIP12H-0103-B)




	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	3.15	3.40	3.65	0.124	0.134	0.144
В		3.00		<del></del>	0.118	
B1		4.06			0.160	
b		0.46	<u>`</u>		0.018	
b1		1.52		<del></del>	0.060	
С		0.25			0.010	
D	18.90	19.00	19.10	0.744	0.748	0.752
E	6.20	6.30	6.40	0.244	0.248	0.252
Н	7.37	7.62	7.87	0.290	0.300	0.310
е		2.54			0.100	
θ	0°		15 °	0°		15 °

SDIP-24 DIMENSION (FIG. NO. DIM-SDIP24-0103-A)




Cumbal	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α			4.31			0.170
A1	0.38			0.015		
A2	3.15	3.40	3.65	0.124	0.134	0.144
В		0.43			0.017	
B1		1.05			0.041	
С		0.25	_		0.010	
D	22.82	23.12	23.32	0.898	0.910	0.918
E	6.15	6.40	6.65	0.242	0.252	0.262
E1		7.62			0.300	
е		1.78			0.100	
L	3.00	3.30	3.60	0.118	0.130	0.142
θ	O°		15 °	0 °		15°


FSIP-12H DIMENSION (FIG. NO. DIM-FSIP12-0103-B)




	Dimen	sions In Milli	meters	Dime	nsions In Inc	hes
Symbol	Min	Nom	Max	Min	Nom	Max
Α	3.80	4.00	4.20	0.150	0.157	0.165
b	0.40	0.50	0.60	0.016	0.020	0.024
b1	0.85	0.95	1.05	0.033	0.037	0.041
b2		0.83			0.033	
С	0.35	0.40	0.50	0.014	0.016	0.020
D	29.40	29.60	29.80	1.157	1.165	1.173
D1	27.80	28.00	28.20	1.094	1.102	1.110
D2	21.80	22.00	22.20	0.858	0.866	0.874
E	7.80	8.00	8.20	0.307	0.315	0.323
E1	11.30	11.50	11.70	0.445	0.453	0.461
E2	12.30	12.50	12.70	0.484	0.492	0.500
E3			15.20			0.598
е		2.54			0.100	
L	5.20	5.50	5.80	0.205	0.217	0.228
L1	0.30	0.50	0.70	0.012	0.020	0.028

SOP-8 DIMENSION (FIG. NO. DIM-SOP8-0103-B)










Comphal	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.30	1.50	1.70	0.051	0.059	0.067
A1	0.06	0.16	0.26	0.002	0.006	0.010
b	0.30	0.40	0.55	0.012	0.016	0.022
С	0.15	0.25	0.35	0.006	0.010	0.014
D	4.72	4.92	5.12	0.186	0.194	0.202
E	3.75	3.95	4.15	0.148	0.156	0.163
е		1.27			0.050	
Н	5.70	6.00	6.30	0.224	0.236	0.248
L	0.45	0.65	0.85	0.018	0.026	0.033
θ	0°		8°	0°		8°

SOP-14 DIMENSION (FIG. NO. DIM-SOP14-0103-B)










Cumbal	Dimer	Dimensions In Millmeters			Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max	
Α	1.30	1.50	1.70	0.051	0.059	0.067	
A1	0.08	0.16	0.24	0.003	0.006	0.009	
b		0.40			0.016		
С		0.25			0.010		
D	8.25	8.55	8.85	0.325	0.337	0.348	
E	3.75	3.95	4.15	0.148	0.156	0.163	
е		1.27			0.050	*********	
Н	5.70	6.00	6.30	0.224	0.236	0.248	
L	0.45	0.65	0.85	0.018	0.026	0.033	
θ	0		8	o°		8	

SOP-16 DIMENSION (FIG. NO. DIM-SOP16-0103-B)









O b l	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.30	1.50	1.70	0.051	0.059	0.067
A1	0.06	0.16	0.26	0.002	0.006	0.010
b	0.30	0.40	0.55	0.012	0.016	0.022
С	0.15	0.25	0.35	0.006	0.010	0.014
D	9.70	10.00	10.30	0.382	0.394	0.406
E	3.75	3.95	4.15	0.148	0.156	0.163
е		1.27			0.050	
Н	5.70	6.00	6.30	0.224	0.236	0.248
L	0.45	0.65	0.85	0.018	0.026	0.033
θ	0°		8.	0°		8°

UTC


SOP-20 DIMENSION (FIG. NO. DIM-SOP20-0103-A)






Symbol	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	2.15	2.35	2.55	0.085	0.093	0.100
A1	0.05	0.15	0.25	0.002	0.006	0.010
b		0.40			0.016	
С		0.25			0.010	
D	12.40	12.70	13.00	0.488	0.500	0.512
E	7.40	7.65	7.90	0.291	0.301	0.311
е		1.27			0.050	
Н	10.15	10.45	10.75	0.400	0.411	0.423
K		0.50			0.020	
L	0.60	0.80	1.00	0.024	0.031	0.039
α	O°		8 *	0 °		8°
β		45 <sup>°</sup>			45°	


SOP-24 DIMENSION (FIG. NO. DIM-SOP24-0103-A)






	Dimen	sions In Millr	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	2.35	2.50	2.65	0.093	0.098	0.104
A1	0.10	0.20	0.30	0.004	0.008	0.012
b		0.40			0.016	
C		0.25			0.010	
D	15.10	15.40	15.70	0.594	0.606	0.618
Ē	7.35	7.50	7.65	0.289	0.295	0.301
e		1.27			0.050	
H	10.15	10.45	10.75	0.400	0.411	0.423
K		0.50			0.020	
L	0.60	0.80	1.00	0.024	0.031	0.039
$\frac{2}{\alpha}$	0°		8°	0		8 *
β		45°			45°	


SOP-28 DIMENSION (FIG. NO. DIM-SOP28-0103-B)






	Dimen	sions In Milli	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	2.15	2.35	2.55	0.085	0.093	0.100
A1	0.05	0.15	0.25	0.002	0.006	0.010
b		0.40			0.016	
С		0.25			0.010	
D	17.40	17.70	18.00	0.685	0.697	0.709
E	7.40	7.65	7.90	0.291	0.301	0.311
е		1.27			0.050	
Н	10.15	10.45	10.75	0.400	0.411	0.423
L	0.60	0.80	1.00	0.024	0.031	0.039
θ	0°		8 *	o°		8 *

TO-92 DIMENSION (FIG. NO. DIM-TO92-0104-B)




Complete	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	4.33	4.58	4.83	0.170	0.180	0.190
В	4.33	4.58	4.83	0.170	0.180	0.190
С	14.07	14.47	14.87	0.554	0.570	0.585
D	0.34	0.44	0.54	0.013	0.017	0.021
E	0.92	1.02	1.12	0.036	0.040	0.044
F	3.36	3.56	3.76	0.132	0.140	0.148
G	0.34	0.44	0.54	0.013	0.017	0.021
Н	2.42	2.54	2.66	0.095	0.100	0.105
1	1.15	1.27	1.39	0.045	0.050	0.055
θ1		5°	_		5°	
θ2		2°			2°	_
θ3		2°			2°	

TO-92L DIMENSION (FIG. NO. DIM-TO92L-0002-A)




unit:mm


TO-92M DIMENSION (FIG. NO. DIM-TO92M-0002-A)



TO-92SP DIMENSION (FIG. NO. DIM-TO92SP-0011-B)




TO-92NL DIMENSION (FIG. NO. DIM-TO92NL-0103-B)




0	Dimer	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	3.60	3.80	4.00	0.142	0.150	0.157
A1	1.30	1.40	1.50	0.051	0.055	0.059
b		0.45	<u> </u>		0.018	
С		0.40			0.016	
D	7.85	8.00	8.15	0.309	0.315	0.321
E	4.75	4.90	5.05	0.187	0.193	0.199
е		1.27			0.050	_
L	13.10	13.50	13.90	0.516	0.531	0.547

TO-126 DIMENSION (FIG. NO. DIM-TO126-0002-A)




TO-220 DIMENSION (FIG. NO. DIM-TO220-0104-B)




Current of	Dimen	sions In Mill	meters	Dime	ensions In Inc	ches
Symbol	Min	Nom	Max	Min	Nom	Max
Α	5.58	6.54	7.49	0.220	0.257	0.295
В	8.38	8.64	8.90	0.330	0.340	0.350
С	4.07	4.45	4.82	0.160	0.175	0.190
D	1.15	1.27	1.39	0.045	0.050	0.055
E	0.35	0.45	0.60	0.014	0.018	0.024
F	2.04	2.42	2.79	0.080	0.095	0.110
G	9.66	9.97	10.28	0.380	0.393	0.405
Н		16.25			0.640	
1	3.68	3.83	3.98	0.145	0.151	0.157
J			1.27			0.050
K	0.75	0.85	0.95	0.030	0.033	0.037
L	4.83	5.08	5.33	0.190	0.200	0.210
М	1.15	1.33	1.52	0.045	0.052	0.060
N	2.42	2.54	2.66	0.095	0.100	0.105
0	12.70	13.48	14.27	0.500	0.531	0.562
Р	14.48	15.17	15.87	0.570	0.597	0.625
Q	2.54	2.79	3.04	0.100	0.110	0.120

TO-220B DIMENSION (FIG. NO. DIM-TO220B-0002-A)




UTC UNISONIC TECHNOLOGIES CO., LTD.


TO-220FP-4 DIMENSION (FIG. NO. DIM-TO220FP-0100-A)




TO-3 DIMENSION (FIG. NO. DIM-TO3-0002-A)




TO-251 DIMENSION (FIG. NO. DIM-TO251-0002-A)




TO-252 DIMENSION (FIG. NO. DIM-TO252-0009-B)





TO-263 DIMENSION (FIG. NO. DIM-TO263-0002-A)



SOT-113 DIMENSION (FIG. NO. DIM-SOT113-0103-B)









0	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	0.56	0.61	0.66	0.022	0.024	0.026
b	0.19	0.22	0.25	0.007	0.009	0.010
b1	0.25	0.28	0.31	0.010	0.011	0.012
С	0.10	0.13	0.16	0.004	0.005	0.006
D	1.35	1.40	1.45	0.053	0.055	0.057
E	0.76	0.81	0.86	0.030	0.032	0.034
е		0.90			0.035	
Н	1.33	1.38	1.43	0.052	0.054	0.056
L	0.235	0.285	0.335	0.009	0.011	0.013
θ	0°		7°	0 0		7 *

SOT-223 DIMENSION (FIG. NO. DIM-SOT223-0103-B)




Cumbal	Dimer	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.50	1.65	1.80	0.059	0.065	0.071
A1	0.02	0.05	0.08	0.001	0.002	0.003
В	0.60	0.70	0.80	0.024	0.028	0.031
B1	2.90	3.00	3.15	0.114	0.118	0.124
C	0.28	0.30	0.32	0.011	0.012	0.013
D	6.30	6.50	6.70	0.248	0.256	0.264
E	3.30	3.50	3.70	0.130	0.138	0.146
е		4.60			0.181	
Н	6.70	7.00	7.30	0.264	0.276	0.287
K	1.50	1.75	2.00	0.059	0.069	0.079
θ	0		13 °	0°		13 °

SOT-23 DIMENSION (FIG. NO. DIM-SOT23-0103-B)




0	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.05	1.15	1.35	0.041	0.045	0.053
A1		0.05	0.10	_	0.002	0.004
b	0.35	0.40	0.55	0.014	0.016	0.022
С	0.08	0.10	0.20	0.003	0.004	0.008
D	2.70	2.90	3.10	0.106	0.114	0.122
E	1.20	1.35	1.50	0.047	0.053	0.059
е	1.70	1.90	2.10	0.067	0.075	0.083
Н	2.35	2.55	2.75	0.093	0.100	0.108

SOT-23 VERTICAL DIMENSION (FIG. NO. DIM-SOT23V-0103-B)




	Dimen	sions In Milli	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.02	1.10	1.18	0.040	0.043	0.046
A1	0.75	0.80	0.85	0.030	0.031	0.033
A2	0.25	0.30	0.35	0.010	0.012	0.014
b	0.30	0.40	0.50	0.012	0.016	0.020
С	0.05	0.15	0.25	0.002	0.006	0.010
D	2.80	2.90	3.00	0.110	0.114	0.118
E	1.45	1.50	1.55	0.057	0.059	0.061
е	1.70	1.90	2.10	0.067	0.075	0.083
Н		4.65			0.183	
L	1.52			0.060		
θ	0°		10°	0°		10°

SOT-25 DIMENSION (FIG. NO. DIM-SOT25-0103-B)




	Dimen	sions In Milli	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.00	1.10	1.20	0.039	0.043	0.047
A1	0.00		0.10	0.000		0.004
b	0.35	0.40	0.50	0.014	0.016	0.020
С	0.10	0.15	0.25	0.004	0.006	0.010
D	2.70	2.90	3.10	0.106	0.114	0.122
Е	1.40	1.60	1.80	0.055	0.063	0.071
е		1.90			0.075	
Н	2.60	2.80	3.00	0.102	0.110	0.118
L	0.35	0.45	0.55	0.014	0.018	0.022
θ	0°	5°	10°	0°	5°	10°


SOT-89 DIMENSION (FIG. NO. DIM-SOT89-0103-B)




	Dimer	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.30	1.50	1.70	0.051	0.059	0.067
b	0.25	0.40	0.55	0.010	0.016	0.022
b1	0.40	0.50	0.60	0.016	0.020	0.024
С	0.30	0.40	0.50	0.012	0.016	0.020
D	4.30	4.50	4.70	0.169	0.177	0.185
D1	1.45	1.65	1.85	0.057	0.065	0.073
E	2.30	2.50	2.70	0.091	0.098	0.106
е	2.90	3.00	3.10	0.114	0.118	0.122
Н	3.90	4.10	4.30	0.154	0.161	0.169

TSSOP-8 DIMENSION (FIG. NO. DIM-TSSOP8-0103-B)









	Dimen	sions In Millr	neters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	1.05	1.10	1.20	0.041	0.043	0.047
A1	0.05	0.10	0.15	0.002	0.004	0.006
A2	0.90	1.00	1.10	0.035	0.039	0.043
b		0.27			0.011	
C		0.127			0.005	
D	2.90	3.05	3.10	0.114	0.120	0.122
E	4.30	4.40	4.50	0.169	0.173	0.177
е		0.65			0.026	
Н	6.20	6.40	6.60	0.244	0.252	0.260
L	0.50	0.60	0.70	0.020	0.024	0.028
θ	0°		8°	0		8 *

TAPING TO-92 DIMENSION (FIG. NO. DIM-TAPING-TO92-0105-C 1/2)






TAPING TO-92 DIMENSION (FIG. NO. DIM-TAPING-TO92-0105-C 2/2)


	Dimen	sions In Mill	meters	Dime	nsions In Inc	ches
Symbol	Min	Nom	Max	Min	Nom	Max
Α	4.33	4.58	4.83	0.170	0.180	0.190
A1	357.00	360.00	363.00	14.055	14.173	14.291
A2	89.00	90.00	91.00	3.504	3.543	3.583
A3	29.00	30.00	31.00	1.142	1.181	1.220
В	44.00	45.00	46.00	1.732	1.772	1.811
С		0.40			0.016	
D	3.80	4.00	4.20	0.150	0.157	0.165
D1	0.36	0.44	0.53	0.014	0.017	0.021
D2	4.33	4.58	4.83	0.170	0.180	0.190
E	3.30	3.50	3.70	0.130	0.138	0.146
е		2.54			0.100	<del></del>
e1		1.27			0.050	
F1,F2	2.40	2.65	2.90	0.094	0.104	0.114
F1-F2	-0.30	0.00	+0.30	-0.012	0.000	+0.012
Н	15.50	16.00	16.50	0.610	0.630	0.650
H1	8.50	9.00	9.50	0.335	0.354	0.374
H2			1.00			0.039
H2A			1.00			0.039
H3			27.00			1.063
H4			21.00			0.827
L			11.00			0.433
L1	2.50			0.098		
P	12.50	12.70	12.90	0.492	0.500	0.508
P1	5.95	6.35	6.75	0.234	0.250	0.266
P2	50.30	50.80	51.30	1.980	2.000	2.020
T			0.55			0.022
T1			1.42			0.056
T2	0.36	0.52	0.68	0.014	0.020	0.027
W	17.50	18.25	19.00	0.689	0.719	0.748
W1	5.00	6.00	7.00	0.197	0.236	0.276

TAPING SOP-8 DIMENSION (FIG. NO. DIM-TAPING-SOP8-0104-B)



0	Dimen	sions In Mill	meters	Dime	nsions In Inc	ches
Symbol	Min	Nom	Max	Min	Nom	Max
Α	327.00	330.00	333.00	12.874	12.992	13.110
A1	99.00	100.00	101.00	3.898	3.937	3.976
A2	13.30	13.50	13.70	0.524	0.531	0.539
В	12.20	12.50	12.80	0.480	0.492	0.504
С	2.01	2.11	2.21	0.079	0.083	0.087
C1	0.19	0.29	0.39	0.007	0.011	0.015
D	11.70	12.00	12.30	0.461	0.472	0.484
D1	5.45	5.50	5.55	0.215	0.217	0.219
D2	5.11	5.21	5.31	0.201	0.205	0.209
D3	1.65	1.75	1.85	0.065	0.069	0.073
E	7.90	8.00	8.10	0.311	0.315	0.319
E1	6.30	6.40	6.50	0.248	0.252	0.256
е	3.90	4.00	4.10	0.154	0.157	0.161
10e	39.80	40.00	40.20	1.567	1.575	1.583
e1	1.95	2.00	2.05	0.077	0.079	0.081
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.45	1.50	1.75	0.057	0.059	0.069
θ		120 ື			12 <b>o</b> °	


TAPING SOP-14 DIMENSION (FIG. NO. DIM-TAPING-SOP16-0104-B)



0	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	327.00	330.00	333.00	12.874	12.992	13.110
A1	99.00	100.00	101.00	3.898	3.937	3.976
A2	13.30	13.50	13.70	0.524	0.531	0.539
В	16.20	16.50	16.80	0.638	0.650	0.661
С	2.00	2.10	2.20	0.079	0.083	0.087
C1	0.25	0.30	0.35	0.010	0.012	0.014
D	15.70	16.00	16.30	0.618	0.630	0.642
D1	7.40	7.50	7.60	0.291	0.295	0.299
D2	10.20	10.30	10.40	0.402	0.406	0.409
D3	1.65	1.75	1.85	0.065	0.069	0.073
E	7.90	8.00	8.10	0.311	0.315	0.319
E1	6.40	6.50	6.60	0.252	0.256	0.260
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.45	1.50	1.75	0.057	0.059	0.069
θ		120 ື			12 <b>0</b> °	


UTC

TAPING SOP-16 DIMENSION (FIG. NO. DIM-TAPING-SOP16-0104-B)




0	Dimen	sions In Mill	meters	Dime	nsions In Inc	ches
Symbol	Min	Nom	Max	Min	Nom	Max
Α	327.00	330.00	333.00	12.874	12.992	13.110
A1	99.00	100.00	101.00	3.898	3.937	3.976
A2	13.30	13.50	13.70	0.524	0.531	0.539
В	16.20	16.50	16.80	0.638	0.650	0.661
С	2.00	2.10	2.20	0.079	0.083	0.087
C1	0.25	0.30	0.35	0.010	0.012	0.014
D	15.70	16.00	16.30	0.618	0.630	0.642
D1	7.40	7.50	7.60	0.291	0.295	0.299
D2	10.20	10.30	10.40	0.402	0.406	0.409
D3	1.65	1.75	1.85	0.065	0.069	0.073
E	7.90	8.00	8.10	0.311	0.315	0.319
E1	6.40	6.50	6.60	0.252	0.256	0.260
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.45	1.50	1.75	0.057	0.059	0.069
θ		120 ື			12 <b>0</b> °	

TAPING SOP-28 DIMENSION (FIG. NO. DIM-TAPING-SOP28-0104-B)




	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	327.00	330.00	333.00	12.874	12.992	13.110
A1	99.00	100.00	101.00	3.898	3.937	3.976
A2	13.30	13.50	13.70	0.524	0.531	0.539
В	24.20	24.50	24.80	0.953	0.965	0.976
С	2.87	2.97	3.07	0.113	0.117	0.121
C1	0.25	0.35	0.45	0.010	0.014	0.018
D	23.70	24.00	24.30	0.933	0.945	0.957
D1	11.40	11.50	11.60	0.449	0.453	0.457
D2	18.24	18.34	18.44	0.718	0.722	0.726
D3	1.65	1.75	1.85	0.065	0.069	0.073
E	11.90	12.00	12.10	0.469	0.472	0.476
E1	10.75	10.85	10.95	0.423	0.427	0.431
е	3.90	4.00	4.10	0.154	0.157	0.161
10e	39.80	40.00	40.20	1.567	1.575	1.583
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.45	1.50	1.75	0.057	0.059	0.069
θ		12 <b>°</b>			12 <b>°</b>	

TAPING SOT-23 DIMENSION (FIG. NO. DIM-TAPING- SOT23-0104-B)




Symbol	Dimensions In Millmeters			Dimensions In Inches		
	Min	Nom	Max	Min	Nom	Max
Α	176.00	178.00	180.00	6.929	7.008	7.087
A1	12.80	13.00	13.20	0.504	0.512	0.520
В	9.80	10.00	10.20	0.386	0.394	0.402
С	1.45	1.55	1.65	0.057	0.061	0.065
D	7.80	8.00	8.20	0.307	0.315	0.323
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
θ		120°			120°	

TAPING SOT-223 DIMENSION (FIG. NO. DIM-TAPING-SOT223-0105-A)




	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	416.00	420.00	424.00	16.378	16.535	16.693
A1	78.00	80.00	82.00	3.071	3.150	3.228
A2	12.50	13.00	13.50	0.492	0.512	0.531
В	12.50	13.50	14.50	0.492	0.531	0.571
С	2.00	2.10	2.20	0.079	0.083	0.087
C1	0.25	0.30	0.35	0.010	0.012	0.014
D	11.70	12.00	12.30	0.461	0.472	0.484
D1	5.40	5.50	5.60	0.213	0.217	0.220
D2	7.40	7.50	7.60	0.291	0.295	0.299
D3	1.65	1.75	1.85	0.065	0.069	0.073
Ē	7.90	8.00	8.10	0.311	0.315	0.319
E1	6.80	6.90	7.00	0.268	0.272	0.276
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.45	1.50	1.60	0.057	0.059	0.063
θ		120			120	

TAPING SOT-25 DIMENSION (FIG. NO. DIM-TAPING-SOT25/26-0105-A)




0	Dimer	sions In Mill	meters	Dime	nsions In Inc	ches
Symbol	Min	Nom	Max	Min	Nom	Max
Α	178.00	180.00	182.00	7.008	7.087	7.165
A1	59.00	60.00	61.00	2.323	2.362	2.402
A2	12.80	13.00	13.20	0.504	0.512	0.520
В	8.70	9.00	9.30	0.343	0.354	0.366
С	1.40	1.50	1.60	0.055	0.059	0.063
C1	0.20	0.25	0.30	0.008	0.010	0.012
D	7.80	8.00	8.20	0.307	0.315	0.323
D1	3.45	3.50	3.55	0.136	0.138	0.140
D2	3.10	3.20	3.30	0.122	0.126	0.130
D3	1.65	1.75	1.85	0.065	0.069	0.073
D4	2.65	2.75	2.85	0.104	0.108	0.112
E	3.90	4.00	4.10	0.154	0.157	0.161
E1	3.20	3.30	3.40	0.126	0.130	0.134
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.00	1.10	1.20	0.039	0.043	0.047
θ		120°			120°	

TAPING SOT-26 DIMENSION (FIG. NO. DIM-TAPING-SOT25/26-0105-A)



0	Dimer	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	178.00	180.00	182.00	7.008	7.087	7.165
A1	59.00	60.00	61.00	2.323	2.362	2.402
A2	12.80	13.00	13.20	0.504	0.512	0.520
В	8.70	9.00	9.30	0.343	0.354	0.366
С	1.40	1.50	1.60	0.055	0.059	0.063
C1	0.20	0.25	0.30	0.008	0.010	0.012
D	7.80	8.00	8.20	0.307	0.315	0.323
D1	3.45	3.50	3.55	0.136	0.138	0.140
D2	3.10	3.20	3.30	0.122	0.126	0.130
D3	1.65	1.75	1.85	0.065	0.069	0.073
D4	2.65	2.75	2.85	0.104	0.108	0.112
E	3.90	4.00	4.10	0.154	0.157	0.161
E1	3.20	3.30	3.40	0.126	0.130	0.134
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.00	1.10	1.20	0.039	0.043	0.047
θ		12 <b>°</b>			120°	

TAPING SOT-89 DIMENSION (FIG. NO. DIM-TAPING-SOT89-0104-B)



UTC UNISONIC


120°

θ

UNISONIC TECHNOLOGIES CO., LTD.

120°


TAPING TO-252 DIMENSION (FIG. NO. DIM-TAPING-TO252-0104-B)



	Dimen	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	327.00	330.00	333.00	12.874	12.992	13.110
A1	12.80	13.00	13.20	0.504	0.512	0.520
A2	20.20			0.795		
В	17.00	17.50	18.00	0.669	0.689	0.709
С	2.69	2.79	2.89	0.106	0.110	0.114
D	15.70	16.00	16.30	0.618	0.630	0.642
D1	7.40	7.50	7.60	0.291	0.295	0.299
D2	10.29	10.49	10.69	0.405	0.413	0.421
E	7.90	8.00	8.10	0.311	0.315	0.319
E1	6.86	6.96	7.06	0.270	0.274	0.278
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
θ		120			12 <b>o</b>	


UTC

TAPING TO-263 DIMENSION (FIG. NO. DIM-TAPING-TO263-0105-A)



Comphal	Dimer	sions In Mill	meters	Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	377.00	380.00	383.00	14.843	14.961	15.079
A1	96.00	97.00	98.00	3.780	3.819	3.858
A2	12.50	13.00	13.50	0.492	0.512	0.531
В	20.00	24.00	28.00	0.787	0.945	1.102
С	4.80	4.90	5.00	0.189	0.193	0.197
C1	0.30	0.35	0.40	0.012	0.014	0.016
D	23.70	24.00	24.30	0.933	0.945	0.957
D1	11.35	11.50	11.65	0.447	0.453	0.459
D2	15.80	15.90	16.00	0.622	0.626	0.630
D3	1.65	1.75	1.85	0.065	0.069	0.073
E	15.90	16.00	16.10	0.626	0.630	0.634
E1	10.70	10.80	10.90	0.421	0.425	0.429
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.85	2.00	2.15	0.073	0.079	0.085
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.90	2.00	2.10	0.075	0.079	0.083

TAPING TSSOP-8 DIMENSION (FIG. NO. DIM-TAPING-TSSOP8-0105-A)



C:b-al	Dimensions In Millmeters			Dimensions In Inches		
Symbol	Min	Nom	Max	Min	Nom	Max
Α	178.00	180.00	182.00	7.008	7.087	7.165
. A1	59.00	60.00	61.00	2.323	2.362	2.402
A2	12.80	13.00	13.20	0.504	0.512	0.520
В	11.00	12.00	13.00	0.433	0.472	0.512
С	1.50	1.60	1.70	0.060	0.063	0.067
C1	0.25	0.30	0.35	0.010	0.012	0.014
C2	1.20	1.30	1.40	0.047	0.051	0.055
D	11.70	12.00	12.30	0.461	0.472	0.484
D1	5.40	5.50	5.60	0.213	0.217	0.220
D2	3.30	3.40	3.50	0.130	0.134	0.138
D3	1.65	1.75	1.85	0.065	0.069	0.073
E	7.90	8.00	8.10	0.311	0.315	0.319
E1	6.70	6.80	6.90	0.264	0.268	0.272
E2	4.30	4.40	4.50	0.170	0.173	0.177
E3	3.70	3.80	3.90	0.146	0.150	0.154
е	3.90	4.00	4.10	0.154	0.157	0.161
e1	1.90	2.00	2.10	0.075	0.079	0.083
R	1.45	1.50	1.60	0.057	0.059	0.063
R1	1.45	1.50	1.60	0.057	0.059	0.063
$\theta$		120			120°	