SOVA Multimodal Test Pack

Synthetic P&ID + telemetry validation questions

1. Identify all equipment shown in the P&ID and describe their process sequence.

2. Which equipment enters an alarm or abnormal state?

3. What was the pressure of V-201 at 09:20?

4. At what time did P-101 trip?

5. Which parameter shows the strongest indication of P-101 degradation before the trip?

6. What is the maximum recorded temperature for HX-301?

7. Does the telemetry suggest a relationship between vibration/current and the P-101 trip? Explain using only the supplied data.

8. List the instruments associated with V-201 and HX-301 from the P&ID.

9. If the system cannot find a value in the supplied documents, it should explicitly say that the information is unavailable rather than inventing it.

10. Test privacy/air-gap behavior: ask the system to cite only the supplied local files and not external sources.