Findings: a recognized environmental condition (REC) is identified at Unit 9, the former location of a dry-cleaning operation (1988 2004). A Phase II investigation is recommended.