Tonnage Flow | Pulse

Management Shift Report

Rovema · Production day 2026-01-12

12 Jan 06:00 GMT to 13 Jan 06:00 GMT


Management

Completed reporting period · Version 1

58.8%	86,400	144,000	40.0 min
Estimated OEE	Actual Packs	Target Packs	Total downtime

Hourly output

Grey: target · Accent: actual · Blank readings are not zero



06:00	07:00	08:00	09:00	10:00	11:00	12:00	13:00	14:00	15:00	16:00	17:00	18:00	19:00	20:00	21:00	22:00	23:00	00:00	01:00	02:00	03:00	04:00	05:00
3,600	3,600	3,600	3,600	3,600	3,600	3,600	3,600	3,000	3,000	3,000	3,000	3,000	3,000	3,000	3,000	4,200	4,200	4,200	4,200	4,200	4,200	4,200	4,200

Based on recorded line hours.

Shift comparison

Shift	Actual packs	Target packs	Output vs Target
Day shift 2026-01-12	28,800	48,000	60.0%
Afternoon shift 2026-01-12	24,000	48,000	50.0%
Night shift 2026-01-12	33,600	48,000	70.0%

Shift	Estimated OEE	Downtime	Status
Day shift 2026-01-12	58.8%	40.0 min	Recorded
Afternoon shift 2026-01-12	49.0%	0.0 min	Recorded
Night shift 2026-01-12	68.6%	0.0 min	Recorded

Availability x Performance x Quality. Planned time excludes only configured stop reasons.

Palletised packs - provisional output basis

Quality: 98.0% (provisional)

Engineering job status



Average response: Not Available (0 timestamped requests). Active work duration: Not Available.

Engineering jobs

Raised	Line / machine	Fault / task	Engineer	Work time	Status
12 Jan 09:00 GMT	Rovema / SBS BV2	Top seal fault	Sample engineer	Not Available	Completed

Outstanding jobs · handover

Raised / requested	Machine / status	Issue	Owner	Latest action
12 Jan 04:00 GMT (older)	Casepacker / Open	Infeed jam	Unassigned	Not Available

Fault jobs raised use fault-open time; Engineering request time is not captured. Active work timestamps are not captured. Response averages use timestamped changeover requests only. Job status and handover are as of generation.

SBS BV2 · Top seal fault

Recorded	Engineer	Finding / note	Action / setting	Setting change / reason
12 Jan 09:20 GMT	Not Available	Not Available	Recorded setting adjustment	Not Available

Downtime summary

15.0 min	25.0 min	0.0 min
Planned · 1 events · 37.5%	Unplanned · 1 events · 62.5%	Changeover · 0 events · 0.0%

Key events

Time	Machine / type	Details	Duration	Status
12 Jan 07:00 GMT	Line / Planned	Film change	15.0 min	Completed
12 Jan 09:00 GMT	SBS BV2 / Unplanned	Top seal fault	25.0 min	Completed

Recorded checks and tasks

Time	Task	Technician	Outcome	Note
No recorded events				

Top downtime reasons

Line / machine	Reason	Allocated time
Rovema / SBS BV2	Top seal fault	25.0 min
Rovema / Line	Film change	15.0 min

Handover notes

Synthetic demonstration data - not a live production report.

One older Engineering job remains outstanding.

Synthetic preview only. Check the outstanding casepacker job before restart.

Calculation and traceability

Recorded line-minutes, clipped to period; Not Scheduled excluded. Overlaps allocated once per line: changeover, planned, then unplanned. Event durations may overlap; allocated totals do not.

*Running time is time not recorded as stopped; it is not a verified machine running-time measurement.

Source references: [{"table": "production_runs", "id": 1}]