



MS-3108-F-28-20-P MS-3108-F-28-20-P

Label : "PDTR" (Black on Yellow) Heat Shrink Boot : Both Side

Heat Shrink Tube : Full Cable (Rubber)

*Max Temp: 100'C








Label : "PDNL" (Black on Yellow) Heat Shrink Boot : Both Side

Heat Shrink Tube : Full Cable (Rubber)


*Max Temp: 100'C








15 cm



Label : "COCK" (Black on Yellow) MS-3108-F-24-7-P Heat Shrink Boot : Both Side Heat Shrink Tube : Full Cable (Rubber) *Max Temp : 100'C



Cable #8th

