



MS-3108-F-28-20-P MS-3108-F-28-20-P

Label : "PDTR" (Black on Yellow) Heat Shrink Boot : Both Side

Heat Shrink Tube : Full Cable (Rubber)

*Max Temp: 100'C








Label : "PDNL" (Black on Yellow) Heat Shrink Boot : Both Side


Heat Shrink Tube : Full Cable (Rubber)


*Max Temp: 100'C













Cable #8th





MS-3106-F-14S-6-P