

Custom Service Leasing Pty Ltd

GREY

Phone: (02) 98083133 15 - 17 Rhodes st West Ryde ABN: 60 002 836 633 Fax: (02) 98076866 info@centraldistrictssmash.com License: 22572

Estimate No: 60797

Insurance:

Owner: SONY AUSTRALIA (30) Colour:

Address : CRN BERRY & WALKER STREET Odometer :

NORTH SYDNEY

 Phone :
 0418158027 (H); +61418158027 (M)
 Claim # : 618862/1

 Vehicle :
 2014 Toyota RAV4 Wagon
 Estimator : Brian Muller

 Reg No :
 CA68CY
 SCHED. IN: 19/06/2015 SCHED. OUT:

VIN: JTMZDREV10D038110

Original Estimate

R&R (Rate: \$29)	Hrs	Amount
REAR BAR D/A	2.00	\$58.00
REAR BAR REINFORCEMENT	0.40	\$11.60
REAR BAR SENSORS & WIRING INCLUDE DRILL & BOX	2.00	\$58.00
L/H REAR MUD FLAP	0.30	\$8.70
R/H REAR MUD FLAP	0.30	\$8.70
L/H TAILIGHT	0.30	\$8.70
R/H TAILIGHT	0.30	\$8.70
R/H REAR 1/4 PANEL FLARE	0.80	\$23.20
L/H REAR 1/4 PANEL FLARE	0.80	\$23.20
TAPE L/H REAR 1/4 GLASS	0.50	\$14.50
L/H TURRET MOULD	0.80	\$23.20
TAPE R/H REAR 1/4 GLASS	0.50	\$14.50
R/H TURRET MOULD	0.80	\$23.20
TAPE FRONT SCREEN FULL	1.00	\$29.00
INNER CABIN TRIMS & FITTINGS TO SUIT REPAIRS	4.00	\$116.00
TAILGATE AND D/A	5.00	\$145.00
TAILGATE WIRING & TUBING THROUGH PILLAR	0.80	\$23.20
REAR EXHAUST & HEAT SHIELD	1.50	\$43.50
BEAVER PANEL	8.50	\$246.50
BEAVER PANEL INNER	6.00	\$174.00
L/H REAR LOWER TAILAMP PANEL	4.00	\$116.00
R/H REAR LOWER TAILAMP PANEL	4.00	\$116.00
FRONT BAR D/A	2.60	\$75.40
L/H FRONT BAR FLARE	0.80	\$23.20
R/H FRONT BAR FLARE	0.80	\$23.20
BONNET LOCK SUPPORT	0.30	\$8.70
AIR CON CORE	0.50	\$14.50
CAROLINER	3.00	\$87.00
	Sub Total	\$1,525.40
Repair (Rate: \$29)		
L/H REAR 1/4 PANEL	4.00	\$116.00
L/H REAR CHASSIS RAIL INCLUDE END PLATE	8.00	\$232.00
R/H REAR 1/4 PANEL	4.00	\$116.00
R/H REAR CHASSIS RAIL INCLUDE END PLATE	8.00	\$232.00
BOOT FLOOR PANEL	8.00	\$232.00
	Sub Total	\$928.00

Paint (Rate: \$57)					
MIX & MATCH			0.56		\$31.92
REAR BAR COVER			3.50		\$199.50
REAR BAR SENSORS			1.00		\$57.00
BEAVER PANEL OUTER			2.20		\$125.40
TAILAMP PANELS INCLUDE BLEND APPETURE			1.50		\$85.50
L/H REAR QUARTER PANEL			3.10		\$176.70
L/H CANT PANEL			2.00		\$114.00
R/H REAR QUARTER PANEL			3.10		\$176.70
R/H CANT PANEL			2.00		\$114.00
INNER CABIN REPAIRS INCLUDE MASK TIME			3.00		\$171.00
UNDER BODY REPAIRS			1.00		\$57.00
TAILGATE OUT AND IN			4.70		\$267.90
SILL CLAMP DAMAGE			2.00		\$114.00
			Sub T	otal	\$1,690.62
Sublet					
R/R TAILGATE GLASS (Billed through repairer)					\$100.00
RESET ON BOARD SYSTEMS (R.On) (Billed through	repairer)				\$0.00
DECOMMISSION & RECOMMISSION AIR (Billed thro	ough repairer)				\$170.00
TOWING (Billed through repairer)					\$276.10
			Sub T	otal	\$546.10
Other					
BOOTH ALLOWANCE					\$80.00
SPRAY & BRUSH ON SEALER BEAVER OUTER					\$40.00
SPRAY & BRUSH ON SEALER BEAVER INNER					\$40.00
ENVIRONMENTAL LEVY					\$6.00
CAVITY WAX REPAIRS					\$35.00
			Sub	Total	\$201.00
New Parts list	Part No.	Qty	Unit price		
REAR BAR COVER	5215942200	1	\$419.80		\$419.80
L/H REAR BAR SLIDE	5215642010	1	\$47.27		\$47.27
L/H REAR REAR BAR SLIDE	5256342030	1	\$48.66		\$48.66
R/H REAR BAR SLIDE	5215542030	1	\$47.27		\$47.27
R/H REAR REAR BAR SLIDE	5256242020	1	\$48.66		\$48.66
L/H REAR BAR LAMP	8149042040	1	\$75.20		\$75.20
R/H REAR BAR LAMP	8148042040	1	\$75.20		\$75.20
REAR BAR REINFORCEMENT	5235142020	1	\$241.08		\$241.08
REAR BAR SENSOR KIT	PZQ9833061G3	1	\$250.00		\$250.00
L/H LOWER BAR GARNISH	5872442010	1	\$81.12		\$81.12
R/H LOWER BAR GARNISH	5872342010	1	\$89.27		\$89.27
BEAVER PANEL OUTER	5830242020	1	\$368.04		\$368.04
BEAVER PANEL INNER	5830742021	1	\$523.55		\$523.55
L/H OUTER BEAVER VENT	6294012180	1	\$26.49		\$26.49
L/H INNER BEAVER VENT		1	\$0.00		\$0.00
R/H OUTER BEAVER VENT	6294012180	1	\$26.49		\$26.49
R/H INNER BEAVER VENT		1	\$0.00		\$0.00
L/H LOWER TAILAMP PANEL	6162242050	1	\$76.21		\$76.21
R/H LOWER TAILAMP PANEL	6162142050	1	\$76.21		\$76.21
TAILGATE	6700542450	1	\$1,277.85		\$1,277.85
TAILGATE SEAL	6788142060	1	\$300.19		\$300.19
TAILGATE BADGETOYOTA		4	# 45.00		
TAILGATE DADGETOTOTA	7544142070	1	\$45.03		\$45.03

7543142100

9097502071

1

\$45.03

\$44.71

\$45.03

\$44.71

TAILGATE BADGE RAV 4

TAILGATE EMBLEM

TAILGATE LOCK	6935028150	1	\$228.87	\$228.87
TAILGATE TRIM	6775042051CO	1	\$357.40	\$357.40
TAILGATE INNER HANDLE POCKET	7481113010CO	1	\$15.32	\$15.32
BEAVER PANEL TRIM	6471642030CO	1	\$131.21	\$131.21
L/H REAR 1/4 PANEL TRIM	6474042072CO	1	\$549.47	\$549.47
R/H REAR 1/4 PANEL TRIM	6473042092CO	1	\$549.47	\$549.47
BOOT FLOOR TRIM	5841042070CO	1	\$281.58	\$281.58
SPARE WHEEL FOAM	6477742050	1	\$177.05	\$177.05
SPARE WHEEL BOLT	5193133230	1	\$14.90	\$14.90
FORWARD BOOT FLOOR TRIM	5841542040C2	1	\$168.51	\$168.51
PLASTIC TRIM BEHIND REAR SEAT	5841042070CO	1	\$281.58	\$281.58
FRONT BAR LOWER COVER	5241142030	1	\$507.38	\$507.38
FRONT BAR ABSORBER	5261142080	1	\$61.06	\$61.06
BONNET LOCK SUPPORT	5208542040	1	\$56.56	\$56.56
AIR CONDENSOR	8846042110	1	\$589.68	\$589.68

Sub Total \$8,203.37

Total Labour \$4,345.02

Total Sublet \$546.10

Total Parts \$8,203.37

Original Estimate total excl. GST\$13,094.49

GST \$1,309.45

Original Estimate total incl. GST\$14,403.94