Α

Acetic Acid 5/a

Order No. 67 22 101

Application Range

	•		
Standard Measuring Range:		5 to 80 ppm	
Number of Strokes n:		3	
Time for Measurement:		approx. 30 s	
Standard	Deviation:	± 10 to 15 %	
Color Change:		blue violet → yellow	

Ambient Operating Conditions

Temperature:	10 to 40 °C
Absolute Humidity:	$<$ 30 mg $\rm H_2O$ / $\rm L$

Reaction Principle

	CH ₂ COOH +	nH Indicator	→	yellow reaction	product
--	------------------------	--------------	----------	-----------------	---------

Cross Sensitivity

It is impossible to measure acetic acid in the presence of other acids.

Organic acids are indicated by the same color change, but with different sensitivities.

Mineral acids (e.g. hydrochloric acid) are indicated by red discolorations and different sensitivities.

