# Pentane 100/a

Order No. 67 24 701

### Application Range

Standard Measuring Range:	100 to 1,500 ppm
Number of Strokes n:	1
Time for Measurement:	approx. 15 s
Standard Deviation:	± 15 to 20 %
Color Change:	white → brown green

# **Ambient Operating Conditions**

Temperature:	0 to 40 °C
Absolute Humidity:	1 to 40 mg H <sub>2</sub> O / L

## Reaction Principle

$\sim$ $\Box$		- 1	
(, H	+ 1 ( ) -	·	
O51 119	1005	10	

#### Cross Sensitivity

Alcohols, esters, aromatics, petroleum hydrocarbons and ethers are indicated, but with different sensitivities. It is impossible to differentiate between them.



7-20047-2017