



RAVIRATNA MOTORS PVT. LTD.

(Authorised Maruti Dealer)

OPP. YOGI PETROL PUMP, N.H. NO. 8, BHARUCH - 392011. PHONE : 96876 91076, 96876 91044, 96876 32647 E-mail : raviratn.brh.ccm2@marutidealers.
GSTIN : 24AABCR7938L1ZY • PAN NO. : AABCR7938L

ORIGINAL FOR RECIPIENT/DUPPLICATE FOR TRANSPORTER/TRIPPLICATE FOR SUPPLIER

Job Card Retail - Tax Invoice

Customer Name & Address : ID : 2248352484 Invoice No. : 6/BR/25009446 Date : 15/10/2025 18:40:08
BBELL INDUSTRY LLP
119,GIDC SAYAKHA, AT:SAYAKHA, TA:VAGRA DIST:BHARUCH
BHARUCH Job Card No. : JC25015461 Job Card Date: 15/10/2025
Pin:392140 Reg.No. : GJ16DG7919 Mileage : 154017
State & Code : 24-GUJARAT SA Name : PRAKASHBHAI MAGANBHAI PAR SA(M):9687691059
Mobile : 7016840460 Model : MARUTI EECO 5 STR AC, EW Type : NA
Loyalty Card : NA Chassis No. : A91645 Last Service : 141663 (20-07-25)
Cust GSTIN/UIN : 24AAPFK0441G1ZK PAN : AAPFK0441G Service type: Periodic Maintenance Service Next Service Due : PMS160
Place of Supply: GUJARAT

Srl.	Part Number	Description	Batch	HSN/SAC	Tax	Qty.	Rate	Taxable Amount	Tax Paid Amount	Labour Charges
Labour										
Schedule Service										
1	ZE26L0P	PMS 50/70/100		998729						1,340.00
Demanded Repairs-Others/Suggested Jobs										
1	ZA11L0	WHEEL ALIGNMENT		998729						310.00
2	ZF03L0	DOOR GLASS/ ADJUST/ LUBRICATE		998729						373.50
3	ZA04L0	WHEEL BALANCING - 4 WHEEL		998729						260.00
4	MK02R01	FRONT BRAKE CALIPER ASSY (ONE SIDE) WITH OPPOSITE SIDE		998729						467.82

Recommendations :

ALL TIRE NOT GOOD HEAD LIGHT OUT
SIDE FEETING

For RAVIRATNA MOTORS PVT LTD

Authorised Signatory

Dealer GSTIN : 24AABCR7938L1ZY

Sub Total Amount	:	2,038.46	0.00	2,751.32
CGST @ 9%	:	183.46		247.62
SGST @ 9%	:	183.46		247.62
Sub Total Amount	:	2,405.38	0.00	3,246.56
Net Bill Amount (Rounded)	:			5,652.00

Rupees Five Thousand Six Hundred And Fifty Two Only

* Unapproved fitments may affect your and vehicle safety. Kindly do not fit any unapproved fitments in your vehicle.

A + B = 5652