

DESIGN FOR MANUFACTURING REPORT

Part Information

Optimal Mold Direction : +Z

Manufacturability Summary

Undercut Faces : 127

Undercut Regions : 38

Parting Faces : 106

Core / Cavity Analysis

Core Faces : 186

Cavity Faces : 263

Parting Line

Start Point : [57.22364078 -84.7553892 -0.52592818]

End Point : [-57.05374251 79.38072667 -0.40290068]

Overall DFM Assessment

Score : 2.13 / 100

Rating : Poor

Risk Level : High

Recommendation : Reduce undercuts or use sliders.