## REGISTER PO CER

Dari Tanggal: 09/05/2018 s/d 09/05/2019

Project: D40L

09-May-2019 13:35.32

	NO. PO	TGL PO	CER REQ	CERQ	SUPPLIER NAM E	DESCRIPTION	QTY	UNIT	PRICE -	DELIVERY		
NO.										PLAN	ACT UAL	
1	PO-PPR-1903-0007 0	06-Mar-2019	CER-PPR/ADM/D40L/1903-0030 0	CERQ-PPR/D40L/1903-0007 0	CUI - COPPAL UTAMA INDOMELT, PT - CUI	1 19PFHMHEADM022PRO2 Ploses Pattern Router Moss Headlining, Roof,(VAN),	1.00	unit	14,500,000	06-Apr-19	06-Apr-19	
2	PO-PPR-1903-0008 0	06-Mar-2019	CER-PPR/ADM/D40L/1903-0026 0			D40L Proses Pattern Router Mold, Headlining, Roof,(VAN), D40L	<b>)</b>					the section of the section of
					INDOMELT, PT - CUI	1 19PFHMHEADM021PRO2 Proses Pattern Router Mod. Headlining, Roof, No. 1 (PU), D40L Proses Pattern Router Mold,	1.00	unit	14,500,000	11-Apr-19	11-Apr-19	ltem description to berulang, padahal master tidak beru
3	PO-PPR-1903-0009 0	08-Mar-2019	CER-PPR/ADM/D40L/1903-0032 0	_	YPT - YOGYA PRESISI TEHNIKATAMA INDUSTRI PT YPT	Headlining, Roof, No. 1 (PU): B401  1 19PFHMHEADM022MAC	1.00	unit	340,000,000	28-Jun-19		
4	PO-PPR-1903-0010 0	08-Mar-2019	CER-PPR/ADM/D40L/1903-0028 0	CERQ-PPR/D40L/1903-0010 0	YPT - YOGYA PRESISI	4 Proses Machining Fix Mold, Headlining, Roof (VAN), D40L Proses Machining Fix Mold, Headlining, Roof (VAN), D40L						
				_	TEHNIKAT AM A INDUSTRI PT YPT	1 19PFHMHEADM021MAC 4 Proses Machining Fix Mold, Headlining, Roof, No. 1 (PU), D40L Proses Machining Fix Mold.	1.00	unit	290,000,000	17-Jun-19		

n tertulis hal secara erulang