

SBC 201 Chapter 11 Accessibility — Group R-1 High-Rise Dimensional Requirements Matrix (2024)

1. Document metadata and use limitation

- **Project basis:** Mixed-use tall building containing Group R-1 (hotel) with Group R-2 residential and Group B office/amenities sharing podium, parking and routes. An occupied floor is stated to be more than 23 m above the relevant reference level. This matrix filters Chapter 11 for the **Group R-1 hotel** portion.
- **Deliverable tier:** Project-use matrices in Sections 1–17 (design-check rows, not pasted inventory), plus a coverage summary and unresolved-source register. The full row inventory is not published.
- **Code/source basis:** SBC 201 (2024), Chapter 11, source file Reference\SBC 201 2024\source_reference\Chapter_11 – ACCESSIBILITY.txt.
- **Extraction audit:** Internal inventory: **276** independently checkable numeric records (**192** Verified, **84** Verify source). Unresolved OCR is listed in the register and is not a design-release value.
- **Model:** Cursor Grok 4.6.
- **Prepared:** 2026-08-28.
- **Status:** Source-only architectural advisory matrix for design coordination. It is not a stamped compliance statement, accessibility consultant report, SCD NOC, SBPS approval, legal opinion, or permission to construct.
- **Outbound-source rule:** No value in this matrix has been imported from ICC A117.1, Chapter 10, Chapter 9, Section 403, Chapter 30, SBC 701, SBC 901, HUD/FHAG, ADA, commentary examples, or the chapter summary. Where Chapter 11 sends the user elsewhere, this matrix records the dependency without supplying the outbound value.

Scope and assumptions

1. Group R-1 and high-rise status are project statements, not independently verified classifications.
2. The mixed-use podium with Group R-2 and Group B is a project statement. Shared routes, parking, EV, recreation and public entrances must be assigned to an occupancy before a row is used as Direct.
3. The exact AHJ/permit pathway, project stage and SCD NOC status are unconfirmed; therefore this matrix does not conclude compliance.
4. Typical transient hotel path is **Section 1108.6.1.1** (Accessible units per Table 1108.6.1.1). Type B units apply only where units are **intended to be occupied as a residence** (1108.6.1.2).
5. Automatic sprinkler protection is not selected in this chapter extract. Chapter 11 does not branch hotel unit scoping on NFPA 13 versus 13R.
6. Guestroom count, parking counts/types, valet, banquet/F&B, recreation layouts and EV provision are unconfirmed.
7. Chapter 11 is **scoping**. Technical millimetre geometry for accessible routes, doors, toilets, kitchens and Accessible units is ICC A117.1. Charging **1102.1** names ICC A117.1 with **no edition year**. General Comments name 2009; later commentary discusses 2017 anthropometry. Neither commentary year is adopted as a charging substitution.
8. All eight appended tables are concatenated OCR. No reconstructed cell is adopted as a design-release value. Affected project-use rows are **Verify source**.
9. Group R-2 apartment Type A/B mix, R-2 2-percent parking, and the 1107.2 R-2 EV exemption are **not** applied to the hotel. See the companion R-2 High-Rise Chapter 11 matrix for the residential tower.

2. Legends

Applicability

Status	Meaning
Direct	Expected to govern the stated R-1 hotel basis, subject to confirmed geometry and design data.
Conditional	Governs only when the stated feature, use, occupant load, unit type or mixed-use/podium condition exists.
Not typical	Unrelated occupancy-only rule; omitted from this deliverable unless the gap register already opened that use.
External verification	Chapter 11 points to another section/code/standard, or the project/AHJ basis must be confirmed before use.

Source confidence

Status	Meaning
Verified	Requirement and any stated numeric value were checked against unambiguous mandatory Chapter 11 source text.
Verify source	OCR, flattened table, page-split, or footnote attachment is unresolved. Not a design-release value.

3. Project decision and gap register

Decision / gap	Current project basis	Why it controls Chapter 11 application	Required project action
ICC A117.1 edition	Charging 1102.1 has no year; General Comments name 2009; commentary discusses 2017	Controls turning spaces, clear floor space, door manoeuvring, Accessible-unit interiors	AHJ/code consultant to lock the referenced edition; do not silently switch editions
Transient vs extended-stay	Unconfirmed	1108.6.1.1 Accessible units always; 1108.6.1.2 Type B only if units are intended as a residence	Freeze hotel operating model (nightly vs corporate/extended stay) before unit typicals
Guestroom count and classes	Unconfirmed	Table 1108.6.1.1 quotas; > 50 units per structure counted separately on a multi-building site; dispersion among classes	Issue a signed key schedule by class (standard, suite, kitchenette, executive)
Mixed-use Type B on the same structure	R-2 Type B units stated on the same building	1104.1 vehicular-way exception does not apply to buildings containing or serving Type B units	Provide a pedestrian accessible route from every applicable arrival point; do not use a driveway-only exception
Mixed-use power doors	Table 1105.1.1 lists A-1–A-4, B, M, R-1 ; footnote uses most restrictive listed load	Hotel public entrances can be pulled in by Group B/A/M loads even if the hotel load alone is below the table	Sum listed mixed-use occupant loads after published-source check of the table
Parking facility split	Unconfirmed shared garage	R-1 uses 1106.3 Item 2 → Table 1106.2 , not the R-2 2-percent rule; calculate each parking facility separately (1106.2)	Produce a parking schedule by facility and occupancy served (hotel, residential, office)
Valet / porte-cochère	Unconfirmed	1106.9.3 requires an accessible passenger loading zone at valet; 1106.9.1 spaces accessible zones at ≤ 30 m	Confirm drop-off length and valet operation

Decision / gap	Current project basis	Why it controls Chapter 11 application	Required project action
Recreation serving which occupancy	Unconfirmed shared pool/gym	Hotel/office recreation uses 1111.3 (all facilities accessible). R-2 Type A/B uses 1111.2.2 (25% / ≥ 1) . 1111.4.14 Ex. 3 water-entry waiver is only on the 1111.2.2/2.3 path	Map every recreational facility to the occupancies it serves
EV charging	Unconfirmed	1107.2 exception is R-2, R-3, R-4 only — hotel EV is not exempt	If hotel or public chargers exist, apply 1107.2.1 / 1107.2.2
Occupied roof / amenities	Unconfirmed	1104.4 requires an accessible route to each accessible story, mezzanine and occupied roof; 1108.3 common rooms serving Accessible units must be accessible	Show an accessible route to lobby, F&B, banquet, gym, pool deck and any occupied roof serving the hotel
NOC / accessibility consultant	Unconfirmed	Technical A117.1 geometry, assisted-evacuation and SCD acceptance cannot be concluded from Chapter 11 scoping alone	Engage the qualified local accessibility/fire consultants before design freeze

4. Scoping versus technical standard

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1101.1	Chapter scope	This chapter controls design and construction of facilities for accessibility	All facilities in scope	None stated	Direct	Treat Chapter 11 as the scoping document for the hotel and the site elements that serve it	Verified
1102.1	ICC A117.1	Accessible in accordance with this code and ICC A117.1 (no year)	All required accessible facilities	None stated	External verification	Lock the A117.1 edition with the AHJ; do not import millimetre geometry here	Verified
1108.2	Unit interiors	Accessible / Type A / Type B units comply with applicable portions of Chapter 11 of ICC A117.1 ; higher unit types may substitute	Required unit types	Type A may be built as Accessible; Type B as Accessible or Type A	External verification	Produce Accessible-guestroom typicals from the referenced A117.1 chapter, not from commentary millimetres	Verified
1110.1 Exception	Unit toilets/kitchens	Accessible, Type A and Type B units shall comply with Chapter 10 of ICC A117.1	Those unit types	1110 otherwise still governs common/public features	External verification	Note the source names Chapter 10 here and Chapter 11 at 1108.2; verify the printed A117.1 mapping before detailing	Verified
1108.3	Common rooms serving units	Rooms and spaces available to the public or residents and serving Accessible, Type A or Type B units shall be accessible, including toilet/bathing, kitchen, living/dining and exterior patios/terraces/balconies	Amenities serving required units	1108.4 story exemptions; 1111.2 recreation (R-2/R-3/R-4 path, not the hotel 1111.3 path)	Direct	Put lobby, restaurants, banquet, laundry, gym and pool deck on an accessible route serving Accessible guestrooms	Verified

5. General applicability and surviving exceptions

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1103.1	Default accessibility	Sites, buildings, structures, facilities, elements and spaces, temporary or permanent, shall be accessible	All construction	Only to the extent permitted by 1103.2 / 1104–1112	Direct	Assume accessible unless a numbered exception is proven	Verified
1103.2.2	Employee work areas	Approach, enter and exit plus 907.5.2.3.1, 1009 and 1104.3.1 only	Employee work areas	Portions < 28 m² and ≥ 175 mm essential level change exempt from all requirements (not courtroom stations)	Conditional	Apply to BOH, kitchens, housekeeping and security desks; keep visible alarm and accessible MOE outbound	Verified
1103.2.9	Equipment spaces	Spaces frequented only by service personnel for maintenance, repair or occasional monitoring of equipment are not required to comply with this chapter	Service-only equipment spaces	None stated	Direct	Do not force an accessible route into elevator pits, penthouses or typical MEP rooms	Verified
1103.2.14	Walk-in coolers	Walk-in cooler and freezer equipment accessed only from employee work areas is not required to comply with this chapter	BOH coolers	Public-facing coolers still need operable parts / display on the public side (1110.10.2, 1110.15)	Conditional	Exempt kitchen walk-ins; keep front-of-house display coolers in the operable-parts package	Verified
1104.3.1 Ex. 1	Small work-area path	Common-use circulation paths in employee work areas < 100 m² defined by permanent partitions/furnishings need not be accessible routes	Employee work areas	Equipment-integral and weather-exposed exterior path exceptions also stated	Conditional	Keep an accessible route to the work area; the path through a small defined workstation may be exempt	Verified

6. Accessible routes and stories

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1104.1	Site arrival route	At least one accessible route from transit, accessible parking, accessible loading, streets/sidewalks to the accessible entrance	Site arrival points	Vehicular-way-only exception does not apply to buildings containing or serving Type B units (R-2 on this mixed-use structure)	Direct	Provide a pedestrian accessible route from every applicable arrival point	Verified
1104.2	On-site connections	At least one accessible route connecting accessible buildings, facilities, elements and spaces on the same site	Multiple accessible elements on one site	Vehicular-way-only; recreation only as 1111	Direct	Connect podium, parking, lobby, F&B and recreation to the same accessible network	Verified
1104.3	Connected spaces	At least one accessible route to each required accessible portion, to accessible entrances connecting accessible walkways, and to the public way	Building required to be accessible	1104.4 story skips; assembly levels without wheelchair spaces; courtroom workstations; 1111 recreation	Direct	Trace the accessible route from public way through lobby, lifts, guest floors with Accessible units, and amenity floors	Verified
1104.4	Multistory / occupied roof	At least one accessible route shall connect each accessible story, mezzanine and occupied roofs	Multilevel buildings	Exception 1 (≤ 279 m² aggregate) does not apply to this elevator high-rise. Exception 2: stories with no 1108/1109 accessible elements need not be served	Direct	Serve every story that contains Accessible units, public use or common use serving those units, including occupied roof	Verified

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1104.5	Route coincidence	Accessible routes shall coincide with or be in the same area as general circulation; interior circulation requires an interior accessible route; a single accessible route shall not pass through kitchens, storage, restrooms, closets or similar	Accessible routes	2. A single route may pass through a kitchen or storage room inside an Accessible, Type A or Type B unit	Direct	Keep common accessible routes in public circulation, not through service rooms	Verified
1108.4	Route to units	At least one accessible route shall connect accessible building entrances with the primary entrance of each Accessible, Type A and Type B unit and with interior/exterior spaces serving the units	Required units	5. In Group R-1, a route is not required to connect stories within an individual unit if the accessible level is an Accessible unit and provides sleeping for two persons minimum and a toilet on that level. 7. Type B stories exempted by 1108.7	Direct	Serve every Accessible guestroom entrance from an accessible building entrance. Do not use Exception 5 to skip hotel stories	Verified
1104.6	Security barriers	Security barriers shall not obstruct a required accessible route or accessible means of egress	Bollards, checkpoints	Adjacent route permitted around devices that cannot comply (metal detectors), with visual contact of personal items	Conditional	If a lobby security line exists, provide an adjacent accessible path that keeps bags in view	Verified

7. Entrances

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1105.1	Public entrances	At least 60 percent of all public entrances shall be accessible, in addition to 1105.1.2–1105.1.8	Public entrances	Areas not required to be accessible; loading/service entrances that are not the only tenant entrance	Direct	Count public doors (not egress-only doors) and make ≥ 60% accessible	Verified
1105.1.1 / Table 1105.1.1	Power-operated public entrance	One full-power or low-energy power-operated door at each required accessible public entrance when occupancy and building occupant load exceed the table; vestibule: one leaf in and one leaf out	Table lists Groups A-1–A-4 and B, M, R-1 . Mixed-use uses the most restrictive listed load	Flattened OCR occupant-load cells are not adopted	Direct	Power-operate accessible hotel public entrances once the published R-1/B/M/A load is confirmed; mixed-use may use the most restrictive listed load	Verify source
1105.1.2	Parking-garage entrance	Direct pedestrian access from parking structures to building/facility entrances shall be accessible	Direct garage-to-building pedestrian access	None stated	Direct	Provide an accessible pedestrian door from the parking structure into the hotel lobby	Verified
1105.1.3	Tunnel / walkway entrance	At least one accessible entrance from each pedestrian tunnel or elevated walkway	Direct pedestrian access from those links	None stated	Conditional	If a podium link bridge exists, make at least one door from it accessible	Verified
1105.1.4	Restricted entrance	At least one restricted entrance shall be accessible	Restricted (security-controlled) entrances	Key-card staff doors that are not “restricted entrances” are not this section	Conditional	If a members-only or staff-secure hotel entry exists, make at least one of that type accessible	Verified
1105.1.7	Tenant entrance	At least one accessible entrance to each tenant in a facility	Multi-tenant facility	Self-service storage not required to be accessible	Conditional	If podium tenancies exist, give each tenant an accessible entrance in addition to the 60% building count	Verified
1105.1.8	Unit entrance	At least one accessible entrance to each dwelling/sleeping unit	Dwelling and sleeping units	Not required to units that are not Accessible, Type A or Type B	Direct	Every Accessible guestroom gets an accessible entrance; shared lobby doors still count toward 60%	Verified

8. Parking, vans and passenger loading

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1106.3 Item 2	R-1 accessible parking	In Group I-1 and R-1 occupancies, accessible parking shall be provided in accordance with Table 1106.2	R-1 parking	Table 1106.2 is flattened OCR. Do not use the R-2 2 percent rule (Item 1)	Direct	Size hotel accessible stalls from the published Table 1106.2 after source check; calculate each parking facility separately (1106.2)	Verify source
Table 1106.2	General parking table	Flattened OCR table; no reconstructed stall-count cell is adopted	Parking facilities using 1106.2	R-1 uses this table via 1106.3 Item 2	Direct	Hold stall counts until the published table is verified; do not reconstruct concatenated cells	Verify source
1106.3 Item 3	1:1 parking vs Accessible units	Where at least one parking space is provided for each dwelling/sleeping unit, at least one accessible parking space shall be provided for each Accessible and Type A unit	Parking provided at ≥ 1 space per unit	Code does not state that Item 2 and Item 3 are additive	Conditional	If assigned 1:1 hotel parking exists, provide an accessible stall for every Accessible guestroom and compare with Table 1106.2	Verified
1106.3 Item 4	In-building parking	Where parking is within or beneath a building, accessible parking shall also be within or beneath the building	Parking in/under the building	None stated	Direct	Put accessible stalls in the podium/basement garage, not only on the surface lot	Verified
1106.6	Van spaces	For every six or fraction of six accessible parking spaces, at least one shall be van-accessible	Accessible parking provided	2100 mm van-height reduction is Group U private garages serving R-2 and R-3 only — not R-1	Direct	Provide 1-in-6 vans; do not use the 2100 mm R-2/R-3 garage exception for hotel stalls	Verified
1106.7 Ex. 1	Van-space level	In multilevel parking structures, van-accessible parking spaces are permitted on one level	Multilevel parking	Accessible spaces still dispersed; van-height millimetres are A117.1 (not imported)	Direct	Concentrate van stalls on the level that can provide the A117.1 van clearance	Verified
1106.9.1	Continuous loading zone	One accessible passenger loading zone in every continuous 30 m maximum	Passenger loading zones provided	None stated	Conditional	If a porte-cochère exists, space accessible zones at ≤ 30 m	Verified
1106.9.3	Valet loading zone	A passenger loading zone shall be provided at valet parking services	Valet parking	Valet does not delete accessible parking	Conditional	If valet is offered, provide an accessible drop-off; still provide 1106 parking	Verified

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1112.1 Item 2	Hotel stall identification	Accessible parking required by 1106.3 shall be identified by the ISA	1106.3 accessible spaces	Assigned-stall identification exception is I-1, R-2, R-3, R-4 only — not R-1	Direct	Sign every required hotel accessible stall; do not use the R-2 assigned-space signage exception	Verified

9. Electrical vehicle charging

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1107.2 Exception	R-2 EV exemption (not R-1)	EV charging stations provided to serve Groups R-2, R-3 and R-4 are not required to comply with 1107.2	EV serving those occupancies	Group R-1 is not listed	Direct	Do not apply the residential EV exemption to hotel or public chargers	Verified
1107.2.1	Accessible EV count	Not less than 5 percent of vehicle spaces served by EV systems, but not fewer than one of each type , shall be accessible	EV systems not covered by the R-2/R-3/R-4 serving exception	None stated beyond 1107.2	Conditional	If hotel or podium/public chargers exist, reserve 5% (≥ 1 of each charger type)	Verified
1107.2.2	Accessible EV stall size	3300 mm minimum vehicle-space width with adjoining access aisle 1500 mm minimum	Accessible EV spaces required by 1107.2.1	None stated	Conditional	Do not substitute a narrower A117.1 van option; this section specifies 3300 + 1500	Verified

10. Sleeping-unit mix (Accessible / Type B)

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1108.6.1.1	Accessible-unit site vs structure	Accessible units per Table 1108.6.1.1. Multi-building site: structures > 50 units counted per structure ; structures ≤ 50 units counted site-wide . Disperse among classes of units	Group R-1 dwelling/sleeping units	1103.2.11 (≤ five sleeping units + proprietor residence) is not this tall hotel	Direct	Count guestrooms on the signed key schedule; use the 50-unit split if more than one hotel structure exists	Verified
Table 1108.6.1.1	Accessible-unit quotas	Flattened OCR table (without roll-in / with roll-in / total). No reconstructed cell is adopted	Group R-1 Accessible units	Applies also to congregate R-2 (not this hotel path)	Direct	Provide Accessible guestrooms, including the published roll-in-shower split, only after source check of the table	Verify source
1108.6.1.2	Type B extended stay	In structures with four or more dwelling/sleeping units intended to be occupied as a residence, every such unit shall be Type B	Units intended as a residence	Reduction permitted per 1108.7. Typical transient hotel is not this trigger	Conditional	If corporate/extended-stay product is intended as a residence, make every such unit Type B (Accessible units already exceed Type B)	Verified
1108.7.3	Elevator only to lowest unit story	Where elevator service provides an accessible route only to the lowest story containing residence units, only units on that story need be Type B	Elevator limited to the lowest unit story	Applies to Type B reductions, not Accessible-unit quotas	Conditional	If Type B is triggered and the lift core serves all hotel floors, this exception is not available	Verified

11. Common toilets, kitchens, drinking fountains and lifts

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1110.2	Toilet/bathing rooms	Each toilet room and bathing room shall be accessible; at least one of each type of fixture/element/control/dispenser accessible	Toilet/bathing rooms	Ex. 2: rooms serving dwelling/sleeping units not required to be accessible by 1108 . Ex. 3: clustered single-user rooms ≥ 50% (≥ 1 of each use). Do not locate the only toilets on a non-accessible floor	Direct	Make lobby, F&B and banquet toilets accessible; Accessible-guestroom bathrooms follow A117.1	Verified
1110.2.1	Family/assisted-use toilet	Required in assembly and mercantile where aggregate male+female water closets ≥ 6 ; travel ≤ 150 m and ≤ one story from separate-sex rooms	Assembly/mercantile fixture count	Mixed occupancy: count only A/M water closets. Family bathing room required where separate-sex bathing rooms are provided in recreational facilities	Conditional	If banquet/F&B/retail hits six WCs, add a family room on an accessible route	Verified
1110.2.4	Compartments	≥ 5% of compartments wheelchair-accessible; if compartments+urinals ≥ 6 , ≥ 5% ambulatory-accessible in addition	Multi-compartment toilets	Unit bathrooms excepted via 1110.2 Ex. 2	Conditional	Size lobby/F&B toilets with a wheelchair stall; add ambulatory stall when the room is large	Verified
1110.2.5	Lavatories	≥ 5% (≥ 1) accessible; extra accessible lavatory if the only one is inside the accessible stall; ≥ 6 lavatories → one enhanced-reach	Lavatories provided	Enhanced reach per A117.1 (not imported)	Conditional	Do not hide the only accessible lavatory inside the accessible stall	Verified
1110.4	Kitchens and kitchenettes	Kitchens and kitchenettes in accessible spaces or rooms shall be accessible	Common kitchens / kitchenettes	Unit kitchens follow 1110.1 Exception / A117.1 (not imported)	Direct	Detail lobby pantry, club lounge kitchen and staff break kitchenettes as accessible	Verified
1110.5.1	Drinking fountains	No fewer than two : one wheelchair, one standing (or dual-spout substitute)	Drinking fountains provided on a floor/site/secured area	Children’s standing spout 760 mm minimum	Conditional	If fountains are provided, install hi-lo; do not import SBC 701 fixture counts	Verified
1110.8	Elevators	Passenger elevators on an accessible route shall be accessible and comply with Chapter 30	Passenger elevators on an accessible route	Freight/construction elevators not this section	External verification	All passenger cars on the accessible route are accessible; stretcher/FSAE sizes live in Chapter 30 / 403, not here	Verified
1110.9 Item 4	Platform lifts in units	Platform lifts permitted on a required accessible route within an individual Accessible, Type A or Type B unit	New construction	ASME A18.1 (not imported)	Conditional	Use a lift inside a split-level Accessible suite only if chosen; it does not replace building elevators	Verified
1110.13.2	Sales and service counters	At least one of each type of sales or service counter/window shall be accessible; disperse if the counters are dispersed	Reception, F&B, retail counters	Not a check-out-aisle table	Direct	Lower at least one reception/check-in and one of each F&B/retail service counter type	Verified

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1110.13.3	Food-service lines	Food service lines shall be accessible; ≥ 50% (≥ 1) of each type of self-service shelf accessible	Food-service lines provided	None stated	Conditional	If a buffet or cafeteria line exists, put the line and ≥ 50% of each shelf type on the accessible route	Verified

12. Recreational facilities

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1111.3	Recreation other than R-2/R-3/R-4	Recreational facilities not falling within 1111.2 shall be accessible	Hotel, office and other occupancies outside 1111.2	Shared facilities that also serve R-2 Type A/B still cannot drop below 1111.3 where they serve the hotel	Direct	Make every hotel-serving pool, gym, court and spa accessible — do not use the R-2 25% rule	Verified
1111.4.14	Pool water entry	Swimming pools, wading pools, cold baths, hot tubs and spas shall be accessible and on an accessible route	Those water features provided	Ex. 1 catch-pool/slide terminus. Ex. 2 clustered spas 5% (≥ 1 of each type). Ex. 3 water-entry waiver is only for 1111.2.2 / 1111.2.3 (Type A/B) — not 1111.3	Direct	Provide an accessible route to and into hotel pools/spas; do not use the Type A/B water-entry waiver	Verified
1111.4.10	Exercise machines	At least one of each type of exercise machine and equipment shall be on an accessible route	Exercise machines provided	Operable-part heights are A117.1 (not imported)	Conditional	Put at least one of each gym machine type on the accessible route	Verified
1111.4.2	Player seating	At least one wheelchair space in team/player seating serving areas of sport activity	Team/player seating provided	Bowling-lane exception	Conditional	If a court has player benches, provide one wheelchair space	Verified
1111.4.4	Court sides	At least one accessible route shall directly connect both sides of the court	Court sports	None stated	Conditional	If tennis/padel/basketball courts exist, connect both sides without leaving the court area	Verified
1111.2.2	R-2 Type A/B recreation (companion)	25 percent , but not less than one , of each type where recreation serves a single building containing Type A or Type B units	Recreation serving R-2 Type A/B	Does not govern hotel-only facilities; mixed shared rec still meets 1111.3 for the hotel	Conditional	If a pool is hotel-only, ignore this row. If shared with R-2, the hotel 1111.3 100% path governs the hotel share	Verified

13. Signage

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1112.1 Items 4–7	Partial-access identification	Identify accessible toilets, entrances, check-out aisles and dressing/locker rooms where not all are accessible	Mixed accessible/non-accessible sets	None stated	Direct	Sign the accessible lobby entrance if any public entrance remains inaccessible	Verified
1112.1 Items 8–9	Accessible MOE signs	Accessible areas of refuge and exterior areas for assisted rescue in accordance with Section 1009.9	Those elements provided	Values not in Chapter 11	External verification	Coordinate ISA with the Chapter 10 accessible-egress package	Verified
1112.3	Directional signs	Directional ISA signage at inaccessible entrances, toilets, elevators not on an accessible route, family-toilet locations, exits not providing approved accessible MOE (1009.10), and split hi-lo fountains	Those conditions	Visual characters per A117.1 (not imported)	Direct	Place directional copy at every inaccessible public entrance	Verified
1112.4 Item 1	ALS availability sign	Assembly areas required to comply with 1109.2.7 shall notify patrons of assistive listening systems, with the hearing-loss symbol	Assembly with ALS	Signs at each ticket window may substitute for signs in each assembly room	Conditional	If a banquet hall has a PA, post ALS availability at the door or ticket point	Verified

14. Podium, amenity and assembly (conditional)

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
Table 1109.2.2.1	Wheelchair spaces	Flattened OCR table; no reconstructed seating-capacity cell is adopted	Assembly with fixed seating	Companion seat per 1109.2.3 (one per wheelchair space); 5% designated aisle seats	Conditional	If a banquet hall, cinema or lecture room has fixed seats, apply the published table after source check	Verify source
1109.2.5	Designated aisle seats	≥ 5% (≥ 1) of aisle seats, closest to accessible routes	Aisle seats provided	Not required in team/player seating	Conditional	Mark aisle seats nearest the accessible route in amenity auditoria	Verified
1109.2.9.1	Dining surfaces	≥ 5% (≥ 1) of dining surfaces for seating and standing spaces accessible, distributed, on an accessible level	Dining surfaces provided	Mezzanine < 25% dining area exception (1109.2.9 Ex. 2)	Conditional	Provide wheelchair dining in hotel restaurants and bars	Verified
Table 1109.2.7.1	ALS receivers	Flattened OCR table; asterisks unresolved; no reconstructed receiver-count cell is adopted	Assembly where audible communication is integral	Not required (except courtrooms) where there is no audio amplification; induction-loop HAC exception	Conditional	If a banquet hall has a PA, provide receivers after published-source check of the table	Verify source
1110.14	Locker / fitting rooms	≥ 5% (≥ 1) of each type of use in each cluster shall be accessible	Dressing, fitting or locker rooms provided	None stated	Conditional	If spa/gym lockers exist, make ≥ 5% of each cluster accessible	Verified

15. High-rise and outbound controls

Cite	Component / check	Exact source requirement / value	Trigger / condition	Exceptions / branch	R-1 hotel status	Design action	Source confidence
1009 (named)	Accessible means of egress	Chapter 11 repeatedly sends accessible egress to Section 1009	Accessible floors and occupied roofs	No 1009 values imported	External verification	Use the Chapter 10 matrix for AMOE; do not copy those numbers here	Verified
1110.8 / Ch. 30 / 403	Elevators	Passenger elevators on the accessible route: accessible + Chapter 30. Commentary also names stretcher, 1009.2.1 and 36 m FSAE — commentary numbers are not adopted	Elevators / high-rise	Charging 1110.8 does not itself state 36 m or four-storey triggers	External verification	Coordinate stretcher, FSAE and occupant-evacuation elevators from Chapter 30 / 403, not from Chapter 11 commentary	Verified
SBC 901 §306	Existing buildings	Named in General Comments only	Existing buildings	Not quantified in this chapter's code paragraphs	External verification	Alterations are outside this new-construction extract	Verified

16. Project-use controls

1. Use **Verified** rows for initial scoping after the row trigger and branch are confirmed.
2. Treat every **Verify source** row (all reconstructed appended tables) as a design hold point; no affected value is to be placed in issued-for-approval drawings without a published-source check.
3. Do not apply Table 1108.6.1.1 reconstructed cells; wait for the published table.
4. Do not apply the R-2 **2 percent** parking rule, the R-2 assigned-stall signage exception, the 1107.2 R-2 EV exemption, or the 1111.2.2 **25%** recreation rule to hotel-serving facilities.
5. Do not import ICC A117.1 millimetres, Chapter 10 AMOE dimensions, or commentary examples (810 mm doors, 2500 mm van height, 50°C shower temperature).
6. Record AHJ, guestroom-count, parking, recreation-ownership and extended-stay decisions in the project Golden Thread; this matrix is not evidence of SCD NOC or stamped compliance.

17. Coverage summary

Internal inventory of the attached Chapter 11 extract (numbered code, exceptions, tables, footnotes; commentary excluded). Row-level records are not published.

- **Inventory scope:** numbered code, exceptions, tables, footnotes (commentary excluded)
- **Total independently checkable numeric records:** 276
- **Verified:** 192
- **Verify source:** 84
- **Numeric records in Sections 1101 and 1102:** 0

Counts by top-level section

Top-level section	Records
1101	0
1102	0
1103	3
1104	12
1105	9
1106	12
1107	4
1108	51
1109	16
1110	62
1111	22
1112	1

Appended-table coverage

Appended table	Records	Verify source records
Table 1105.1.1	2	2
Table 1106.2	11	11
Table 1108.6.1.1	33	33
Table 1109.2.2.1	7	7
Table 1109.2.7.1	12	12
Table 1109.3	2	2
Table 1110.13.1	4	4
TABLE 111.4.9.1 (OCR title)	13	13

Coverage cross-check against SBC 201 Chapter 11 Accessibility (2024)_CS.md was topics-only: scoping vs ICC A117.1; 1103.2 exceptions; routes and stories; entrances and power doors; parking/vans; EV charging; dwelling-unit mix; assembly seating and toilets. No CS.md value was copied into a matrix cell.

18. Unresolved-source register

Hold points for the 84 **Verify source** inventory records. Counts are record counts, not distinct numeric values. No value in this register is a design-release figure.

Affected table / clause	Why unverified	Control note
Table 1105.1.1	2 flattened occupancy/load cells	Verify published table; R-1 is listed. Mixed-use footnote uses the most restrictive listed occupant load
Table 1106.2	11 flattened stall-count rows	R-1 parking uses this table via 1106.3 Item 2; verify published table before stall counts
Table 1108.6.1.1	33 flattened Accessible-unit cells (without / with roll-in / total)	Direct for Group R-1; verify published table before guestroom mix. 50-unit site/structure rule in 1108.6.1.1 text is Verified
Table 1109.2.2.1	7 flattened wheelchair-space rows	Verify published table before banquet/assembly seating
Table 1109.2.7.1	12 flattened receiver/HAC cells; asterisks unresolved	Verify published table before ALS receiver counts
Table 1109.3	2 flattened self-storage rows	Not typical for this hotel; verify published table only if self-storage is added
Table 1110.13.1	4 flattened check-out-aisle rows	Not typical unless podium retail check-out aisles exist; verify published table
TABLE 111.4.9.1 (OCR title as printed)	13 flattened boat-slip rows	Title OCR; not typical for this hotel; verify published Table 1111.4.9.1 if a marina is added