BEC testing

SBL Micro V2 Parts BEC BEC for 2 Servos BEC for 4 Servos BEC testing The processor Processor part 1 Processor part 2 Testing the processor The output stage Output stage control **Testing output** stage control MOSFET's Testing the **MOSFET's** Filter capacitors Soldering the filter capacitors Testing filter capacitors EMF Evaluation Soldering EMF parts Testing EMF Remaining parts Completion

News

Connect two wires with P1 and P2. If available use a power supply unit with current limiting (50 or 100mA). If you don't have one and you are sure that you don't have not produced any short-circuits, you can also use rechargeable batteries Between the two pads "REC Gnd" and "REC +5V" your voltmeter should now show 5V.

