REPORT NAME: MI-RNP-200



Test Procedure of the Prototype Model

First step

Release the throttle valve of the jacking system and release the pinion gear from restraint. (When the throttle valve is released, the flow will flow freely from port A to port B or from port B to port A, allowing the pinion gear to turn artificially without operating the power system.)



Figure 1: Fig. 1. Illustration of first step