











0.0

psig

P514J0106

Actions

Add Subview

Rate of Change (RoC)

Minimum Reading (MIN)

Maximum Reading (MAX)

Hold Reading (HOLD)

Time Tracker (TIME)

Pressure Temperature Chart (P/T)

Superheat/Subcool Calculation (S/H S/C)

Cancel