
Pre-purchase home inspection

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2012-01

Summary

Buyer inspection found an aging roof, older HVAC equipment, a slow leak below the kitchen sink, two reversed-polarity receptacles, and minor basement moisture staining with no active water intrusion.

Observed Conditions / Findings

- INFO** Roof estimated 8-12 years old with localized granule loss; budget for replacement in the medium term.
- INFO** Furnace manufactured 2004; air conditioner manufactured 2002.
- INFO** Kitchen sink trap showed active seepage.
- INFO** Two first-floor receptacles tested with reversed polarity.
- ATTENTION** Basement west wall had old moisture staining; surface was dry at inspection.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2012-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.