
Pre-purchase sewer scope

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2012-03

Summary

Camera inspection from cleanout to municipal connection showed serviceable clay-to-PVC transition and light root intrusion near 54 feet; no standing water or collapse.

Observed Conditions / Findings

- 1. ATTENTION** Light root intrusion at approximately 54 ft.
- 2. INFO** Recommend cleaning every 3-5 years and re-scope if drainage slows.
- 3. INFO** No structural failure observed.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2012-03

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.