

Garage roof leak investigation

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2017-01

Coverage Record

Investigated a ceiling stain over the attached garage. Water entry traced to deteriorated step flashing where garage roof meets the two-story wall.

Product / Project	Garage roof leak investigation
Coverage	Limited parts / product coverage
Effective date	2017-03-20
Coverage end	See terms below
Registration / Event	E2017-01

Demo Warranty Terms

This fictitious warranty record is designed to let HouseIQ identify coverage dates, model and serial numbers, installer relationships, and warranty expiration. It is not a manufacturer warranty and conveys no real coverage.

- Moisture meter elevated around garage ceiling stain.
- Shingles generally serviceable but showing age.
- Removed localized shingles, replaced step flashing, and installed ice/water membrane patch.
- Interior ceiling left open to dry; no structural rot found.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2017-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.