

Hoosier Chimney & Masonry (Demo)

317-555-0152 | office@hoosierchimney-demo.example

License/ID: MASON-DEMO-144

Estimate

Document #: EST-2019-01-71

Date: 2019-04-06

Chimney-side roof leak investigation

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2019-01

Proposed Scope

Intermittent bedroom ceiling stain traced to failed counterflashing and mortar joints on the chimney, separate from the 2017 garage flashing repair.

- Water test reproduced leak at upper chimney counterflashing.
- Repointed deteriorated mortar joints.
- Installed new counterflashing and sealed reglet.
- Roof shingles noted as aged; recommend budgeting for replacement within 2-4 years.

Quoted project amount	\$1,185.00
Quote status	FOR REVIEW
Valid through	2019-04-06

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2019-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.