

Garage roof leak investigation

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2017-01

Summary

Investigated a ceiling stain over the attached garage. Water entry traced to deteriorated step flashing where garage roof meets the two-story wall.

Observed Conditions / Findings

- 1. ATTENTION** Moisture meter elevated around garage ceiling stain.
- 2. INFO** Shingles generally serviceable but showing age.
- 3. INFO** Removed localized shingles, replaced step flashing, and installed ice/water membrane patch.
- 4. INFO** Interior ceiling left open to dry; no structural rot found.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2017-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.