

**Hoosier Chimney & Masonry (Demo)**

317-555-0152 | office@hoosierchimney-demo.example

License/ID: MASON-DEMO-144

**Invoice**

Document #: INV-2019-01-72

Date: 2019-04-06

## Chimney-side roof leak investigation

**Customer** Jordan & Casey Morgan (Fictitious Demo Homeowners)  
**Service address** 1847 Cedar Hollow Way, Indianapolis, IN 46220  
**HouseIQ property ID** HIQ-DEMO-001  
**Event ID** E2019-01

### Work / Purchase Summary

Intermittent bedroom ceiling stain traced to failed counterflashing and mortar joints on the chimney, separate from the 2017 garage flashing repair.

| Description                           | Amount            |
|---------------------------------------|-------------------|
| Labor / service                       | \$568.80          |
| Materials / equipment                 | \$497.70          |
| Trip, disposal, tax, permit, or misc. | \$118.50          |
| <b>TOTAL</b>                          | <b>\$1,185.00</b> |

**Payment status:** PAID IN FULL

### Technician / Installer Notes

- Water test reproduced leak at upper chimney counterflashing.
- Repointed deteriorated mortar joints.
- Installed new counterflashing and sealed reglet.
- Roof shingles noted as aged; recommend budgeting for replacement within 2-4 years.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2019-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.