

Sump pump replacement

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2020-02

Equipment / Project Identification

Brand	DrainSafe
Model	SP-050C
Serial	DS20E19144
Installed / Completed	2020-05-19

Quick Start / Use

Replaced unreliable sump pump and added battery high-water alarm. Discharge line check valve and lid were also replaced.

Routine Maintenance

- Inspect accessible connections and surrounding area periodically for leaks, damage, unusual noise, or abnormal operation.
- Keep vents, drains, intakes, filters, coils, or moving components clear as applicable.
- Record service dates and replacement parts in the HouseIQ property history.
- Use a qualified service professional for repairs involving electrical, gas, refrigerant, roofing, structural, or concealed plumbing work.

Troubleshooting Notes

- If the equipment stops unexpectedly, verify power and user-accessible controls before scheduling service.
- Do not bypass safety devices.
- When contacting service, provide the model, serial number, installation date, and prior repair history shown above.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2020-02

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.