

Roof condition assessment

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2021-01

Summary

Roof inspection found widespread granule loss, brittle tabs, several exposed nail heads, and aging flashings. Replacement recommended within the year.

Observed Conditions / Findings

- 1. ATTENTION** No active interior leak at inspection.
- 2. INFO** 2017 garage flashing patch remains dry.
- 3. INFO** 2019 chimney counterflashing remains intact.
- 4. INFO** Approximate roof area: 27 squares including waste.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2021-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.