




LEAD REMOVAL CLEARANCE CERTIFICATE

Test Project - Do Not
Delete

Job Reference

LDJ06023

Clearance Date

27 February 2026

Lancaster & Dickenson Consulting Pty Ltd
4/6 Dacre Street, Mitchell ACT 2911
enquiries@landd.com.au
(02) 6241 2779



LANCASTER
AND DICKENSON
CONSULTING



LEAD REMOVAL CLEARANCE CERTIFICATE

Test Project - Do Not Delete

PREPARED FOR:

ACTCON

PREPARED BY:

Lancaster and Dickenson Consulting Pty Ltd
ABN 74 169 785 915

DOCUMENT DETAILS

Report Reference	LDJ06023_Lead Clearance Report - Test Project - Do Not Delete (27 February 2026) - 1
Issue Date	17/03/2026
Report Author	Kyle Lancaster

REVISION HISTORY

Reason for Revision	Revision	Approved By	Date
Original Issue	0	Kyle Lancaster	17/03/2026

INSPECTION DETAILS

Following discussions with ACTCON, Lancaster and Dickenson Consulting (L & D) were contracted to undertake validation of the works area at Test Project - Do Not Delete (herein referred to as 'the Site') following lead abatement works.

Lead abatement works were undertaken by Aztech Services. Ewan Dickenson from L&D visited the Site on 27 February 2026 to complete an inspection of surfaces within the works area for visible settled dust or paint flakes.

Table 1 below details the areas inspected as part of this clearance along with details on the scope of abatement completed for each item.

Photographs of the lead removal area are presented in Appendix A.

Table 1: Lead Clearance Items

Room/Area	Location Description	Works Completed	Photo No.
Front of building	Gutters and downpipes	Flaking lead paint removed, and surfaces overpainted	1

CLEARANCE CERTIFICATION

No visible settled dust or paint flakes associated with the works were identified within the lead abatement area, during the inspection.

The consultant considers that the works area has been suitably remediated and there is no ongoing lead exposure risk and may therefore be re-occupied.

Job exclusions go here

Please do not hesitate to contact the undersigned should you have any queries regarding this report.

For and on behalf of Lancaster and Dickenson Consulting.



Ewan Dickenson
Lancaster & Dickenson Consulting

BACKGROUND

Lead is a toxic substance that can affect people of any age. Lead accumulates in the body, so even small amounts can pose a health hazard over time. Exposure to lead typically occurs through inhalation and ingestion.

During any works which may disturb lead containing paint, generation of lead dust should be eliminated as far as practicable. To ensure the generation of such lead dust is controlled, it is essential to first assess the extent and severity of lead contain paint prior to commencement of works.

REGULATORY GUIDANCE, REGULATIONS AND CODES OF PRACTICE

WHS requirements require that workers must not be exposed to airborne lead dust levels above the workplace exposure standard for lead (0.05mg/m³). Where workers undertake lead risk work, health monitoring must be conducted prior to and during works.

Regulation and Guidance references for works involving the assessment of lead paint in the ACT are listed below:

- ACT Work Health and Safety Act 2011
- ACT Work Health and Safety Regulation 2011
- AS/NZS 4361.2:2017 - Guide to hazardous paint management, Part 2: Lead paint in residential, public and commercial buildings
- U.S. Department of Housing and Urban Development 'Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing' Second Edition, July 2012

STATEMENT OF LIMITATIONS

This report has been prepared by Lancaster & Dickenson Consulting Pty Ltd (L&D) for its client, Client Name in accordance with the agreement/contract between L&D and its Client. The report was designed to be read as a whole document and therefore should only be reproduced in full.

This report is solely for the use of the Client and has not been prepared for use by any other person or third party. This report must only be presented in full and may not be used by any person or third party, other than the Client, unless agreed to in writing by L&D.

This assessment does not comprise a full site register. The assessment was undertaken in accordance with relevant legislation and best practice and is specific to the time the assessment was conducted. The assessment may need to be reviewed periodically to ensure it remains current. All conclusions and recommendations are written by the assessor using information available at the time of writing the report and their professional judgement.



APPENDIX A PHOTOGRAPHS



Photograph 1

Photograph following lead abatement works to gutters and downpipes to front of building