

**RIVERGATE POLICE DEPARTMENT
EVIDENCE UNIT
SCENE / RECOVERED-PARTS PHOTO LOG**

Case Reference (RPD):	TC-2025-1018
Incident Type:	Traffic Collision — Bus vs. Fixed Object / Vehicle vs. Pedestrian (sequential)
Date of Incident:	10/18/2025
Controlling Time of Incident:	02:05 a.m.
Location:	S. Main Street at Third Avenue, Rivergate, CA 91766 (bus-stop platform, east side of S. Main St., approx. 40 ft north of the north curb line of Third Avenue)
Involved Vehicle:	ACTD Bus #4177 — 2019 New Flyer XDE40, Block 512-OWL
Log Prepared By:	Field Evidence Technician M. Cardenas, RPD Evidence Unit
Custodian of Record:	RPD Evidence Unit, 300 Rivergate Plaza, Rivergate, CA 91766
Storage:	RPD Digital Media Server, folder \\RPD-EVS\Cases\2025\TC-2025-1018\Photos ; write-once optical archive DVD-R serial RPD-EV-2025-4419

EQUIPMENT / PHOTOGRAPHER LEGEND

Code	Camera / Operator	Serial / Badge
CAM-A	Nikon D7500 DSLR (RPD Evidence Unit primary) — Field Evidence Tech M. Cardenas	Body S/N NKD-7500-114; Evidence Tech ID EVT-04
CAM-B	Canon EOS 80D (patrol supplemental) — Ofc. R. Delacruz	Body S/N CEO-80D-227; Badge RPD #2814
CAM-C	RPD-issue Ricoh WG-70 macro/rugged compact (close-up trace) — Field Evidence Tech M. Cardenas	Body S/N RCH-WG70-031; Evidence Tech ID EVT-04

All time entries below are local Pacific Daylight Time as recorded by the in-camera clock (verified against RPD Communications time-of-day at 0203 hrs on 10/18/2025, offset < 3 s). Image sequence internally continuous; frame indices preserved. Total exposures logged: **61** (P-001 through P-061).

PHOTO ENTRIES

P-001	Description: General establishing view — S. Main Street looking north from the south crosswalk of Third Avenue; Bus #4177 visible at rest against the bus-stop shelter pole, Rivergate Fire Medic 11 apparatus in foreground. Location: S. Main St. @ Third Ave., south crosswalk, standing position on painted stop bar. Time Captured: 10/18/2025 02:19:14 Camera / Operator: CAM-B / Ofc. R. Delacruz (RPD #2814).
P-002	Description: General establishing view — S. Main Street looking south from a point approx. 30 ft north of Bus #4177's rest position; overview of the bus, impacted light standard, and bus-stop platform in a single frame. Location: S. Main St., east sidewalk, mid-block north of Third Ave. Time Captured: 10/18/2025 02:20:47 Camera / Operator: CAM-B / Ofc. R. Delacruz.
P-003	Description: General establishing view — Third Avenue looking west across S. Main St.; shows signalized intersection, marked crosswalks all four legs, and the darkened NE corner where the light standard is out. Location: Third Ave., east curb, west of S. Main St. intersection. Time Captured: 10/18/2025 02:22:03 Camera / Operator: CAM-B / Ofc. R. Delacruz.

P-004	Description: Establishing view — NE quadrant of the intersection, wide angle; captures the sheared street-light standard, luminaire pendant lying on sidewalk, and bus-stop shelter with Bus #4177 in the background. Corner ambient illumination absent. Location: S. Main St., SE corner across from scene. Time Captured: 10/18/2025 02:23:18 Camera / Operator: CAM-A / Field Evidence Tech M. Cardenas (EVT-04).
P-005	Description: Ambient-lighting reference frame — same NE corner as P-004 without on-scene lighting, exposure 1/8 s f/2.8 ISO 6400 to document darkness at the intersection following loss of the struck light standard. Adjacent-block streetlights SL-2 (SW corner) and SL-3 (mid-block north) visible as light sources in background. Location: S. Main St., east sidewalk, 25 ft south of impacted standard. Time Captured: 10/18/2025 02:24:02 Camera / Operator: CAM-A / M. Cardenas.
P-006	Description: Ambient-lighting reference frame — repeat of P-005 framing after emergency scene lighting deployed by RFD apparatus; provided for comparison to P-005 (unlit baseline). Location: Same as P-005. Time Captured: 10/18/2025 02:24:31 Camera / Operator: CAM-A / M. Cardenas.
P-007	Description: Bus #4177 — front elevation, full-vehicle, showing overall front-end damage envelope: front bumper deformation, cracked destination-sign panel, right-forward A-pillar buckle. Location: S. Main St., standing 12 ft directly in front of vehicle rest position. Time Captured: 10/18/2025 02:27:05 Camera / Operator: CAM-A / M. Cardenas.
P-008	Description: Bus #4177 — right-side elevation, full-vehicle; right-side mirror sheared and missing, forward passenger door frame distorted, forward passenger door in partially open position. Location: S. Main St., east sidewalk parallel to bus. Time Captured: 10/18/2025 02:27:44 Camera / Operator: CAM-A / M. Cardenas.
P-009	Description: Bus #4177 — left-side elevation, full-vehicle; reference view of undamaged side for comparison. Location: S. Main St., NB #1 (median) lane parallel to bus. Time Captured: 10/18/2025 02:28:21 Camera / Operator: CAM-A / M. Cardenas.
P-010	Description: Bus #4177 — rear elevation, full-vehicle; fleet number "4177" visible on rear quarter panel, ACTD district livery. Location: S. Main St., NB lanes, 20 ft aft of vehicle. Time Captured: 10/18/2025 02:29:02 Camera / Operator: CAM-A / M. Cardenas.
P-011	Description: Bus #4177 — front bumper close-up, right side; deformation, crush pattern, transferred grey/black paint consistent with light-standard mast finish. Location: 3 ft standoff from right front bumper corner. Time Captured: 10/18/2025 02:30:14 Camera / Operator: CAM-A / M. Cardenas.
P-012	Description: Bus #4177 — front bumper close-up, center; embedded aluminum fragments (consistent with luminaire housing) lodged in bumper skin. Location: 2 ft standoff, front bumper center. Time Captured: 10/18/2025 02:30:41 Camera / Operator: CAM-A / M. Cardenas.
P-013	Description: Bus #4177 — windshield, driver-side lower quadrant; radial crack pattern originating at a point approximately 14 in. above the base wiper travel; no penetration; no bloodstain on exterior driver-side glass. Location: Standing on front bumper step, standoff 2 ft. Time Captured: 10/18/2025 02:31:19 Camera / Operator: CAM-A / M. Cardenas.

P-014	Description: Bus #4177 — windshield, passenger-side lower quadrant; secondary spider fracture with impact point at lower right corner adjacent to the A-pillar; small tissue-like deposit noted at the corner, tented and marked for trace collection (see P-057). Location: Standing on front bumper step, standoff 2 ft. Time Captured: 10/18/2025 02:31:52 Camera / Operator: CAM-A / M. Cardenas.
P-015	Description: Bus #4177 — destination-sign panel close-up; lens shattered, LED matrix exposed, "512 OWL — DOWNTOWN" partially legible. Location: 3 ft standoff, front upper fascia. Time Captured: 10/18/2025 02:32:20 Camera / Operator: CAM-A / M. Cardenas.
P-016	Description: Bus #4177 — right front A-pillar buckle; measurement placard L-shape 6 in. scale in frame. Location: 2 ft standoff, right front corner. Time Captured: 10/18/2025 02:32:55 Camera / Operator: CAM-A / M. Cardenas.
P-017	Description: Bus #4177 — right-side mirror mount, sheared at bracket; mirror head not located on vehicle; see P-030 for mirror-housing fragments in debris field. Location: Right-side operator window position, standoff 3 ft. Time Captured: 10/18/2025 02:33:22 Camera / Operator: CAM-A / M. Cardenas.
P-018	Description: Bus #4177 — forward passenger door frame distortion; door in partial-open detent; step edge scuffed. Location: Right side, 4 ft standoff. Time Captured: 10/18/2025 02:33:57 Camera / Operator: CAM-A / M. Cardenas.
P-019	Description: Bus #4177 — front grille, wide angle; fabric fibers visible along the horizontal grille slats, right of centerline; markers 1A–1C placed for close-up collection sequence. Location: Directly in front of vehicle, standoff 2 ft. Time Captured: 10/18/2025 02:34:38 Camera / Operator: CAM-A / M. Cardenas.
P-020	Description: Bus #4177 — front grille, macro; marker 1A — dark fabric fibers (multiple, ~2–4 cm) adhering to grille slat approximately 18 in. right of front centerline; ABFO scale in frame. Location: Directly in front of vehicle grille. Time Captured: 10/18/2025 02:35:11 Camera / Operator: CAM-C / M. Cardenas.
P-021	Description: Bus #4177 — front grille, macro; marker 1B — light fabric fibers (fewer, ~1–3 cm), same grille bay as 1A, slightly outboard. Location: Same as P-020. Time Captured: 10/18/2025 02:35:33 Camera / Operator: CAM-C / M. Cardenas.
P-022	Description: Bus #4177 — front grille, macro; marker 1C — small hair sample (single dark strand with apparent root, approximate length 8 cm) recovered from horizontal grille slat, right of centerline; ABFO scale in frame. Location: Same as P-020. Time Captured: 10/18/2025 02:35:58 Camera / Operator: CAM-C / M. Cardenas.
P-023	Description: Trace-collection documentation — evidence envelopes E-1A, E-1B, E-1C sealed and initialed on the tailgate of RPD Evidence Unit vehicle following recovery of fibers and hair sample; envelope face bar-codes visible. Location: RPD Evidence Unit vehicle, east curb north of scene. Time Captured: 10/18/2025 02:41:12 Camera / Operator: CAM-C / M. Cardenas.
P-024	Description: City street-light standard at NE corner — wide view; steel mast deflected approximately 40° from vertical at base, luminaire pendant sheared and displaced onto adjacent sidewalk. Location: NE corner of S. Main St. @ Third Ave. Time Captured: 10/18/2025 02:43:04 Camera / Operator: CAM-A / M. Cardenas.

P-025	Description: Street-light standard — base close-up; anchor-bolt pattern intact, base flange separation, ruptured wiring conduit rising from below-grade handhole. Location: Base of impacted standard, sidewalk level. Time Captured: 10/18/2025 02:43:41 Camera / Operator: CAM-A / M. Cardenas.
P-026	Description: Street-light standard — mid-mast close-up; secondary bend approximately 6 ft above grade, paint transfer band consistent with contact by bus front bumper corner. Location: Face-on to bend, 3 ft standoff. Time Captured: 10/18/2025 02:44:08 Camera / Operator: CAM-A / M. Cardenas.
P-027	Description: Street-light standard — luminaire pendant on sidewalk; housing cracked, refractor lens fragmented, LED array partially exposed. Location: Sidewalk, 4 ft east of base of standard. Time Captured: 10/18/2025 02:44:37 Camera / Operator: CAM-A / M. Cardenas.
P-028	Description: Fixture wiring damage — feeder conductors visible at ruptured conduit stub at base of standard; conductor jackets abraded, one bare copper strand exposed; power to fixture out at time of arrival. DPW Unit 7 make-safe not yet on scene. Location: Base of impacted standard. Time Captured: 10/18/2025 02:45:02 Camera / Operator: CAM-A / M. Cardenas.
P-029	Description: Fixture wiring damage — close-up of the below-grade handhole cover, displaced approximately 3 in. off frame; standing-water in handhole reflects flash. Location: Sidewalk at base of standard. Time Captured: 10/18/2025 02:45:24 Camera / Operator: CAM-C / M. Cardenas.
P-030	Description: Debris field — wide overview looking north from POI-1 (light standard) toward POI-2 (bus-stop platform); mapping markers D-1 through D-14 placed for measurement. Location: NE corner, sidewalk, standing 4 ft south of light-standard base. Time Captured: 10/18/2025 02:48:15 Camera / Operator: CAM-A / M. Cardenas.
P-031	Description: Debris field — marker D-1 — right-side mirror head (glass and housing) resting on sidewalk approximately 9 ft north of light-standard base. Location: NE sidewalk. Time Captured: 10/18/2025 02:48:44 Camera / Operator: CAM-A / M. Cardenas.
P-032	Description: Debris field — markers D-2 through D-5 — destination-sign lens fragments (clear polycarbonate), distributed 3 to 11 ft north of light-standard base; ABFO scale in frame. Location: NE sidewalk. Time Captured: 10/18/2025 02:49:07 Camera / Operator: CAM-A / M. Cardenas.
P-033	Description: Debris field — markers D-6, D-7 — luminaire refractor-lens shards, larger fragments, in gutter pan at NE corner. Location: NE gutter pan. Time Captured: 10/18/2025 02:49:31 Camera / Operator: CAM-A / M. Cardenas.
P-034	Description: Debris field — markers D-8 through D-11 — smaller fragments (mirror housing plastic, black), distributed within a 6-ft radius north of light-standard base. Location: NE sidewalk and platform apron. Time Captured: 10/18/2025 02:50:00 Camera / Operator: CAM-A / M. Cardenas.

P-035	Description: Debris field — markers D-12, D-13, D-14 — bumper plastic and grille clip fragments recovered at the bus-stop platform apron between POI-1 and rest position. Location: Bus-stop platform, south end. Time Captured: 10/18/2025 02:50:29 Camera / Operator: CAM-A / M. Cardenas.
P-036	Description: Debris field — overall diagram-alignment photograph looking south from bus rest position toward POI-1; total-station prism (Ballesteros survey) visible on tripod at POI-1 for reference. Location: North of bus, on sidewalk. Time Captured: 10/18/2025 03:33:11 Camera / Operator: CAM-B / Ofc. R. Delacruz.
P-037	Description: Tire scuff mark TM-1 — full length, right-front tire, curving to the right; ~14 ft; measurement rolatape and yellow evidence cones at endpoints. Location: NB #2 (curb) lane transitioning into parking lane, approx. 70 ft south of Third Ave. north curb line. Time Captured: 10/18/2025 03:04:22 Camera / Operator: CAM-A / M. Cardenas.
P-038	Description: Tire scuff mark TM-1 — close-up, southern origin of scuff; rubber deposit and paint-line crossing point (fog line). Location: NB #2 lane, S. Main St. Time Captured: 10/18/2025 03:04:58 Camera / Operator: CAM-A / M. Cardenas.
P-039	Description: Tire scuff mark TM-1 — close-up, northern terminus, at north curb-face contact. Location: East curb face, S. Main St. Time Captured: 10/18/2025 03:05:22 Camera / Operator: CAM-A / M. Cardenas.
P-040	Description: Tire scuff mark TM-2 — full length, right-rear tire, parallel offset to TM-1; ~11 ft. Location: Parking lane / east edge NB #2 lane, S. Main St. Time Captured: 10/18/2025 03:06:14 Camera / Operator: CAM-A / M. Cardenas.
P-041	Description: Tire scuff mark TM-2 — close-up, midpoint; rubber transfer texture. Location: Same as P-040. Time Captured: 10/18/2025 03:06:42 Camera / Operator: CAM-A / M. Cardenas.
P-042	Description: Roadway — approach view from ~90 ft south of Third Ave. north curb line, framing the entire drift arc (in-lane origin → over fog line → parking lane → curb face); no pre-impact braking skid observed. Location: NB #2 lane, S. Main St. Time Captured: 10/18/2025 03:08:03 Camera / Operator: CAM-A / M. Cardenas.
P-043	Description: Bus-stop platform — overview; shelter, posted MTA/ACTD bus-stop signage, concrete pad, and impact zone at south end of shelter where the bus came to rest. Location: NE corner, west of shelter, standoff 8 ft. Time Captured: 10/18/2025 03:10:19 Camera / Operator: CAM-A / M. Cardenas.
P-044	Description: Bus-stop platform — close-up of shelter sign pole struck by right side of Bus #4177; pole deflected, sign face creased. Location: NE corner, immediately south of shelter. Time Captured: 10/18/2025 03:10:47 Camera / Operator: CAM-A / M. Cardenas.
P-045	Description: Pedestrian personal effects at bus stop — marker PE-1 — a black canvas tote bag on concrete pad at south end of shelter, contents partially spilled; wallet, transit fare card, and mobile phone visible. Location: Bus-stop pad, south end. Time Captured: 10/18/2025 03:12:28 Camera / Operator: CAM-A / M. Cardenas.

P-046	Description: Pedestrian personal effects — marker PE-2 — a single women's shoe (right foot), approximately 4 ft west of tote bag. Location: Bus-stop pad, south end. Time Captured: 10/18/2025 03:12:51 Camera / Operator: CAM-A / M. Cardenas.
P-047	Description: Pedestrian personal effects — marker PE-3 — the second women's shoe (left foot), on sidewalk approximately 11 ft north of tote bag, near Party 2 rest position. Location: Sidewalk, north of platform. Time Captured: 10/18/2025 03:13:16 Camera / Operator: CAM-A / M. Cardenas.
P-048	Description: Pedestrian personal effects — marker PE-4 — a pair of prescription eyeglasses (frames intact, one lens cracked), on sidewalk approximately 6 ft north of platform. Location: Sidewalk, near P-2 rest position. Time Captured: 10/18/2025 03:13:38 Camera / Operator: CAM-A / M. Cardenas.
P-049	Description: Pedestrian personal effects — marker PE-5 — a mobile phone (screen shattered), on concrete pad near center of shelter. Location: Bus-stop pad. Time Captured: 10/18/2025 03:14:02 Camera / Operator: CAM-A / M. Cardenas.
P-050	Description: Personal effects — inventory-tagging photograph; effects sealed in evidence bags E-PE-1 through E-PE-5, on tailgate of RPD Evidence Unit vehicle. Location: RPD Evidence Unit vehicle, east curb. Time Captured: 10/18/2025 03:41:58 Camera / Operator: CAM-C / M. Cardenas.
P-051	Description: Blood evidence — marker BL-1 — pooled blood staining on sidewalk between POI-2 (bus-stop platform south end) and Party 2 rest position, wide view; ABFO scale placed. Location: NE sidewalk, north of platform. Time Captured: 10/18/2025 03:16:34 Camera / Operator: CAM-A / M. Cardenas.
P-052	Description: Blood evidence — marker BL-2 — spatter and drag-transfer pattern on concrete, close-up, approximately 4 ft north of platform edge; ABFO scale placed. Location: NE sidewalk. Time Captured: 10/18/2025 03:17:04 Camera / Operator: CAM-C / M. Cardenas.
P-053	Description: Blood evidence — marker BL-3 — smaller staining on shelter apron directly beneath south shelter pane; ABFO scale in frame. Location: Bus-stop platform apron. Time Captured: 10/18/2025 03:17:31 Camera / Operator: CAM-C / M. Cardenas.
P-054	Description: Blood evidence — marker BL-4 — transferred staining on right front bumper of Bus #4177 (lower fascia, right of centerline); ABFO scale in frame. Swab E-BL-4 taken by M. Cardenas. Location: Bus #4177, right front lower fascia. Time Captured: 10/18/2025 03:19:12 Camera / Operator: CAM-C / M. Cardenas.
P-055	Description: Ambient darkness reference — panoramic view of intersection at 03:22 hrs, still prior to DPW Unit 7 restoration work; NE corner remains without overhead illumination; comparison to P-005/P-006 baseline. Location: SW corner across intersection. Time Captured: 10/18/2025 03:22:47 Camera / Operator: CAM-B / Ofc. R. Delacruz.

P-056	Description: Fixture wiring damage — close-up of exposed feeder conductor at rupture point after DPW Unit 7 arrival for make-safe operation (0312 hrs); DPW technician tagged and de-energized. Photograph taken prior to any repair activity. Location: Base of impacted standard. Time Captured: 10/18/2025 03:14:51 Camera / Operator: CAM-C / M. Cardenas.
P-057	Description: Trace on windshield — return-visit close-up of tissue-like deposit at lower right windshield corner (referenced in P-014); marker T-1 placed; swab E-T-1 collected by M. Cardenas. Location: Bus #4177, windshield, lower right. Time Captured: 10/18/2025 03:26:03 Camera / Operator: CAM-C / M. Cardenas.
P-058	Description: Vehicle DVR / camera module — tagged in place on operator's console prior to release to ACTD Safety representative's designee under data-preservation letter; RPD evidence tag ET-2025-1018-DVR-01 affixed. Location: Bus #4177, operator's console. Time Captured: 10/18/2025 03:41:07 Camera / Operator: CAM-A / M. Cardenas.
P-059	Description: Bus interior — forward passenger cabin looking aft; personal items on floor near forward transverse seat (Occ-1 Cho seating position); overhead grab-rail intact. Location: Interior, forward doorway. Time Captured: 10/18/2025 03:46:14 Camera / Operator: CAM-A / M. Cardenas.
P-060	Description: Bus interior — operator's compartment; farebox and APC head unit intact; ignition key in position, master switch in "run"; operator seat belt visible. Location: Interior, operator's position. Time Captured: 10/18/2025 03:47:02 Camera / Operator: CAM-A / M. Cardenas.
P-061	Description: Scene release documentation — total-station survey benchmark tag on NE corner curb face; taken at conclusion of measurement work (Ofc. K. Ballesteros, RPD #3355). Location: NE corner, curb face. Time Captured: 10/18/2025 04:57:19 Camera / Operator: CAM-B / Ofc. R. Delacruz.

EVIDENCE ITEM CROSS-REFERENCE (items depicted and separately booked)

Envelope / Item	Contents	First Depicted In Log At
E-1A	Dark fabric fibers, grille slat right of centerline	P-020
E-1B	Light fabric fibers, grille bay adjacent to E-1A	P-021
E-1C	Single hair sample (with apparent root), grille slat right of centerline	P-022
E-T-1	Windshield lower-right corner trace swab	P-057
E-BL-4	Right front bumper transferred stain swab	P-054
E-PE-1	Black canvas tote bag and contents	P-045
E-PE-2	Women's shoe, right	P-046
E-PE-3	Women's shoe, left	P-047
E-PE-4	Prescription eyeglasses	P-048
E-PE-5	Mobile phone, screen shattered	P-049

All physical items above booked into RPD Evidence Locker under case TC-2025-1018 at 0402 hrs and 0515 hrs, cross-tagged to Chain-of-Custody form RPD-COC-2025-1018-02 (this log). Biological trace items (E-1C, E-T-1, E-BL-4) held under refrigerated storage pending transfer to the Los Angeles County Sheriff's Department Scientific Services Bureau — Crime Laboratory.

MEDIA CUSTODY / INTEGRITY

- Source media (CAM-A SD card SDN-A-0007, CAM-B SD card SDN-B-0019, CAM-C SD card SDN-C-0004) removed from cameras at 0508 hrs on 10/18/2025 by Field Evidence Tech M. Cardenas.
- Original files hashed (SHA-256) and copied to write-once optical archive DVD-R serial RPD-EV-2025-4419 and to the RPD Digital Media Server working folder.
- Hash manifest RPD-EV-2025-4419-HASH.txt filed with this log.
- Source SD cards returned to service after verification; archival DVD-R retained under case TC-2025-1018.
- No frames deleted from the source media between capture and archival; internal frame sequence continuous.

CHAIN OF CUSTODY — SIGNATURES**Prepared by (Evidence Technician / Photographer):**

Field Evidence Technician M. Cardenas, RPD Evidence Unit (ID EVT-04)

Signature: /s/ M. Cardenas

Date/Time: 10/18/2025 07:52 hrs

Reporting Officer (co-photographer, CAM-B):

Ofc. Ramona Delacruz, RPD #2814

Signature: /s/ R. Delacruz

Date/Time: 10/18/2025 07:56 hrs

Received into RPD Evidence Unit custody:

Evidence Custodian Sgt. L. Portillo, RPD #1592

Signature: /s/ L. Portillo

Date/Time: 10/18/2025 08:14 hrs

Reviewed / Approved:

Sgt. E. Halversen, RPD #1477, Watch Commander

Signature: /s/ E. Halversen

Date/Time: 10/18/2025 08:31 hrs

Distribution: Original — RPD Evidence Unit case file (TC-2025-1018); Copy — RPD Traffic Bureau; Copy — LA County District Attorney's Office (upon filing package); Copy — ACTD Risk Management (upon written request under RPD records-release policy); Copy — City of Rivergate Risk Management (property-damage claim, redacted per policy).

— END OF PHOTO LOG — TC-2025-1018 — 61 exposures logged —