

ONBOARD VIDEO / CAMERA SYSTEM — STILL-FRAME LOG

ALDER CREEK TRANSIT DISTRICT — Fleet Safety / Onboard Video Program

1200 Alder Creek Way, Rivergate, CA 91766

COVER PAGE — CUSTODIAN CERTIFICATION AND PRESERVATION METADATA

Vehicle	ACTD Bus #4177 (2019 New Flyer XDE40, 40-ft low-floor transit coach)
Service Date	10/18/2025 (Saturday)
Block / Run	Block 512-OWL — Owl Route 512
Operator on shift	Raymond T. Keeler, Badge #4417
Log Coverage Window	10/18/2025 01:30:00.000 – 02:10:00.000 PT
Log Prepared	12/03/2025
Prepared By	ACTD Fleet Safety — Onboard Video Program (in coordination with vendor Custodian of Record)
Custodian of Record — Physical Media	ACTD Fleet Safety, Rivergate Yard (Div. 3), video-evidence locker
Custodian of Record — Vendor System	Onboard camera vendor system, incident-clip archive (per vendor CoC)
Incident Reference	ACTD-IR-2025-1018 (Final Incident Report, 12/01/2025, Okonkwo)

Preservation Statement

The underlying MP4 clip covering the window logged herein is preserved in the onboard camera vendor system pursuant to the **litigation hold** issued by the ACTD Office of the General Counsel on 10/18/2025 and confirmed in writing on 12/01/2025. Absent the litigation hold, the vendor's incident-clip retention loop for Bus #4177 would be short — typically 30 to 90 days — after which uncalled clips are automatically overwritten. The hold suspends automatic overwrite and directs the vendor to retain the incident clip in native format with full technical metadata until released in writing by the ACTD General Counsel.

The still-frame entries in this log were derived from that preserved MP4 clip. Each entry is time-synchronized to the bus DVR master clock and is expressed at millisecond precision as recorded by the onboard system.

Vendor System Metadata (attached / verified on capture)

DVR Head Unit — Make / Model	Seon Explorer HD-8 (8-channel MDVR)
DVR Serial Number	SN-EX8-4177-2019
DVR Firmware Version	4.11.06-actd
Onboard Storage	1 TB SATA HDD (primary) + 128 GB SDXC (mirror)
Time Source	GPS-disciplined RTC; drift observed –0.021 s over service night (within tolerance)
Time Zone	America/Los_Angeles (PT); DST not in effect on 10/18/2025 during window (standard time transition occurred later)
Video Codec	H.264/AVC main profile, 720p @ 15 fps (interior channels), 30 fps (road-facing)
Audio	Interior AAC, 48 kHz mono (driver-facing + interior forward channels only)
Native Clip File	4177_20251018_0130-0210_INC.mp4
Native Clip Size	3,412,884,116 bytes
Native Clip SHA-256	5b5b52667953dc1379b324d48454644350bb458d62ab721cdf7c8b05b72c5f23
Vendor Case ID	VMS-2025-1018-4177-01
Vendor Hold Ticket	VMS-HOLD-25-0442 (opened 10/18/2025 04:52 PT by ACTD Fleet Safety on-call)
Original Retention Window	30–90 days rolling; overwrite suspended by hold

Hold Confirmation Correspondence	Vendor acknowledgement email, 10/18/2025 05:14 PT; written hold confirmation from D. Farkas (ACTD GC), 12/01/2025
---	---

Camera Channel Legend

Channel	Camera Position	Field of View
CAM-01	Interior Forward	Wide-angle from bulkhead behind operator, facing rearward into passenger cabin (rows 1–10 visible)
CAM-02	Driver-Facing	Operator compartment; captures operator head, torso, hands, steering wheel, and mirror-check gaze
CAM-03	Road-Facing (Forward)	Windshield-mounted, forward road view, includes speedometer overlay from J1939 bus bus (mph, brake, throttle, turn-signal state)
CAM-04	Rear Door / Rear Cabin	Above rear (exit) door, facing forward; captures alighting activity and rear-cabin rows 8–13

Notes on this Log

- Entries are numbered sequentially. Timestamps are the DVR-recorded frame time (HH:MM:SS.mmm), 24-hour local time, 10/18/2025.
- “Description” states only what is visible or, for CAM-03 overlay, what the recorded J1939 telemetry values were on the frame. No inferences or opinions are recorded.
- Where the same instant is captured by multiple channels, each channel is logged as a separate frame entry.
- This log does not exhaust every frame of the underlying clip; it is a representative frame-by-frame index. The full clip is retained in native format by the vendor Custodian of Record under litigation hold; it is not included in this export.

STILL-FRAME LOG — 10/18/2025, 01:30:00.000 – 02:10:00.000

Segment A — Downtown Loop revenue boardings, ~01:30 (Trip 05, southbound leg)

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
001	01:30:02.117	CAM-03	Coach stopped at S. Main Street & Fifth Avenue northbound curb. Speedometer overlay: 0 mph. Brake: applied. Turn signal: right (kneeling stop). Ambient: dry pavement, clear sky, streetlights lit.
002	01:30:02.400	CAM-04	Rear door open (kneel cycle complete). No boarding activity at rear door.
003	01:30:04.883	CAM-01	Front door open. First boarder — adult male, dark hooded jacket — enters, taps farebox reader, moves to left aisle.
004	01:30:08.267	CAM-01	Second boarder — adult female, backpack — enters, taps farebox reader, proceeds toward mid-cabin.
005	01:30:11.550	CAM-01	Third boarder — adult male, kitchen whites visible under open jacket — enters, taps farebox reader, moves to rear cabin.
006	01:30:14.033	CAM-02	Operator seated, both hands on wheel, head upright, eyes forward toward front door.
007	01:30:19.717	CAM-01	Front door closes. Three passengers visible seated in cabin: left row 4, right row 8, right row 12. Cabin otherwise empty.
008	01:30:20.850	CAM-03	Coach begins to move. Speedometer overlay: 3 mph and increasing. Brake: released. Turn signal: left (merge to travel lane).
009	01:30:34.400	CAM-03	Coach at ~22 mph on S. Main Street southbound. Overhead signal at Fourth Avenue green.

Segment B — Enroute, Trip 05 continuing, ~01:31–01:44

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
010	01:32:47.983	CAM-03	Coach on Alder Creek Boulevard, ~28 mph. No other traffic in forward view.
011	01:35:12.550	CAM-02	Operator hands on wheel, head upright. Right hand releases wheel briefly to adjust cabin HVAC fan control, then returns to wheel.
012	01:38:04.117	CAM-03	Coach approaching Poplar Street / Rivergate Plaza layover point. Speedometer overlay: decelerating from 24 to 10 mph.
013	01:38:22.883	CAM-03	Coach stopped at Poplar / Rivergate Plaza layover pad. Speedometer overlay: 0 mph. Parking brake: engaged.
014	01:38:23.267	CAM-01	Front door opens for layover; no boarding activity (layover point, not revenue stop). Cabin passengers remain seated (three).
015	01:38:31.400	CAM-02	Operator visible reaching to right side of dash — appears to interact with a container out of frame — hand returns to wheel area 6 seconds later.

Segment C — Operator condition at wheel, ~01:45 (mid-layover, still stopped)

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
016	01:44:58.117	CAM-02	Operator seated, head upright but slowly declining toward chest. Eyes appear closed.
017	01:45:01.683	CAM-02	Operator head continues forward decline. Chin approaches sternum. Hands rest on lower wheel rim; no active grip visible.
018	01:45:03.117	CAM-02	Operator head fully forward, chin on chest. Shoulders rounded. Operator's body position is consistent with a visible nodding-off / head-drop at the wheel.
019	01:45:03.550	CAM-01	Cabin view: passengers seated as before (left row 4, right row 8, right row 12); no passenger visible reacting to operator.
020	01:45:05.283	CAM-02	Operator head jerks upright abruptly. Eyes open. Right hand re-grips upper wheel.

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
021	01:45:07.117	CAM-02	Operator rubs right eye with knuckle of right hand; head momentarily tilts left.
022	01:45:15.833	CAM-02	Operator's head declines forward a second time; chin drops. Estimated eyelid closure. Duration of this nod, frame-to-frame, 4.2 seconds before recovery at 01:45:20.017.
023	01:45:20.017	CAM-02	Operator head snaps upright a second time. Both hands return to 10-and-2 position on wheel.
024	01:46:11.400	CAM-02	Operator remains seated upright; no further head decline observed for the balance of the layover.

Segment D — Layover close-out and Trip 06 departure, ~01:58–02:04

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
025	01:58:42.267	CAM-01	Three passengers remain seated in cabin: Cho (left row 4), Mowbray (right row 8), Blau (right row 12). No alighting activity through layover.
026	02:02:14.883	CAM-02	Operator upright, both hands on wheel, checks driver-side mirror.
027	02:04:00.117	CAM-03	Trip 06 departure. Speedometer overlay: 0 → 4 mph. Parking brake: released. Turn signal: left. Coach pulls away from Poplar / Rivergate Plaza pad northbound.
028	02:04:12.400	CAM-03	Coach on Poplar Street northbound, ~18 mph, approaching turn onto S. Main Street.
029	02:04:22.983	CAM-03	Coach completes right turn onto S. Main Street northbound. Speedometer overlay: 15 mph and accelerating. Lane position: centered in the northbound curb lane.
030	02:04:36.117	CAM-02	Operator's head begins to decline forward again. Eyes appear closed.
031	02:04:38.550	CAM-03	Speedometer overlay: 27 mph. Coach centered in northbound curb lane. Overhead signal at Fourth Avenue green. Roadway ahead clear.

Segment E — Departure from lane and impact sequence, 02:04:50–02:05:10

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
032	02:04:50.183	CAM-03	Bus begins to drift left of the northbound curb-lane markings. Lane-marking pixels move rightward within the frame as the coach's heading changes left of parallel. Speedometer overlay: 29 mph. Brake: not applied. Turn signal: none. Throttle: 32%.
033	02:04:50.317	CAM-02	Operator's head remains forward on chest; hands on wheel, but wrists show no active steering input.
034	02:04:52.667	CAM-03	Lane-position drift continues left. Painted lane divider crosses under the right-front quarter of the coach's forward view; coach now straddling the divider between curb lane and inside lane. Speedometer overlay: 30 mph. Brake: not applied.
035	02:04:55.133	CAM-03	Coach fully across the divider, now travelling in the inside northbound lane and continuing to drift left toward the eastern (right-side) curb. Speedometer overlay: 31 mph. Brake: not applied.
036	02:04:58.400	CAM-03	Coach heading has drifted right of the roadway centerline of travel; the eastern curb line of S. Main Street enters the lower right of the road-facing frame. Speedometer overlay: 31 mph.
037	02:05:01.883	CAM-03	City of Rivergate street-light standard (east curb, south of Third Avenue bus-stop pad) visible in forward frame, right-center, closing distance. Speedometer overlay: 31 mph. Brake: not applied. Steering: no correction.
038	02:05:01.917	CAM-02	Operator's head still forward on chest. No visible reaction. Hands limp on wheel.
039	02:05:03.550	CAM-01	Cabin: Cho (left row 4) turns head toward right-side windows. Mowbray (right row 8) grasps stanchion. Blau (right row 12) leans forward.

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
040	02:05:04.017	CAM-03	First impact — coach right-front quarter contacts City of Rivergate street-light standard on east curb south of Third Avenue bus-stop pad. Standard shears at base; upper portion of fixture pitches forward into the frame; fixture lamp flashes then extinguishes. Speedometer overlay at contact: 30 mph. Brake: not applied at moment of contact.
041	02:05:04.150	CAM-01	Cabin: passengers thrown forward; Cho's torso strikes seatback ahead of him; Mowbray's head snaps forward then rebounds. Handrail vibration visible.
042	02:05:04.183	CAM-02	Operator's torso pitches forward against wheel; head still forward. No steering input made. Body then rocks back against seat.
043	02:05:04.617	CAM-03	Sheared upper fixture falls out of the right side of the frame. Intersection ambient light reduced — northeast-corner fixture no longer illuminated. Northwest-corner fixture still illuminated. Coach continues forward under residual momentum. Speedometer overlay: 24 mph. Brake: not applied.
044	02:05:05.983	CAM-03	Coach travelling forward at ~19 mph on shallow left-of-heading angle; northbound S. Main / Third bus-stop pad enters lower-right frame. A standing figure is visible on the pad (facing south toward the approaching coach).
045	02:05:06.750	CAM-03	Standing figure on the pad enlarges in frame; figure is stationary. Coach heading unchanged. Speedometer overlay: 16 mph. Brake: not applied. Steering: no correction.
046	02:05:07.283	CAM-03	Second impact — coach right-front contacts pedestrian standing on the northbound S. Main / Third bus-stop pad. Contact point below the coach's right headlamp and destination-sign masthead. Figure disappears from the road-facing frame at moment of contact. Speedometer overlay at contact: 15 mph. Brake: not applied at moment of contact.
047	02:05:07.317	CAM-01	Cabin: passengers again thrown forward; Cho slides partly into aisle from left row 4; Mowbray remains in seat, head against forward stanchion; Blau seated, hands braced.
048	02:05:07.550	CAM-02	Operator's head lifts partially — first upright motion since Segment C nods observed. Eyes appear to open. Right foot movement visible below dash (foot leaving throttle area).
049	02:05:08.117	CAM-03	Brake-pressure overlay indicates first brake application of the sequence. Speedometer overlay: 12 mph and decreasing. Coach comes onto the bus-stop pad, right-front quarter partly over the concrete edge of the pad.
050	02:05:09.400	CAM-03	Speedometer overlay: 4 mph. Brake: applied. Coach yaws slightly right as right-front wheel contacts pad curb.
051	02:05:10.117	CAM-03	Coach comes to rest. Speedometer overlay: 0 mph. Brake: applied. Parking brake: not yet set. Right-front quarter of coach on the northbound bus-stop pad. Fixture wreckage visible on roadway to right-rear of coach. Northeast-corner light fixture dark; northwest-corner fixture still illuminated.
052	02:05:10.183	CAM-02	Operator upright in seat, both hands on wheel, head turning to right toward passenger side. Mouth open.
053	02:05:10.400	CAM-01	Cabin: all three passengers accounted for in view. Cho on left cabin floor near row 4, moving; Mowbray in right row 8, holding neck; Blau standing up in right row 12 aisle.
054	02:05:10.550	CAM-04	Rear-door view: rear cabin quiet; no passengers at rear door. Rear cabin floor litter dislodged forward from impact.

Segment F — Post-collision, ~02:05:11–02:10

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
055	02:05:14.283	CAM-02	Operator sets parking brake (right hand movement to console). Operator opens mouth; audio channel captures indistinct exclamation.
056	02:05:22.117	CAM-02	Operator remains seated. Head in hands briefly, then lifts.
057	02:05:31.883	CAM-01	Blau moves forward in aisle, reaches Cho, kneels. Mowbray remains seated.
058	02:05:47.400	CAM-03	Second civilian vehicle stops in southbound lane opposite. Driver of that vehicle exits.

#	Timestamp (HH:MM:SS.mm m)	Camera	Description
059	02:06:14.117	CAM-01	Operator stands, moves toward front door but does not exit coach. Front door remains closed.
060	02:06:38.883	CAM-03	Additional civilian pedestrian approaches from northwest corner of intersection, stops near front of coach.
061	02:07:03.550	CAM-02	Operator returns to driver seat; visible to raise a mobile phone to right ear briefly, then lowers it.
062	02:07:22.117	CAM-03	Emergency-services lights (red/blue) first reflect in windshield glass from behind coach; no unit yet in frame.
063	02:09:41.883	CAM-03	Rivergate PD unit (light bar active) visible pulling to stop in front-left of coach.
064	02:09:58.117	CAM-01	Officer approaches front door of coach on foot from left.
065	02:10:00.000	ALL	End of logged coverage window. Native MP4 continues past this timestamp in vendor archive under litigation hold.

END OF STILL-FRAME LOG

Additional preserved channels (interior aft, curbside exterior) and the full native MP4 file are retained by the vendor Custodian of Record under litigation hold; they are not included in this export.

Custodian Certification. I certify that the still-frame entries above were extracted from the native MP4 clip preserved for Bus #4177 covering 10/18/2025 01:30:00.000 – 02:10:00.000 PT under the litigation hold described on the cover page; that the timestamps reflect the DVR master clock as recorded by the onboard camera system; and that no frame described above has been altered from the source frame in the native archive.

/s/ Elena Marchetti

Elena Marchetti — Supervisor, Onboard Video Program, ACTD Fleet Safety

Date: 12/03/2025

/s/ Marcus T. Whitfield

Onboard camera vendor — Custodian of Record (VMS-2025-1018-4177-01)

Date: 12/03/2025