S N	DEVICE NAME	LOCATION	SERIAL NUMBER	CURRENT SOFTWAR E VERSION	RECOMEND ED STABLE FIRMWARE VERSION	COMMENTS
1	ISR4451	DODOMA	FGL2410L7C N	16.08.01	17.12.3a	We recommend the device to be upgraded
2	ISE (SNS-3615- K9)	DODOMA	WZP250903V B	3.0.0.458	3.4	-We have noticed most features have not been activated and being used thus making the System not performing at its maximum value. -We recommend System redesign and redeployment to work to its functionality
3	WC Controller AIR-CT3504-K9	DODOMA	FCW2202M00 6	8.5.105.0	8.10.196.0	-We Recommend the device to be upgraded. *End of SW
	50200 400	Dobotti	TO COLLOY OF	15124	15.10.4	Maintenance Releases Date*
4	C9300-48P	DODOMA	FOC2449L8D M	16.12.4	17.12.4	To be upgraded in Phase 2
5	C9300-48P	DODOMA	FOC2449L8L C	16.12.4	17.12.4	To be upgraded in Phase 2
6	C9300-48P	DODOMA	FOC2447LF31	16.12.4	17.12.4	To be upgraded in Phase 2
7	C9300-48P	DODOMA	FOC2449L8H X	16.12.4	17.12.4	To be upgraded in Phase 2
8	C9300-48P	DODOMA	FOC2447LF37	16.12.4	17.12.4	To be upgraded in Phase 2
9	C9300L-48P-4X	MWANZA	FOC2716Z9M W	17.06-04	17.12.4	To be upgraded in Phase 2
10	ISR4451	MWANZA	FD02232A3P M	16.09.03	17.12.3a	To be upgraded in Phase 2
11	C9300L-48P-4X	TABORA	FOC2703YT9 Y	17.03.05	17.12.4	To be upgraded in Phase 2
12	C1900	TABORA	FGL202523BR	153-3.M3	15.7.3M9	*This device need to be decommissioned * -End of support
13	C9300L-48P-4X	MBEYA	FOC2716Z8XJ	17.06-04	17.12.4	To be upgraded in Phase 2

14	ISR4300	MBEYA	FDO2232A3P Q	16.09.03	17.12.3a	To be upgraded in Phase 2
15	C9300L-48P-4X	ARUSHA	FOC2716Z9F V	17.06-04	17.12.4	To be upgraded in Phase 2
16	ISR4300	ARUSHA	FDO2232A3P N	16.09.03	17.12.3a	To be upgraded in Phase 2
17	C9300L-48P-4X	DSM	FOC2703YS8 W	17.03.05	17.12.4	To be upgraded in Phase 2
18	C2900	DSM	FCZ1719704U	15.2.4M3	15.7.3M8	*This device need to be decommissioned * -End of support